

Note: This document has not been finalised.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: China Taiping Insurance (Singapore) Pte. Ltd.
3 Anson Road
#16-00 Springleaf Tower
Singapore 079909

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Tan Kah Leong

Date: 15 Feb 2023

Preliminary Advice

Insured Vehicle No	: XE6879G	Accident Date	: 18/08/2022
TP Vehicle No	: SJK286R	Assignment Date	: 22/08/2022
Make	: VOLKSWAGEN SPORTSVAN	Est. Duration of Repair	: 5
Date of Inspection	: 23/08/2022		
Inspection At	: AVANTAGE VAG (TOH GUAN) (HQ) 48 TOH GUAN ROAD EAST, #05-136 ENTERPRISE HUB SINGAPORE 608586		

Point of Impact / General Description of Damages

Parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	6,247.07
Revised Amount	:S\$	4,222.46
Check Items (Estimated)	:S\$	188,72
Total	:S\$	4,411.18

Lump Sum Repair :S\$

Total Loss Consideration

New for Old Value	:S\$
Pre-Accident Value	:S\$
COE / PARF Rebate	:S\$
Salvage Value	:S\$
Margin for Repair	:S\$

Remarks

- () The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- (X) Other comments : Please note that the preliminary advice amount (Revised & Check Items) stated are subject to consistency check, part prices and labour cost.