

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Reg. No: 199607198R GST Reg. No. 19-9607198-R					
Affiliated to Federation Internationale Des Experts En Automobile					
	AUTO & GENERA	L INSURANCE (S) PL	Ref:	CS/AGI22008083/Rny3q2	
	(BUDGET DIRECT 190 CLEMENCEA SINGAPORE SHO 239924	INSURANCE) U AVENUE #03-01 PPING CENTRESINGAPORE	Date	22/11/2022	
			Code	: AGI	
1.					
	Insured Veh.	SLT 9951Z	Veh. Inspected	SLP 5691X	
	Policy No.	P10571681R01	Coverage (\$)	0.00	
	Claim No.	C10016401/JL	Excess (\$)	0.00	
	Assign From	SALIZAWATI HAIZAR	Assign Date	23/08/2022	
2. Vehicle Particulars & Condition					
	Make & Model	TOYOTA PRIUS HYBRID 1.8 CVT	c.c	1798	
	Engine No.	HIDDEN	Year of Reg.	2017	
	Chassis No.	JTDKB3FU103559635	Colour	GREY	
	Odometer	580384 KM	Steering	IN ORDER	
	Brakes	IN ORDER	Modification	SPORTS RIM	
	General	FAIR			
3. Conditions of Tyres					
		Size	Make	Balance	
	R/H Front Tyre	195/65 R15	RYDANZ	6 mm	
	L/H Front Tyre	195/65 R15	RYDANZ	6 mm	
	R/H Rear Tyre	195/65 R15	RYDANZ	6 mm	
	L/H Rear Tyre	195/65 R15	RYDANZ	6 mm	
4.	Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE O/S FRONT PORTION.				
	DAMAGES SEE DETAILS.				
5.	5. General Information				
	Accident Date	17/07/2022	Inspection Date	24/08/2022	
	Survey held at	4 Jalan Besut S(619557)			
	Repairer	LION CITY RENTALS PTE LTD			
5a.	a. Remarks				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b.	5b. Estimate Days of Repair				

3 Working Days

ESTIMATED NORMAL PERIOD FOR REPAIR: