

SOON SAN MOTOR TRADING

Bik.3006,UBI ROAD 1,#01-390,SINGAPORE 408700,TEL:68414445 & FAX:67473546

To: Motor Claims Dept

AXA INSURANCE SINGAPORE PTE LTD

8, Shenton Way #27-01

AXA Tower S,pore 068811

Accident date:19/08/2022

Date:22/08/2022

Estimate cost to repair vel:SJM 7579P (Toyota Vios) claims under ve;SHA 782B.

Not Authorized
new
mercy
H/S @ 3000/
5 days
Tunphw Aterey-
23/8/22

1pce boot lid	\$ 720.00	R X	
1pce boot lid rubber	195.10	Twi ✓	166.10
1pce boot lid vios plate	38.10	11 X	
1pce boot lid emblem	55.20	11 X	
1pce boot lid E plate	40.30	11 X	
1pce boot lid lower lock	42.00	11 X	
1pce boot lid lower lock cover	190.10	Twi ✓	180.20
1pce tai lamp right	301.50	CRA ✓	
1pce tai lamp inner panel	102.00	R X	
1pce rear bumper	445.00	DE ✓	407.50
1pce rear bumper reflector	120.00	CRA ✓	86.20
1set rear bumper reverse sensors	450.00	shhd 2005/N	
1pce rear bumper side holder	55.10	but ✓	
10pcs rear bumper inner clips@\$6	60.00	11 X	
1pce rear bumper inner bracket	110.00	11 X	
1pce rear bumper inner beam	198.00	NS X	
2pcs rear bumper top side clips@\$10	20.00	11 X	
1pce rear panel	550.00	DE ✓	
2pcs rear fender trim covers@\$210	420.00	11 X	
1pce rear inner side sponge	120.00	Tofn ✓	
1pce spare tyer top cover board	180.00	Tofn ✓	
1pce rear right fender	950.00	R X	
	\$ 5,362.40		
Less 25%	1,340.60		
1pce Rear floor tool sponge	\$130.00	Tofn ✓	page 1
1pce Rear floor tool sponge centre	\$110.00	Tofn ✓	

252

SOON SAN MOTOR TRADING

Blk.3006,UBI ROAD 1,#01-390,SINGAPORE 408700,TEL:68414445 & FAX:67473546

To: Motor Claims Dept

AXA INSURANCE SINGAPORE PTE LTD

8, Shenton Way #27-01

AXA Tower S.p.a 068811

Accident date:19/08/2022

Date:22/08/2022

Estimate cost to repair vel:SJM 7579P (Toyota Vios) claims under ve;SHA 782B.

Page 2	\$4,021.80
1pce rear number plate with cover	100.00 s/n n x
Lobour	
To rustproof	200.00 30
To check wiring	50.00 20
To dismantle/renew reverse sensors	100.00 50
To remove/refit rear interior to effect repair	100.00 20
To dismantle/renew accident portion	1,200.00 800
To spray paint	1,200.00 900
Total:	\$ 6,971.80

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed **and** is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

P-128660
252
171495
200
1880
3794.95