

ASSIGNMENT

From:

Date:

Estimated Cost:

TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

10

days

Res.: Yes or No

Lum Sum:

20

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

3701

Vehicle: IN / OUT

Date / Time

Action / Instruction

301 hrs 7m 26s

COE until 15-04-2024 227 Pk.

nett \$10692

13/9/22 1/5 @ 9200 inboard Allen.

Veh No:

SJP 9201A

Yr Regn:

16/04/09

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer of (M)

Make:

KIA cerato forte Ex.c.c 1591

Colour

Black

A/C:

Insured / Std / NI / NA

Sp. Reading

601523

T/Radio:

Insured / Std / NI / NA

Eng/No:

KNAFH221295029887

C/No:

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

225/45Zr17

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

6

mm

Rear

6

R/Bal.

mm

L/Bal.

6

mm

L/Bal.

6

mm

D.O.A.

22/08/22

D.O.I.

23/08/22

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date/Time, File Pass to?

☐

: Preli. Report

1)

☐

: Final Report

Date/Time, File Return to?

2)

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation:

Add Fee:

☐

: Site Insp (\$

) S + RS, SI

☐

: Interview (\$

) Photos

☐

: Tech. Invs (\$

) Others

☐

: Weekend (\$

)

TOTAL

Report Format :

Lump Sum / I.B.I: (\$

)

Ashu

Not Authorized
 23/08/22
 2/5 \$9200/
 10 days.

FASTECH AUTO PTE LTD

1 Kaki Bukit Ave 6 #01-48 Autobay

Singapore 417883

Tel No: 67452063/ 67467158 Fax No: 67458520

Tax Reg No : 200006262D

VEHICLE No: SJP 9201A

1PC	BOOTLID	R		\$1,661.00	X
2PCS	BOOTLID HINGES @\$150.00	17		\$300.00	X
1PC	BOOTLID REAR LOGO	17		\$85.00	X
1PC	BOOTLID 'CERATO' EMBLEM	17		\$68.00	X
1PC	BOOTLID 'FORTE' EMBLEM	17		\$60.00	X
1PC	BOOTLID 'K3' EMBLEM	17		\$52.00	X
1PC	BOOTLID C&C LOGO	17		\$50.00	X
1PC	BOOTLID INNER LOCK	17		\$199.00	X
1PC	BOOTLID WEATHERSTRIP	17		\$281.00	X
2PCS	BPPTLID REFLECTORS @\$725.00	17		\$1,450.00	X
1PC	BOOTLID INNER TRIM	17		\$281.00	X
1SET	BOOTLID INNER TRIM CLIPS	17		\$50.00	X
1PC	REAR BUMPER	Dis	688	\$850.00	—
1PC	REAR BUMPER LOWER GARNISH	De	204	\$650.00	—
2PCS	REAR BUMPER REFLECTORS @\$88.00	17		\$176.00	X
2PCS	REAR BUMPER SIDE RETAINERS @\$60.00	0/s cr	48	\$120.00	PC
1PC	REAR BUMPER REINFORCEMENT	cr	381	\$515.00	—
2PCS	REAR BUMPER REINFORCEMENT BRACKETS @\$180.00	17		\$360.00	X
3PCS	REAR BUMPER REINFORCEMENT TOP BRACKETS @25.00	17		\$75.00	X
2PCS	REAR BUMPER REINFORCEMENT LOWER BRACKETS @\$25.00	17		\$50.00	X
1PC	REAR BUMPER SPONGE	Torn	145	\$160.00	—
1SET	REAR BUMPER CLIPS	ner		\$50.00	—
1PC	REAR END PANEL	Dis/nerf	472	\$691.00	—
1PC	REAR END PANEL TOP GARNISH	17		\$288.00	X
2PCS	TAILLAMPS @\$1050.00	0/s 320	405	\$2,100.00	PC
2PCS	TAILLAMP HOUSING PANELS @\$450.00	0/s 25	255	\$900.00	PC
1PC	REAR FLOOR PANEL	R		\$1,420.00	X
1PC	REAR FLOOR PANEL TOP BOARD	17		\$615.00	X
2PCS	REAR FENDERS @\$1650.00	n/s n 0/s Dis	1260	\$3,300.00	PC
2PCS	REAR FENDER INNER TRIMS @\$355.00	17		\$710.00	X
1PC	REAR AXLE BEAM	Surf/tw	1415	\$1,745.00	—
1PC	REAR WHEEL HUB BEARING O/S	Daye	390	\$422.00	—
1PC	REAR SHOCK ABSORBER O/S	tw	286	\$350.00	—
1PC	REAR SHOCK ABSORBER SPRING O/S	Dis	155	\$180.00	—
1PC	REAR SHOCK ABSORBER STOPPER O/S	Torn	80	\$120.00	—
1PC	REAR WINDSCREEN MOULDING	ner		\$86.00	—
1PC	REAR WHEEL HOUSING PANEL O/S	R		\$850.00	X
1PC	REAR DOOR O/S	Surf/nerf		\$966.00	—
1PC	REAR DOOR INNER LOCK O/S	shold		\$320.00	—
1PC	REAR DOOR INNER TRIM BOARD O/S	17		\$680.00	X
1PC	REAR DOOR GLASS OUTER MOULDING O/S	ner		\$90.00	—

100% 292 82

FRONT DOOR O/S *R*
ROCKER PANEL O/S *Body*

(102) *615* \$980.00 *X*
\$850.00
\$25,206.00

S.NETT

1SET	REAR DOOR VISOR O/S	<i>net</i>	\$50.00	<i>✓</i>
1PC	REAR SPORT RIM O/S	<i>che</i>	\$280.00	<i>✓</i>
1PC	REAR TYRE O/S	<i>put</i>	\$220.00	<i>802 132</i>
1PC	REAR END PANEL SEALANT	<i>net</i>	\$50.00	<i>✓</i>
1SET	REAR FLOOR PANEL INSULATOR	<i>11</i>	\$200.00	<i>X</i>
1PC	REAR WINDSCREEN SEALANT	<i>net</i>	\$50.00	<i>40</i>
1PC	REAR WINDSCREEN INNER SEAL	<i>net</i>	\$50.00	<i>40</i>

TO CHECK WIRING		\$50.00	<i>20</i>
TO DISMANTLE & REPLACED REVERSE SENSOR	<i>net</i>	\$80.00	<i>X</i>
TO TRANSFER BOOTLID MECHANISM	<i>11</i>	\$100.00	<i>X</i>
TO DISMANTLE & REFIX CUSHION UPHOLSTERY		\$120.00	<i>100</i>
TO SPRAY RUST PROOFING		\$120.00	<i>90</i>
TO CONDUCT WHEEL ALIGNMENT		\$100.00	<i>60</i>
TO DISMANTLE & REFIX FUEL TANK	<i>11</i>	\$100.00	<i>X</i>
TO MOUNT VEHICLE ON CAR O-LINER	<i>11</i>	\$380.00	<i>X</i>
TO DISMANTLE & REPLACED REAR UNDER CARRIAGE		\$380.00	<i>250</i>
TO TRANSFER REAR DOOR MECHANISM		\$100.00	<i>60</i>
LABOUR FOR PANEL BEATING & REPLACED PARTS		\$2,500.00	<i>1800</i>
TO PUTTY & SPRAY PAINTING		\$2,000.00	<i>1200</i>
TOTAL		\$32,136.00	

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

8275
102
7447.50
592
3580
11619.5
202
9285