

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: India International Insurance Pte Ltd
64 Cecil Street
#04-00 IOB Building
Singapore 049711

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Bhargavi Purushothaman Dhanya

Date: 24 Aug 2022

Preliminary Advice

Vehicle No	: SKW7804A	Accident Date	: 16/07/2022
Make	: TOYOTA WISH	Policy No.	: D20MFL0000326_02
Assignment Date	: 24/08/2022	Excess	: S\$0.00
Date of Inspection	: 24/08/2022	Est. Duration of Repair	: 5
Inspection At	: COMFORTDELGRO ENGINEERING PTE LTD (BRADDELL) 205 BRADDELL ROAD SINGAPORE 579701		

Point of Impact / General Description of Damages

Parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	11,453.75
Revised Amount	:S\$	5,630.12
		1,994.78
Total	:S\$	7,624.90
Lump Sum Repair	:S\$	

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	56,000.00
COE / PARF Rebate	:S\$	32,408.00
Salvage Value	:S\$	
Margin for Repair	:S\$	23,592.00

Remarks

- (X) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- (X) Other comments : Please note that the preliminary advice amount (Revised & Check Items) stated are subject to consistency check, part prices and labour cost.