

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd.  
4 Shenton Way  
#21-01 SGX Centre 2  
Singapore 068807

From: LKK Auto Consultants Pte Ltd  
51 Ubi Ave 1 #01-25  
Paya Ubi Industrial Park  
Singapore 408933

Attn: Jowyn Tay Mei Ling

Date: 22 Dec 2022

**Preliminary Advice**

Insured Vehicle No	: SFY212C	Accident Date	: 22/08/2022
TP Vehicle No	: SLQ349M	Assignment Date	: 24/08/2022
Make	: TOYOTA PRIUS HYBRID	Est. Duration of Repair	: 12
Date of Inspection	: 24/8/2022		
Inspection At	: BORNEO MOTORS (S) PTE LTD		

**Point of Impact / General Description of Damages**

Parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	35,015.53
Revised Amount	:S\$	20,256.07
Check Items (Estimated)	:S\$	0.00
Total	:S\$	20,256.07

Lump Sum Repair	:S\$	
-----------------	------	--

**Total Loss Consideration**

New for Old Value	:S\$	
Pre-Accident Value	:S\$	73,000.00
COE / PARF Rebate	:S\$	29,182.00
Salvage Value	:S\$	
Margin for Repair	:S\$	43,818.00

**Remarks**

- ( X ) The vehicle is economical for repair  
 ( ) The vehicle is not economical for repair  
 ( X ) Part-by-Part repair  
 ( ) Lump Sum repair

- ( X ) The above survey was conducted on a 'without prejudice' basis.

Please note that the preliminary advise amount (Revised & Check items) stated are subject to consistency check, part prices and labour cost .