




LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

PRE-REPAIR INSPECTION REPORT				
AXA INSURANCE PTE LTD 8 SHENTON WAY #24-01 AXA TOWER SINGAPORE 068811 ATTN: TEO KITTY			Ref: CS3/ASM22008134/Rqy3e2 Date: 19/09/2022 Code: ASM	
1. Policy Particulars :- (THIRD PARTY CLAIM)				
	Insured Veh.	SH 2201G	Veh. Inspected	GBF 5537E
	Policy No.	VFX/P2419138	Coverage (\$)	0.00
	Claim No.	S2M049JQ	Excess (\$)	0.00
	Assign From	TEO KITTY	Assign Date	24/08/2022
2. Vehicle Particulars & Condition				
	Make & Model	TOYOTA DYNA 150 M	c.c	2982
	Engine No.	HIDDEN	Year of Reg.	2016
	Chassis No.	JTFAT35YX0K207129	Colour	BLUE
	Odometer	276922 KM	Steering	IN ORDER
	Brakes	IN ORDER	Modification	NIL
	General	FAIR		
3. Conditions of Tyres				
		Size	Make	Balance
	R/H Front Tyre	195 R15C	MICHELIN	7 mm
	L/H Front Tyre	195 R15C	MICHELIN	7 mm
	R/H Rear Tyre	155 R12C (D)	MICHELIN	5/5 mm
	L/H Rear Tyre	155 R12C (D)	MICHELIN	5/5 mm
4. Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.			
5. General Information				
	Accident Date	22/08/2022	Inspect Date / Time	25/08/2022 (03:10 PM)
	Survey held at	5 SOON LEE STREET #06-36 PIONEER POINT		
	Repairer	TAI TIONG AUTO MOBIL TRADING		
5a. Remarks				
	A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS. D) THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$5,000-\$6,000			
5b. Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		8 Working Days	

Report Ref No. CS3/ASM22008134/Rqy3e2

Inspected By

MRB

MOHAMMED RASUL BIN MOHD YUNUS

Automotive Assessor

K.K.LAU

K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE, MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.
No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or
relying on this Report, in whole or in part, does so at his or her own risk.