



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
STRIDES AUTOMOTIVE SERVICES PTE LTD 60 WOODLANDS INDUSTRIAL PARK E4SINGAPORE 757705			Ref: CS/SMR22008140/Kny3e2 Date: 16/01/2023 Code: SMR	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SHF 333M	Veh. Inspected	SKU 2877H	
Policy No.		Coverage (\$)	0.00	
Claim No.	TAX/08/22/2066	Excess (\$)	0.00	
Assign From	HUA YEN	Assign Date	24/08/2022	
2. Vehicle Particulars & Condition				
Make & Model	MAZDA 5 (A)	c.c	1998	
Engine No.	HIDDEN	Year of Reg.	2015	
Chassis No.	JM6CW1071F0121905	Colour	METALLIC GREY	
Odometer	152081 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	205/60 R16	KAPSEN	3 mm	
L/H Front Tyre	205/60 R16	KAPSEN	3 mm	
R/H Rear Tyre	205/60 R16	YOKOHAMA	7 mm	
L/H Rear Tyre	205/60 R16	YOKOHAMA	7 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE FRONT AND REAR PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	23/08/2022	Inspection Date	25/08/2022	
Survey held at	ACCORD AUTO SERVICES PTE LTD 10 ANG MO KIO INDUSTRIAL PARK 2A AMK AUTO POINT #03-11 SINGAPORE 568047			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:			9 Working Days	