TwinCar AUTOMOTIVE PTE LTD

Company Registration and GST No. 200714616M

2 Kaki Bukit Avenue 2 #01-17 Kaki Bukit Autohub, Singapore 417921 Tel: 67440510 Fax: 67410510 Email: sales@n51.com.sg

Our Ref:

SJL 6822 Z SLX 7813 G

Your ref:

24 August 2022

CHINA TAIPING INSURANCE (S) PTE LTD

3 ANSON ROAD #16-00 SPRINGLEAF TOWER SINGAPORE 079909

Attn: Motor Claims Department

Dear Sir/Madam.

NAME OF CLAIMANT: MUHAMMAD IQBAL BIN NASRON

VEHICLE NUMBER: SJL 6822 Z

YOUR INSURED VEHICLE NUMBER: SLX 7813 G

ACCIDENT ON 22 AUG 2022 ALONG SLIP RD FROM PIE(TUAS) ONTO PIONEER RD NORTH

EXIT 38 AT ABOUT 17:40 HOURS

We refer to your email / fax dated **24 Aug 2022** informing that you wish to conduct a pre-repair survey and your List of Surveyors.

Our client confirmed appointment **LKK of Adrian Ling** as the Single Joint Expert for this matter.

Please be informed that the said vehicle can be inspected at:

TWINCAR AUTOMOTIVE PTE LTD

Kaki Bukit Autohub 2 Kaki Bukit Avenue 2 #01-17 Singapore 417921

Contact Person:

6842 0051 / 6744 0510 (Melody)

If you fail to conduct the pre-repair inspection within the next 2 working days excluding any intervening Saturday, Sunday or Public Holiday, the said workshop will commence repairs thereafter without further reference to you.

Yours faithfully,



FOR SURVEYOR:

Please initial here after completion of pre-repair inspection. Thank you!
Appointed surveyor:

(Name & Signature):

Date & Time of Inspection:

Twincar Automotive Pte Ltd