



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
STRIDES AUTOMOTIVE SERVICES PTE LTD 60 WOODLANDS INDUSTRIAL PARK E4SINGAPORE 757705			Ref: CS/SMR22008149/Gqy3m4 Date: 02/12/2022 Code: SMR	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SHB 5931A	Veh. Inspected	E-BIKE (CC25)	
Policy No.		Coverage (\$)	0.00	
Claim No.	TAX/08/22/2043	Excess (\$)	0.00	
Assign From	HUA YEN	Assign Date	24/08/2022	
2. Vehicle Particulars & Condition				
Make & Model	MIDO PRO	c.c	0	
Engine No.	HIDDEN	Year of Reg.		
Chassis No.		Colour	RED	
Odometer	-	Steering	IN ORDER	
Brakes	IN ORDER	Modification	NIL	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre			1 mm	
L/H Front Tyre			mm	
R/H Rear Tyre			1 mm	
L/H Rear Tyre			mm	
4. Description of Damages				
THE BICYCLE SUSTAINED DAMAGES AT THE FRONT PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	17/08/2022	Inspection Date	24/08/2022	
Survey held at	21 Woodlands Close Primz Bizhub #01-14			
Repairer	WAREHOUSESG PTE LTD			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:			1 Working Days	