



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
AXA INSURANCE PTE LTD C/O SEAH ONG & PARTNERS LLP 36 ROBINSON ROAD #12-03 CITY HOUSE SINGAPORE 068877		Ref: CS3/ASM22002660/Ecy3e2-1 Date: 02/09/2022 Code: ASM	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	SHA 6792H	Veh. Inspected	FBK 8373P
Policy No.	VFX/P2419138	Coverage (\$)	0.00
Claim No.	22.29979	Excess (\$)	0.00
Assign From	HENG XIN YI(SEAH ONG)	Assign Date	22/08/2022
2. Vehicle Particulars & Condition			
Make & Model	HONDA CB400	c.c	399
Engine No.	HIDDEN	Year of Reg.	2016
Chassis No.	NC421605015	Colour	BLACK
Odometer	-	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	FAIR		
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre	120/60-17	GOODYEAR	4 mm
L/H Front Tyre			mm
R/H Rear Tyre	160/60-17	GOODYEAR	4 mm
L/H Rear Tyre			mm
4. Description of Damages			
THE VEHICLE SUSTAINED DAMAGES AT THE O/S BODY AND FRONT PORTION. DAMAGES SEE DETAILS.			
5. General Information			
Accident Date	14/03/2022	Inspection Date	23/03/2022
Survey held at	I-MOTORING CREDIT PTE LTD BLK 1008 BUKIT MERAH LANE 3 #01-14 SINGAPORE 159722		
5a. Remarks			
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair			
ESTIMATED NORMAL PERIOD FOR REPAIR:		4 Working Days	