

(08/11/13)

wef

REF:

CC3/AIG22008158/Rqc

ASS. REC. BY:

CAME

201C

COEXPIRY: 2016/may

ASSIGNMENT

From: Date:

Estimated Cost:

OD/TP/WS/TP RES/OD RES/EVA/INV/MV

To Inspect Vehicle No: SLC 8775L

at Workshop m/s Premium

of 24, Honda Accord

Insured: AIG

Policy No.

Claims No.


Sum Insured: Excess: ~~TBA~~ 500

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value: 68K

IDAC Accident Rpt: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: 8 days Res.: Yes or No

Lum Sum: % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: Person Contacted:

Vehicle: IN / OUT

Veh No: SLC 8775L

Yr Regn: 2016 / may

Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Audi A3 Sedan 1.4 TFSI (CATR) c.c 1398

Colour: GREY A/C: Insured / Std / NI / NA

Sp. Reading: 160356 T/Radio: Insured / Std / NI / NA

Eng/No:

C/No: WAAZ228V541089776

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 205/55R16

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or

Front

Rear

R/Bal. 6 mm

R/Bal. 6 mm

L/Bal. 6 mm

L/Bal. 6 mm

D.O.A. 22/08/22

D.O.I. 24/08/22

Survey held at Premium

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

O/S FR

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

REPAIR LIMIT - 39K

Rasul finalised final fig \$20111.60, 8 days. (Red \$33320.40, 62%)

Date/Time, File Pass to?

☐: Prel. Report

Days Of Repair: 8

1)

☐: Final Report

Resurvey No. of Trip: 2

Date/Time, File Return to?

Survey Fee:

2)

Transportation:

Add Fee: ☐: Site Insp (\$

) S + RS. SI

☐: Interview (\$

) Photos

☐: Tech. Invs (\$

) Others

☐: Weekend (\$

TOTAL

Report Format: MER-OD

Lump Sum I.B.I. (\$ 20111.60)

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATE : ACCIDENT REPAIRS
WORKSHOP : UBI ROAD 1
CONTACT NO : 6366 2323
FAX NO : 6841 1183
REFERENCE : PA/OD/0723/2022/EQ
DATE : 23-Aug-22
WIP : 38490

VEHICLE IN WORKSHOP. KINDLY ARRANGE FOR SURVEY ON 23/08/2022

AIG ASIA PACIFIC INSURANCE PTE LTD

78 SHENTON WAY

#07-16 AIG BUILDING

SINGAPORE 079120

Attn: Motor Claims Dept

Tel: 6880 4602 - Fax: 6880 4838

OWNER'S NAME : MS LAM PEK YING
ADDRESS : 3 PASIR RIS VIEW
SINGAPORE 518586

TELEPHONE : HP +65 91899940
TYPE OF CLAIM : OWN DAMAGE CLAIM
POLICY NO : 2100468761-06
VEHICLE NO : **SLC 8775 L**
MODEL CODE : A3 SEDAN 1.4 TFSI
MODEL YEAR : 27/5/2016
ENGINE NO : CZC 540605
CHASSIS NO : WAUZZZ8V5G1089776
MILEAGE : -
DATE IN : -
ESTIMATED BY : JOHNNY BOO / ALLAN WU
ACCIDENT DATE : 22-Aug-22
PLACE OF ACCIDENT : MOHAMED SULTAN ROAD IN FRONT
OF SULTAN LINK BLDG

55 UBI ROAD 1, SINGAPORE 408699
TEL : 6366 2323 FAX : 6841 1183
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SLC 8775 L

S/N	NATURE OF JOBS	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE, CHECK AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR AND HEADLIGHT WASHER ASSY.	S/N \$ 360.00 ?	
2	TO REMOVE AND TRANSFER RHS HEADLIGHT'S CONTROL UNIT AND POWER MODULE.	S/N \$ 400.00 250	
3	TO REMOVE AND REINSTALL AIRCON CONDENSER, CHARGE AIR COOLER AND RADIATOR. CHECK ELECTRICAL FANS AND CONTROL UNIT. PRESSURISE COOLING SYSTEM. TO CARRY OUT VACUUM AND REGAS FOR R1234.	S/N \$ 1,500.00 X	
4	TO REMOVE AND TRANSFER RHS FRONT DOOR'S MULTI-LOCK SYSTEM AND POWER WINDOW DEVICES. INSPECT FOR DAMAGES.	S/N \$ 400.00 280	
5	TO DISMANTLE AND RENEW FRONT BUMPER, RHS FRONT FENDER, BONNET, RHS FRONT DOOR AND RHS HEADLIGHT. TO RENEW FRONT LOCK CARRIER AND ALIGN TO POSITION. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.	\$ 6,400.00 1500 QSW X 3	
TOTAL LABOUR CHARGES		: \$ <u>9,060.00</u>	

55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SLC 8775 L

S/N	NATURE OF JOBS	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
6	TO RESPRAY FRONT BUMPER, RHS FRONT FENDER, BONNET, RHS UPPER A-PILLAR AND RHS FRONT DOOR. <i>550 X 4</i>	5,000.00 <i>2200</i>	
7	TO RENEW RHS FRONT WHEEL SUSPENSION ASSY WITH SUBFRAME. S/N \$	2,500.00 ?	
8	TO RENEW RHS FRONT RIM WITH TYRE. TO CARRY OUT PRE/POST WHEEL ALIGNMENT. S/N \$	620.00 <i>520</i>	
9	TO CARRY OUT PRE/POST DISGNOSTIC CHECK. S/N \$	484.00 /	
TOTAL LABOUR CHARGES		: \$ 17,664.00	

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SLC 8775 L

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
1	FRONT BUMPER <i>de /</i>	1	\$ 2,377.00	
2	FRONT BUMPER FIXING PARTS <i>nee /</i>	1	\$ 195.00	
3	FRONT BUMPER TRIM - RH <i>?</i>	1	\$ 182.00	
4	FRONT BUMPER CLOSING ELEMENT - LOWER CENTRE <i>?</i>	1	\$ 175.00	
5	FRONT BUMPER PULL STRAP - LOWER <i>X</i>	4	\$ 231.00	
6	FRONT BUMPER GUIDE SECTION - RH <i>cm /</i>	1	\$ 43.00	
7	FRONT AIR GUIDE GRILLE - RH <i>mis /</i>	1	\$ 122.00	
8	RADIATOR GRILLE <i>cm /</i>	1	\$ 765.00	
9	RADIATOR GRILLE COVER <i>?</i>	1	\$ 109.00	
10	FRONT BUMPER FOAM FILLER PIECE <i>?</i>	1	\$ 154.00	
11	FRONT REINFORCEMENT BEAM COVER <i>?</i>	1	\$ 63.00	
12	FRONT BUMPER REINFORCEMENT BEAM <i>?</i>	1	\$ 847.00	
13	HORN SIGNAL HIGH TONE - RH <i>bt /</i>	1	\$ 213.00	
14	FRONT FENDER - RH <i>bue /</i>	1	\$ 954.00	
15	FRONT FENDER ATTACHMENT PARTS <i>?</i>	1	\$ 75.00	
16	FRONT FENDER BRACKET <i>nee /</i>	1	\$ 46.00	
17	FRONT FENDER RIVET <i>ne /</i>	6	\$ 23.00	
18	FRONT FENDER BRACE <i>?</i>	1	\$ 107.00	
19	FRONT FENDER BRACKET - RH <i>?</i>	1	\$ 31.00	
20	FRONT WHEEL HOUSING LINER - RH <i>de /</i>	1	\$ 183.00	
SUB TOTAL SPARE PARTS		:	\$ 6,895.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
SPARE PARTS ARE SPECIAL NETT.

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SLC 8775 L

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
21	FRONT WHEEL HOUSING LINER ATTACHMENT PARTS - RH <i>ra</i>	1	\$ 93.00	
22	BONNET <i>repair</i>	1	\$ 3,348.00	
23	BONNET STRIKER <i>X</i>	1	\$ 123.00	
24	BONNET EDGE PROTECTION <i>X</i>	1	\$ 31.00	
25	BONNET LOCK <i>X</i>	1	\$ 228.00	
26	BONNET CATCH HOOK <i>X</i>	1	\$ 71.00	
27	HEADLIGHT - RH <i>sa</i>	1	\$ 2,810.00	
28	HEADLIGHT BULB - RH <i>X</i>	1	\$ 454.00	
29	HEADLIGHT POWER MODULE - RH <i>?</i>	1	\$ 635.00	
30	HEADLIGHT CONTROL UNIT - RH <i>?</i>	1	\$ 1,279.00	
31	HEADLIGHT HOSE - RH <i>?</i>	1	\$ 60.00	
32	HEADLIGHT LIFT CYLINDER - RH <i>?</i>	1	\$ 211.00	
33	LIFT CYLINDER HOSE <i>?</i>	1	\$ 204.00	
34	LOCK CARRIER <i>X</i>	1	\$ 806.00	
35	RADIATOR COOLANT <i>X</i>	6	\$ 297.00	
36	RADIATOR AIR GUIDE - RH <i>?</i>	1	\$ 28.00	
37	RADIATOR OUTER SEAL STRIP - RH <i>?</i>	1	\$ 9.00	
38	RADIATOR AIR GUIDE - UPPER CENTRE <i>?</i>	1	\$ 14.00	
39	OUTSIDE TEMPERATURE SENSOR BRACKET <i>?</i>	1	\$ 21.00	
40	FRONT DOOR - RH <i>bf</i>	1	\$ 3,265.00	
SUB TOTAL SPARE PARTS		:	\$ 13,987.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
SPARE PARTS ARE SPECIAL NETT.

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SLC 8775 L

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
41	FRONT OUTER DOOR SEAL - RH <i>new</i>	1	\$ 179.00	
42	BONDING AGENT <i>new</i>	1	\$ 51.00	
43	CLEANING SOLUTION <i>new</i>	1	\$ 74.00	
44	APPLICATOR <i>new</i>	1	\$ 9.00	
45	FRONT DOOR ATTACHMENT PARTS <i>X</i>	1	\$ 252.00	
46	FRONT DOOR CATCH - RH <i>2?</i>	1	\$ 116.00	
47	FRONT TYRE PRESSURE DATA PLATE <i>new</i>	1	\$ 34.00	
48	FRONT WINDOW SLOT SEAL TRIM STRIP - RH <i>X</i>	1	\$ 346.00	
49	FRONT WINDOW GUIDE TRIM STRIP - RH <i>X</i>	1	\$ 287.00	
50	FRONT WATER DEFLECTOR STRIP - RH <i>X</i>	1	\$ 104.00	
51	FRONT ALUMINIUM RIM - RH <i>500</i>	1	\$ 1,303.00	
52	FRONT ASSEMBLY CARRIER <i>?</i>	1	\$ 1,108.00	
53	FRONT BONDED RUBBER BUSHES - UPPER / LOWER <i>?</i>	1	\$ 179.00	
54	FRONT LOWER CONTROL ARM - RH <i>?</i>	1	\$ 394.00	
55	FRONT STABILIZER - RH <i>?</i>	1	\$ 452.00	
56	FRONT WHEEL BEARING HOUSING - RH <i>?</i>	1	\$ 628.00	
57	FRONT WHEELHUB BEARING - RH <i>?</i>	1	\$ 554.00	
58	FRONT LOWER BALL JOINT - RH <i>?</i>	1	\$ 137.00	
59	FRONT COUPLING ROD - RH <i>?</i>	1	\$ 105.00	
60	FRONT GAS SHOCK ABSORBER - RH <i>?</i>	1	\$ 282.00	
SUB TOTAL SPARE PARTS		:	\$ 6,594.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
SPARE PARTS ARE SPECIAL NETT.

55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SLC 8775 L

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
61	FRONT DRIVE SHAFT - RH ?	1	\$ 1,521.00	
62	FRONT STEERING RACK ?	1	\$ 5,552.00	
63	FRONT STEERING BOX REPAIR SET ?	1	\$ 50.00	
64	FRONT INNER TIE ROD - RH ?	1	\$ 99.00	
65	FRONT OUTER TIE ROD END - RH ?	1	\$ 126.00	
66	FRONT NO PLATE ST ✓	S/N	\$ 60.00	
67	RHS FRONT TYRE X	S/N	TBC	
68	SUNDRIES ?		\$ 700.00	
TOTAL SPARE PARTS		:	\$ 35,584.00	
TOTAL LABOUR CHARGES		:	\$ 17,664.00	
GRAND TOTAL		:	\$ 53,248.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST
 LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.



55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

NAME : **Rahul - Hp 90010068**
SURVEYED DATE : **24/08/22 @ 1545**
AUTHORISED DATE :
EXCESS COST : **8 days**
LIABILITY : **Excess: TBA**
REMARKS : **Revers**
Resurvey before paint

PLEASE NOTE : THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF THE AFFECTED VEHICLE. SHOULD WE REQUIRE FURTHER LABOUR CHARGES AND SPARE PARTS IN THE PROGRESS OF REPAIR, WE SHALL INFORM YOU ACCORDINGLY. FOR INSPECTION OF VEHICLE, PLEASE REFER TO MS. NORAH KHAI AT TEL: 6768 9828 / 6768 9911 FOR APPOINTMENT.

YOURS FAITHFULLY,
PREMIUM AUTOMOBILES PTE LTD

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

JOHNNY BOO
BODY REPAIR MANAGER

ALLAN WU
CLAIMS CONSULTANT

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Actual Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date of Submission	22/08/2022 16:03 (SGT)
Reported by	Both
Date of Accident	22/08/2022 11:04 (SGT)
Exact Location of Accident	59 Mohamed Sultan Rd, Singapore 238999
Additional Location Information	MOHAMED SULTAN ROAD IN FRONT OF SULTAN LINK BLDG
Country/State of Loss	Singapore

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SLC8775L
INSURED/POLICYHOLDER	
Is company?	No
Name Of Registered Owner	LAM PEK YING
NRIC No	SXXXX701C
Email Address	VERON@LINK-MULTIPLES.COM
Mobile Phone No	(Phone) +65-91899940
Alternative Phone No	-

VEHICLE PARTICULARS

Manufacturer	Audi
Model	A3
Variant	SEDAN 1.4 TFSI
Exact purpose for which vehicle was being used at time of accident	Private use
Are you claiming under your own insurance policy for repair to your vehicle?	Yes
Vehicle Category	Private car
Transmission	Auto
CC	1395

INSURANCE COMPANY

Name of Insurance Company	AIG Asia Pacific Insurance Pte. Ltd.
Policy Number / Cover Note Number	2100468761-06

DRIVER

Name of Driver	LAM PEK YING
NRIC No	SXXXX701C
Date Of Birth	04/07/1961
Occupation	Indoor

Date Of Driving Pass
 Driving experience
 Gender
 Mobile Number
 Alt. Phone Number
 Email Address
 Address
 Address complement
 Postcode
 Is the driver the policyholder?
 If No, Relationship of the Driver with the Insured
 Does Driver Own Other Vehicles?
 Vehicle Registration Number of Other Vehicle Owned by Driver
 Insurance Company of Other Vehicle Owned by Driver

23/11/1985
 36 YEARS AND 9 MONTHS
 Female
 (Phone) +65-91899940
 -
 VERON@LINK-MULTIPLES.COM
 3 PASIR RIS VIEW
 -
 518586
 Yes
 -
 No
 -
 -

GENERAL INFORMATION OF THE ACCIDENT

Type of Accident
 Weather Conditions
 Road Surface

Collision - Change/cross lane
 Clear
 Dry

OTHER INFORMATION

Was any foreign vehicle involved in the accident?
 Number of vehicles involved in the accident
 Was anybody injured in the Accident?
 Was any injured conveyed to hospital by ambulance?
 Was any other vehicle or property damaged?
 Number of Passengers (Including Driver)
 Has the driver been approached by unknown person(s) soliciting/offering accident claims assistance?
 Translator's name
 Translator's ID
 Translator's phone number
 Translator's email
 Original language used in the statement

No
 2
 No
 -
 Yes
 1
 No
 -
 -
 -
 -
 -

DETAILS OF POLICE ACTION

Was the accident reported to the police?
 Was notice of intended Prosecution given?
 If yes, against whom?

No
 No
 -

CIRCUMSTANCES OF ACCIDENT

AS PER THE VIDEO: WHEN MY CAR WAS ALREADY 3/4 OUT WITH THE SIGNAL LIGHT ON, THE THIRD-PARTY VEHICLE SLU2740G WAS NO NEAR ME (A DISTANT). HIS VEHICLE WAS TRAVELLING VERY FAST. PLEASE ALSO NOTE THAT THERE WAS ANOTHER LADY SEATED FRONT SEAT AT THE TIME OF THE ACCIDENT AT 11.04 AM (ABOUT). MY DOOR WAS JAMMED INSTEAD OF ASSISTING ME OUT. BOTH THE DRIVER AND THE LADY WERE TALKING. AND LATER THE LADY LEFT. I HAVE TO SIGNAL/ WAVED TO HIM TO HELP ME OUT. PLEASE CHECK THE VIDEO AS I HAVE PICTURED OF THE ACCIDENT IN THAT MY CAR WAS 3/4 OUT. (THE SPEED THAT HE WAS TRAVELLING- YOU HAVE TO TAKE INTO CONSIDERATION.

ATTACHMENT(S)

Are accident photos available for attachment?
 Was there any video captured by Car Camera?

Yes
 Yes

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number
 Vehicle Manufacturer
 Vehicle Model
 Vehicle Variant

SLU2740G
 Mazda
 3
 -

Vehicle Colour
Vehicle Category
Name of Driver
Contact Number
Address
Address complement
Postcode
Insurance Company Name
Nature Of Damage
Details of property damaged in accident
No. Of Passenger (Including Driver)

Blue
Private car
LEE KOH YUAT CHRISTOPHER
(Phone) +65-97326192

-

-

-

-

-

-

2

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that

(a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of

(i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;

(ii) investigating the accident and/or my claims;

(iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;

(iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelope/mail packages); and/or

(v) complying with applicable law in administering, processing, handling and/or dealing with my claims.

(collectively the "Purposes")

(b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and

(c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.

[Signature]

Policyholder's Signature / Date & Time


Sketch Plan

Driver's Signature (If driver is not the policyholder) / Date & Time



Witnessed by Reporting Centre Personnel

A: SLC 8775 L
B: SLV 2740 G



Describe Circumstances of the Accident

AS PER VIDEO:-

When my ~~teach~~ car already 3/4 out with signal light on. The third party vehicle SL 4 27406 was no near me (a distant).

His vehicle was travelling very fast.

Please also note that there were another lady seated front seat at the time of accident 11.04am (about).


My door was jammed ~~but~~, instead of assisting me out. Both the driver and the lady were talking. And later the lady left.

I have to signal/waved to him to help me out.

Please check the video as I have pictured of the accident that my car wa 3/4 out. (The speed, but he was travelling - you have to take into consideration.


Declaration

We declare the foregoing particulars are true in every respect.



Policyholder's Signature / Date & Time

Driver's Signature (If driver is not the policyholder) / Date & Time



Witnessed by Reporting Centre Personnel

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Owner ID Type:	Singapore NRIC
Owner ID:	701C
Vehicle No.:	SLC8775L
Vehicle to be Exported:	No
Intended Deregistration Date:	25 Aug 2022
Vehicle Make:	AUDI
Vehicle Model:	A3 SEDAN 1.4 TFSI (ATTRACTION)
Primary Colour:	Grey
Manufacturing Year:	2016
Engine No.:	CZC540605
Chassis No.:	WAUZZZ8V5G1089776
Maximum Power Output:	92.0 kW (123 bhp)
Open Market Value:	\$25,096.00
Original Registration Date:	27 May 2016
First Registration Date:	27 May 2016
Transfer Count: -	0
Actual ARF Paid:	\$17,135.00
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	26 May 2026
PARF Rebate Amount:	\$11,137.00
COE Expiry Date:	26 May 2026
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$47,020.00
COE Rebate Amount:	\$17,645.00
Total Rebate Amount:	\$28,782.00

The information contained herein is correct as at 25 Aug 2022

OK

Audi A3 Sedan 1.4A TFSI Attraction

Overview

Financial

Accessories

Similar

Research

Photos

Map



UNITED MOTORRING PTE LTD

Price	\$68,800		
Depreciation ⓘ	\$16,470 /yr View models with similar depre	Reg Date	31-May-2016 (3yrs 9mths 5days COE left)
Mileage	N.A.	Manufactured ⓘ	2016
Road Tax ⓘ	\$624 /yr	Transmission	Auto
Dereg Value ⓘ	\$26,851 as of today (change)	OMV ⓘ	\$22,568
COE ⓘ	\$49,000	ARF ⓘ	\$13,596
Engine Cap	1,395 cc	Power	92.0 kW (123 bhp)
Curb Weight ⓘ	1,310 kg	No. of Owners ⓘ	2