

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: AIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way
#09-16
Singapore 079120

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Nadaraja, Deeban

Date: 25 Aug 2022

Preliminary Advice

Vehicle No	: SFS2221U	Accident Date	: 12/08/2022
Make	: AUDI A3	Policy No.	: 2070067312-02
Assignment Date	: 25/08/2022	Excess	: S\$0.00
Date of Inspection	: 24/08/2022	Est. Duration of Repair	: 10
Inspection At	: 24 BENOI SECTOR		
	REPAIRER: PREMIUM AUTOMOBILES PTE LTD		

Point of Impact / General Description of Damages

Parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	34,001.00
Revised Amount	:S\$	20,182.25
Check Items (Estimated)	:S\$	6,952.00
Total	:S\$	27,134.25
Lump Sum Repair	:S\$	

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	41,000.00
COE / PARF Rebate	:S\$	
Salvage Value	:S\$	19,867.00
Margin for Repair	:S\$	21,133.00

Remarks

- (x) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- (x) Other comments :Repairer able to undertake the repair cost not more than \$21,000.00. Please note that the preliminary advice amount (Revised & Check Items) stated are subject to part prices and labour cost check.