

Claim Audit

AUDIT TRAIL				
No.	On	Audit	Remarks	By
1	22 Aug 2022 19:47	Clm Veh Model Changed		[] Merimen Administrator
2	22 Aug 2022 19:47	Clm Created	Reg No: SFS2221U. Policy No: 2070067312-02. Acct Date: 2022/08/12. Claim Type: SC. Insurer: AIG Asia Pacific Insurance Pte. Ltd. (SG). Ins.Status => Notification. Created from SAS:SA1O228M0006	[I] Merimen Administrator
3	25 Aug 2022 10:32	Clm Registration Modified	Setl.Type:3->0. Claim Type:SC->OD.	[] CELINE FONG
4	25 Aug 2022 10:32	Adj Clm Retrieved	Adj: LKK Auto Consultants Pte Ltd (HQ)	[] CELINE FONG
5	25 Aug 2022 10:32	Adj Co Assigned	LKK Auto Consultants Pte Ltd (HQ):	[A] CELINE FONG
6	25 Aug 2022 10:32	Adj Next Rpt Changed	Next Rpt:Final Rpt.Due Date:2022/09/05	[A] CELINE FONG
7	25 Aug 2022 10:32	Adj Mandate Set	Approved:0.00.Reinsp:Adj decides.	[A] CELINE FONG
8	25 Aug 2022 10:32	Clm Registration Modified	Rep:1137->200611.	[A] CELINE FONG
9	25 Aug 2022 10:32	Clm Veh Model Changed	(204858) AUDI A3 1.4 SEDAN TFSI (AMBIENTE) (A).	[A] CELINE FONG
10	25 Aug 2022 10:32	Adj Adjuster Assigned	[None] -> MOHD RASUL	[A] CELINE FONG
11	25 Aug 2022 14:11	Adj Rpt Initiated		[A] Elaine Kuan Hwa Meen
12	25 Aug 2022 14:11	Clm Dtl Modified	Claim Conclusion: -> 3.	[A] Elaine Kuan Hwa Meen
13	25 Aug 2022 14:11	Clm Dtl Modified	JPJ Reg. Date: -> 2014/05/30.	[A] Elaine Kuan Hwa Meen
14	25 Aug 2022 14:11	Clm Details Notified		[A] Elaine Kuan Hwa Meen
15	25 Aug 2022 14:38	Adj Im. Advice Submitted	Next Rpt:Final Rpt.Due Date:2022/09/05	[A] HUEY YON
16	25 Aug 2022 14:43	Adj Mandate Request	Cur.Req:27134.25:damages consistent.repair cost economical. Repairer able to under take the repair cost not more than \$21,000.00. We have not authorise repair.	[A] HUEY YON

AUDIT TRAIL

No.	On Audit	Remarks	By
17	25 Aug 2022 16:08 Cim Registration Modified	Init.Est.: -> 5,000 - 6,000. Excess: -> 600.00. 2F Remarks: -> Not Applicable. GST: -> 7.00.	[I] Abu Kassim, Noor Mariesa
18	26 Aug 2022 09:02 Adj Next Rpt Changed	Next Rpt: Final Rpt. Due Date: 2022/09/05. Mandate Remarks: Vehicle may commence repair - To set repair limit @ \$21K to repairer. Checked and Supplementary items to resurvey with CLEAR photos for damage and consistency. Before paint photos for	[I] Lim, Kok-Chong
19	26 Aug 2022 09:02 Adj Mandate Set	Approved: 20182.25: Vehicle may commence repair - To set repair limit @ \$21K to repairer. Checked and Supplementary items to resurvey with CLEAR photos for damage and consistency. Before paint photos for all NEW Panels and Parts required	[I] Lim, Kok-Chong
20	08 Sep 2022 11:16 Adj Mandate Request	Cur. Req: 20732.25: Kindly approve on supplementary.	[A] HUEY YON
21	08 Sep 2022 17:00 Adj Mandate Request Cancelled		[A] HUEY YON
22	08 Sep 2022 17:03 Adj Mandate Request	Cur. Req: 21000.00: Kindly approve on supplementary.	[A] HUEY YON
23	12 Sep 2022 17:47 Adj Next Rpt Changed	Cur Rpt: Final Rpt. Cur Due Date: 2022/09/05. Mandate Remarks: To set repair limit @ \$21K to repairer. Checked and Supplementary items to resurvey with CLEAR photos for damage and consistency. Before paint photos for all NEW Panels and Parts r	[I] Lim, Kok-Chong
24	12 Sep 2022 17:47 Adj Mandate Set	Approved: 20732.25: To set repair limit @ \$21K to repairer. Checked and Supplementary items to resurvey with CLEAR photos for damage and consistency. Before paint photos for all NEW Panels and Parts required after repair and document into	[I] Lim, Kok-Chong

Date From



Date To



Audit Type

None



Go

ACTIVITY

No record

Merimen Billing for this case - Transaction History

Bill Ref No	Bill Date	Bill Type	Acc Type	Acc Name	Co Name (Branch)	Ref 1	Ref 2	Amount
2834449	25 Aug 2022 14:11:37	OD/TP Case (Adjuster)	Motor	LKK Auto Consultants Pte Ltd	LKK Auto Consultants Pte Ltd (HQ)	SFS2221U		11.00