



# National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H



Page No.:1 of 2

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHA 7976M

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<b><u>REPLACEMENT OF PARTS</u></b>				
1	FRONT BUMPER COVER	CRACKED	481.10	481.10
1	RADIATOR GRILLE	NOT NECESSARY	1,409.10	-
1	FRONT BUMPER MOULDING CENTRE UPPER	CUT	368.50	368.50
1	FRONT BUMPER TOP COVER	NOT NECESSARY	476.30	-
2	FRONT HEADLAMP LH / RH @\$2110.30	N/S NOT NECESSARY / O/S CRACKED	4,220.60	2,110.30
1	FRONT BUMPER GRILLE RH	MISSING	186.90	186.90
1	FRONT DAYLIGHT RH	NOT NECESSARY	642.50	-
1	HEAD LAMP PANEL	NOT NECESSARY	949.30	-
2	FRONT BUMPER BRACKET LH / RH @\$35.00	BROKEN (1PC ONLY)	70.00	35.00
1	FRONT FENDER RH	TO REPAIR SEE LABOUR	588.80	-
2	FRONT FENDER SHIELD LH / RH @\$164.70	NOT NECESSARY	329.40	-
1	FRT FENDER EMBLEM	NECESSARY	26.60	26.60
1	FRONT RH WHEEL COVER	NOT NECESSARY	346.40	-
10	FRONT BUMPER CLIPS	NECESSARY	22.00	22.00
1	BRACKET-FR BUMPER SIDE SU	BROKEN	28.00	28.00
	LESS 20% DISCOUNT		-2,029.10	-651.68
			8,116.40	2,606.72
<b><u>NETT ITEMS</u></b>				
1	FRONT NUMBER PLATE W/HOLDER (N)	NOT NECESSARY	55.00	-
	LESS 10% DISCOUNT		-5.50	-
			49.50	-
<b><u>LABOUR</u></b>				
	PANEL BEATING. INCLUSIVE OF THE REPAIR OF FRONT FENDER RH.		900.00	350.00
	SPRAY PAINTING.		800.00	500.00

Report Ref No. NS/INC22008188/Gqce2



## National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H



Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	CHECK LIGHTING.		60.00	30.00
			1,760.00	880.00
GRAND TOTAL			9,925.90	3,486.72
RECOMMENDED COST OF REPAIRS (CONFIRMED)				3,486.72

Report Ref No. NS/INC22008188/Gqce2

XING GUO QIANG

M.MATAI, AMSAE-A

Automotive Assessor

K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE,  
MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

**DISCLAIMER OF LIABILITY TO THIRD PARTIES:-** This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.