

COMFORTDELGRO ENGINEERING PTE LTD

REPAIR ESTIMATE*

VEHICLE NO SHC3406H

DATE 21.08.2022

MAKE/REG 10.08.2018

MODEL : HYUNDAI IONIQ G2

CHIANG/NTUC

Qty	Parts Description/ Labour	Type	Unit Price	Amount
1	TAIL LAMP RH <i>CRP</i>			\$935.40
1	REAR WHHEL COVER RH <i>Cert</i>			\$346.40
1	FRONT WING MIRROR RH <i>X repair</i>			\$1,391.70
	SUB TOTAL			\$2,673.50
	LESS 20%			\$534.70
	DISCOUNTED TOTAL			\$2,138.80
1	REAR FENDER ADVERTISEMENT APP <i>Cut</i>			\$100.00
				\$100.00
	Labour Charge			
	Panel Beating		250	\$700.00
	Spray Painting Charge		250	\$600.00
	Remove/refix Pillar Garnish		<i>nn</i> X	\$90.00
	Check Wiring		300	\$60.00
	TOTAL LABOUR			\$1,450.00
	ESTIMATE TOTAL			\$3,688.80
This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.				

2 Days.

45

Gao Qip

3pm

21/8/22

-20%: 1400

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary work(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: