

JWG INTERNATIONAL PTE. LTD.

10, ANG MO KIO IND PARK 2A, #03-08 AMK AUTOPOINT, SINGAPORE 568047

H/P: 9698 8882 | FAX: 6909 9592

E-Mail: jwg.claims@yahoo.com

To: MSIG

Att: Motor Claims Dept

ACCIDENT INVOLVING FBP3207T [YOUR INSURED] & SMY3493E [OUR CLIENT]
ON 23/08/2022.

ESTIMATED REPAIR COSTS FOR SMY3493E

MODEL : HONDA SHUTTLE

<u>QTY</u>	<u>PARTS</u>	<u>AMOUNT</u>	
1PC	WING MIRROR RH <i>broken</i>	<i>547.55</i> \$ 893.00	✓
1PC	WING MIRROR COVER RH <i>HH</i>	\$ 201.00	X
1PC	WING MIRROR GLASS RH <i>HH</i>	\$ 105.00	X
1PC	FRONT FENDER HYBRID EMBLEM LH <i>HF</i>	\$ 1,000.00	X
1PC	FRONT DOOR RH <i>ry</i>	\$ 240.00	X
1PC	FRONT DOOR WEATHERSTRIP RH <i>HH</i>	\$ 281.00	X
1PC	FRONT DOOR WINDOW MOULDING RH <i>HH</i>	\$ 140.00	X
1PC	FRONT DOOR BLACK PLASTIC RH <i>HH</i>	\$ 99.00	X
1PC	REAR DOOR RH <i>ry</i>	\$ 1,830.00	X
1PC	REAR DOOR WINDOW MOULDING RH <i>HH</i>	\$ 140.00	X
1PC	REAR DOOR BLACK PLASTIC RH <i>HH</i>	\$ 99.00	X

PARTS SUM: \$ 5,028.00

PARTS LESS 20%: \$ 1,005.60

PARTS TOTAL: \$ 4,022.40

LABOUR & SPECIAL NETT ITEMS

*	TO SUPPLY 1PCS RIM COVER <i>HH</i>	\$ 300.00	X
*	TO SUPPLY FRONT DOOR INNER TRIMBOARD CLIPS <i>HH</i>	\$ 50.00	X
*	TO SUPPLY REAR DOOR INNER TRIMBOARD CLIPS <i>HH</i>	\$ 50.00	X
*	TO REMOVE ALL INTERIOR UPHOLSTERLY ITEMS TO FACILIATE REPAIRS	\$ 300.00	HH
*	TO REMOVE & PANEL BEAT ALL DAMAGED ABOVE PARTS & PANELS	\$ 800.00 300/-	
*	TO RESPRAY NEW PAINTWORK FOR ALL DAMAGED AREAS	\$ 1,000.00 500/-	

*	TO CONDUCT COMPUTERIZED WHEEL ALIGNMENT	\$	120.00	HH
*	TO RNR REAR DOOR MECHANISM TO FACILITATE REPAIRS	\$	250.00	HH
*	TO RNR FRONT DOOR MECHANISM TO FACILITATE REPAIRS	\$	250.00	HH
*	TO CHECK & RE-FIX ALL ELECTRICAL WIRINGS	\$	200.00	HH
*	TO COMPUTERIZE DIAGNOSE FAULT CODES & CONTROL UNITS. RESET ALL MEMORIES TO FACTORY DEFAULT SETTINGS	\$	300.00	HH

LABOUR & S/N TOTAL: \$ 3,620.00

GRAND TOTAL ESTIMATED REPAIR COSTS (NON-INCLUSIVE OF 7% GST): \$ 7,642.40

31/08/2022 @ 1030h

HH Auto

2/2 P/Pat

Photo after rep

with damaged parts.

2/2

2 days.

2tk Auto

Check part prices.

2

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: