



Police Station Of Origin: Tampines N.P.C

6 Tampines Avenue 4 SINGAPORE 529682

Tel No: 1800-5871999

1 of 3 Report No. T/20210619/2032

REPORT OF A TRAFFIC ACCIDENT

Date/Time Report Made: 19/06/2021 13:45			Vide Report No.: G/20210618/0157	Station Diary No.
	ant's Partic			Providence of the Control of the Con
Name of Informant: MUHAMMAD ZAHIN BIN HATMAN		Address: APT BLK 707 TAMPINES STREET 71 #09-88 SINGAPORE 520707		
ID Type / ID No.: NRIC NO / S9018027D			Contact No.: Home/Office:	Makila concent
Nationality: SINGAPORE CITIZEN		Email: Mobile: 96663974		
Sex: Male	Age:	Date of Birth: 23/05/1990	Type of Informant:	
Race: Malay			Language:	Institution / School Name:
Occupation: SERVICE ENGINEER			Driving Licence Informa Class: 2B,2A,3,4	ation: Date of Expiry:

Type of Accident:	Injury Attended by Police	Drink Drive: No	Date/Time of Accident: 18/06/2021 18:30	Type of Location Straight Road	
TAMPINES S	TREET 71				
Weather: Clear		Road Surface: Dry		Road Speed Limit:	
Traffic Flow: Dual Carriage Type of Collisi		Traffic Control: Not Controlled		Traffic Volume:	

Vehicle No.	Туре	Make	Model	Color	0	T
FBK2401G	Motorcycle	HONDA	400X M	STORY OF THE OWNER, STORY	Condition	No of Passenger
				Red	Slightly	0
C 1070640	0	-			Damaged	
SJP7064S	Car				Slightly	0

	ehicle Insurance Insurance Company	T	200 800 200	
		The state of the s	Effective	Expiry Date
DNZ401G	TENET SOMPO INSURANCE PTE.	D21MTMC0100222	05/04/2021	04/04/2022





Police Station Of Origin: Tampines N.P.C 6 Tampines Avenue 4 SINGAPORE 529682 Tel No: 1800-5871999

2 of 3 Report No. T/20210619/2032

Brief Details.

On 18/06/2021 at about 1830hrs, I met with an accident along Block 708 Tampines Street 71, near the entrance of the carpark (TMT31). I was riding my motorcycle bearing plate no. FBK2401G. I saw the car bearing plate no.SJP7064S was driving in front of me. I thought the car was turning into the carpark. The car suddenly made an U-turn which I do not expected it as such I hit on the front right of the car (driver door). I fell off from the right side of the motorcycle and landed on the road.

CONTINUATION OF REPORT

My motorcycle right body frame, engine pipe, right mirror and right lever guard has scratches and brake lever bent downwards. I was also informed my motorcycle cannot be start up by the tow truck personnel. The other vehicle has dent and tire mark on the driver door.

I do not remember who called for the police but the incident was attended by the traffic police. I was conveyed by the ambulance to Changi General Hospital and was given 5 days MC (18/06/2021 to 22/06/2021). There was no passenger on my motorcycle.

No government property was damaged.

I would like to state that I do not have any video recording. The motorcycle, is my own personal motorcycle.

I am lodging this police report as requested by the IO from traffic police.





Police Station Of Origin: Tampines N.P.C 6 Tampines Avenue 4 SINGAPORE 529682 Tel No: 1800-5871999

3 of 3 Report No. T/20210619/2032

CONTINUATION OF REPORT

Sketch Plan

Informant is not able to provide sketch plan

IMPORTANT: Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the **report number** as reference.

Signature Of Officer Recording The Report: G / Insp TAN YU KAI, JUSTIN	Signature Of Informant:		
Signature Of Interpreter: Not applicable	Date/Time: 19/06/2021 13:45		
Officer In Charge Of Case:	Classification Of Case:		
Staff Sgt LEE GUANG HUL SINGAPURE POLICE FORCE	The state of the s		
Authentication Stamp NP168			