



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

OPINION ON REPAIR COST FOR VEHICLE NO. FBT 9430D

Qty	Description of Parts	Condition	Recommended (\$)
	<u>REPLACEMENT OF PARTS</u>		
1	FRONT RIM	CUT	320.00
1	FRONT FENDER WHEEL GUARD	CUT	57.00
1	FRONT FORK ASSY	BENT	500.00
1	FRONT FORK INNER TUBE	BENT	420.00
1	FRONT FORK OUTER TUBE	BENT	255.00
1	FRONT FORK BRACKET	BENT	125.00
1	FRONT FORK OIL SEAL	NECESSARY	10.00
1	FRONT HEADLAMP FAIRING	DENTED	196.00
1	FRONT WING MIRROR (O/S)	SCRATCHED	80.00
1	FRONT LH SIGNAL LAMP	SCRATCHED	85.00
1	FRONT RH SIGNAL LAMP	SCRATCHED	85.00
1	STEERING CONE	SCRATCHED	150.00
1	HANDLE BAR BALANCER RH	SCRATCHED	20.00
1	SIDE FAIRING	SCRATCHED	192.00
1	SIDE FAIRING TOP GARNISH	DISLODGE	95.00
1	EXHAUST MUFFLER HEAT SHIELD	CUT	65.00
1	EXHAUST MUFFLER ASSY	DENTED	400.00
1	REAR FENDER WHEEL GUARD	SCRATCHED	75.00
1	REAR LH SIGNAL LAMP	SCRATCHED	88.00
1	REAR RH SIGNAL LAMP	SCRATCHED	88.00
1	REAR BOX	SCRATCHED	200.00
1	DRIVER BASKET	CRACKED	45.00
1	REAR TAILLAMP FAIRING	CRACKED	150.00
	LESS 10% DISCOUNT		-370.10
			3,330.90
	<u>LABOUR</u>		
	REPLACING ACCIDENT DAMAGED PARTS, CHECK & REPAIR ACCIDENT AFFECTED AREAS.		600.00
	SPRAY PAINTING ACCIDENT AFFECTED AREAS.		300.00
	CHECK ELECTRICAL WIRING & LIGHTING SYSTEM FOR PROPER FUNCTION.		30.00



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Recommended (\$)
	CHECKING AND REPAIR FRONT FORK ALIGNMENT ACCORDING TO SPECIFICATION.		60.00
			990.00
GRAND TOTAL			4,320.90

RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			3,450.00
---	--	--	----------

Report Ref No. CS3/SPF22008221/Rvy3m4

NOTES : THE ESTIMATED UPPER RANGE OF REPAIR COST FOR THE DAMAGED VEHICLE IS IN THE REGION OF \$3,450-\$3,900

MOHAMMED RASUL BIN MOHD YUNUS

Automotive Assessor

K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE,
MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.