



SERVICE PRE-INVOICE

KAH MOTOR CO. SDN. BHD.

(A Member of the Oriental Holdings Berhad)

370 Ubi Road 3 Singapore 408651. Tel: +65 6841 3883 Fax: +65 6741 5022

255 Alexandra Road Singapore 159937. Tel: +65 6471 5458 Fax: +65 6471 5460

GST Reg No.: M200050223

Company Ref. No.: S60FC1380G

Customer: CU0085349 / CHINA TAIPING
Chassis No: JHMRC1890GC202229
License No: SLB2556Y
Mileage: 115553
Engine No: K24W72010905

Document No: SVO22038899
Printed By: SHNG
Order Date: 31. August 2022
Order Time: 5:57:10 PM
Service Advisor: NG SIN HAI

ITEM	DESCRIPTION	QTY	UNIT	DISC %	AMOUNT	7% GST Amount	Amount incld GST
	TP DIRECT SETTLEMENT (J/NO:) OWNER:ESO THOMAS KARIANMANAYIL OWNER INSURER:LIBERTY ACC DATE:25/08/2022 SURVEYED BY:RASUL DATE:26/08/2022 REF NO: TP INSURER:CHINA TAIPING TP VEH:SJT6050S SUPPLEMENTARY PART						
NMRS-4P-TM3040L	4PCS ACT RR.SENSOR	1	320.00		320.00	22.40	342.40
04814-T6A-M00ZA	TONGUE SET,R.FR.SEATBELT OUTER	1	477.30	30	334.11	23.39	357.50
77100-T6A-000ZA	PANEL COMPINSTRUMENT UPPER	1	941.80	30	659.26	46.15	705.41
77820-T6A-N80	MODULE ASSYPASSENGER	1	2,785.60	30	1,949.92	136.49	2,086.41
68100-T6A-Q10ZZ	TAILGATE COMP	1	1,146.20	30	802.34	56.16	858.50
74440-T6A-003	WEATHERSTRIPTAILGATE	1	125.70	30	87.99	6.16	94.15
91513-T6A-003	CLIPTAILGATE SPOILER	1	2.60	30	1.82	0.13	1.95
75701-T6A-000	EMBLEMH	1	28.20	30	19.74	1.38	21.12
04715-T6A-900ZZ	FACERR.BUMPER	1	608.30	30	425.81	29.81	455.62
71593-T6A-003	SPACERR.RR.BUMPER SIDE	1	20.40	30	14.28	1.00	15.28
71598-T6A-003	SPACERL.RR.BUMPER SIDE	1	20.40	30	14.28	1.00	15.28
91505-TM8-003	CLIP,BUMPER	7	2.30	30	11.27	0.79	12.06
66100-T6A-Q01ZZ	PANEL COMP,REAR	1	493.20	30	345.24	24.17	369.41
04656-T6A-310ZZ	PAN SET,3RD SEAT	1	361.70	30	253.19	17.72	270.91
72841-SH3-315	OILSHEET	3	43.50	30	91.35	6.39	97.74
84640-T6A-003ZA	LINING ASSYRR.PANEL	1	110.90	30	77.63	5.43	83.06
73214-T6A-003	MOLDINGRR.WINDSHIELD SIDE	2	19.20	30	26.88	1.88	28.76
73215-T6A-003	MOLDINGR.RR.WINDSHIELD CORNER	1	18.10	30	12.67	0.89	13.56
73216-T6A-003	MOLDINGL.RR.WINDSHIELD CORNER	1	18.10	30	12.67	0.89	13.56
73221-SR4-000	SPACERRR.W/SHIELD	4	4.20	30	11.76	0.82	12.58
73225-TM8-000	RUBBER A WINDSHIELD DAM	1	3.90	30	2.73	0.19	2.92
73226-SZW-000	DAMPERSTD 5X5	2	9.10	30	12.74	0.89	13.63
76711-T6A-003	CAPPIVOT	1	5.20	30	3.64	0.25	3.89
BO-NUM-COMP-S	NUMBER PLATE WITH CASING-S(N)	1	45.00		45.00	3.15	48.15
33100-T6A-Q11	HEADLIGHT ASSYR.WITH LED	1	2,516.00	30	1,761.20	123.28	1,884.48
33150-T6A-Q11	HEADLIGHT ASSY,L.WITH LED	1	2,516.00	30	1,761.20	123.28	1,884.48
33950-TY0-003	LIGHT ASSY, L. FR.FOG	1	285.90	30	200.13	14.01	214.14
33955-T6A-003	BRACKETL.FR.FOGLIGHT	1	67.70	30	47.39	3.32	50.71
71109-T6A-921	GARNISHL.FR.BUMPER	1	50.80	30	35.56	2.49	38.05
60100-T6A-000ZZ	HOOD COMP	1	718.70	30	503.09	35.22	538.31
60120-T6A-000ZZ	HINGE COMPR.HOOD	1	50.80	30	35.56	2.49	38.05
60170-T6A-000ZZ	HINGE COMPL.HOOD	1	50.80	30	35.56	2.49	38.05
74120-T6A-003	LOCK ASSYHOOD	1	113.70	30	79.59	5.57	85.16
74141-T6A-010	INSULATORHOOD	1	101.00	30	70.70	4.95	75.65
90672-SNB-003	HOLDERROD	1	2.10	30	1.47	0.10	1.57
80050-SP0-000	LABEL AIR CONDITIONER CAUTION	1	1.90	30	1.33	0.09	1.42
19043-PNB-A00	LABELCOOLANT INFORMATION	1	5.40	30	3.78	0.26	4.04
71121-T6A-003	BASEFR.GRILLE	1	180.80	30	126.56	8.86	135.42
71122-T6A-003	MOLDING,FR.GRILLE	1	290.20	30	203.14	14.22	217.36



SERVICE PRE-INVOICE

KAH MOTOR CO. SDN. BHD.

(A Member of the Oriental Holdings Berhad)

370 Ubi Road 3 Singapore 408651. Tel: +65 6841 3883 Fax: +65 6741 5022

255 Alexandra Road Singapore 159937. Tel: +65 6471 5458 Fax: +65 6471 5460

GST Reg No.: M200050223
Company Ref. No.: S60FC1380G

Customer: CU0085349 / CHINA TAIPING
Chassis No: JHMRC1890GC202229
License No: SLB2556Y
Mileage: 115553
Engine No: K24W72010905

Document No: SVO22038899
Printed By: SHNG
Order Date: 31. August 2022
Order Time: 5:57:10 PM
Service Advisor: NG SIN HAI

75700-TA0-A00	EMBLEMFR.	1	30.80	30	21.56	1.51	23.07
90301-ST0-003	NUT,PUSH 3MM	2	2.10	30	2.94	0.21	3.15
04711-T6A-900ZZ	FACE,FR.BUMPER	1	749.30	30	524.51	36.72	561.23
71105-T6A-901	GRILLEFR.BUMPER LOWER	1	71.90	30	50.33	3.52	53.85
71130-T6A-310ZZ	BEAM COMP,FR.BUMPER	1	312.40	30	218.68	15.31	233.99
71151-T6A-911	BASE,MID GRILLE	1	205.60	30	143.92	10.07	153.99
71152-T6A-921	UPPER MOLDING,MID GRILLE	1	169.30	30	118.51	8.30	126.81
71153-T6A-921	MID MOLDING,MID GRILLE	1	162.20	30	113.54	7.95	121.49
71193-T6A-003	SPACERR.FR.BUMPER SIDE	1	12.60	30	8.82	0.62	9.44
71198-T6A-003	SPACERL.FR.BUMPER SIDE	1	12.60	30	8.82	0.62	9.44
91505-TM8-003	CLIP,BUMPER	14	2.30	30	22.54	1.58	24.12
60210-T6A-300ZZ	FENDER COMPR.FR.	1	587.20	30	411.04	28.77	439.81
60260-T6A-300ZZ	FENDER COMPL.FR.	1	587.20	30	411.04	28.77	439.81
74100-T6A-000	FENDER ASSYR.FR.INNER	1	129.20	30	90.44	6.33	96.77
74206-T6A-000	GARNISHL.FR.FENDER	1	35.50	30	24.85	1.74	26.59
90682-SEA-003	CLIP ABUMPER	4	2.60	30	7.28	0.51	7.79
91505-TM8-003	CLIP,BUMPER	14	2.30	30	22.54	1.58	24.12
80111-T6A-003	CONDENSER COMP	1	729.90	30	510.93	35.77	546.70
08CLA-P9911LK8	COOLANT ANTI-FREEZE TYPE 2	6	23.20	30	97.44	6.82	104.26
19010-5X6-J02	RADIATOR COMP	1	1,442.10	30	1,009.47	70.66	1,080.13
60400-T6A-320ZZ	BULKHEAD COMP,FR.	1	465.10	30	325.57	22.79	348.36
38387-SLE-003	ANTENNA ASSY,L.RR.	1	64.80	30	45.36	3.18	48.54
74940-TR0-003	BUZZER ASSYSMART	1	64.30	30	45.01	3.15	48.16
60433-T6D-H00ZZ	SUPPORTR.FR.BULKHEAD UPP SIDE	1	35.90	30	25.13	1.76	26.89
60483-T6D-H00ZZ	SUPPORT,L.FR.BULKHEAD UPP SIDE	1	35.90	30	25.13	1.76	26.89
71159-T6A-921	LOWER MOLDING,L.MID GRILLE	1	43.50	30	30.45	2.13	32.58
80525-T2F-A01	SENSOR ASSYAMBIENT	1	46.50	30	32.55	2.28	34.83
17230-5X6-J00	CHAMBER ASSYRESONATOR	1	117.50	30	82.25	5.76	88.01
38611-5A4-H02	FAN COMPCOOLING	1	58.00	30	40.60	2.84	43.44
38615-5X6-J01	SHROUD COMP	1	89.70	30	62.79	4.40	67.19
38616-5X6-J02	MOTOR,COOLING FAN	1	345.40	30	241.78	16.92	258.70
74130-T6A-003	WIRE ASSYHOOD	1	39.30	30	27.51	1.93	29.44
77960-T6A-J12	UNIT ASSY,SRS	1	1,036.30	30	725.41	50.78	776.19
77930-T6A-J21	SENSOR ASSYFR.CRASH	2	140.90	30	197.26	13.81	211.07
91578-T0A-003	CLIPFR.GRILLE	4	2.40	30	6.72	0.47	7.19
79330-SAA-942	TRANSISTOR ASSY	1	152.20	30	106.54	7.46	114.00
		SUM PARTS:		16,241.84	1,136.94	17,378.78	
BOSUN	1466	1	50.00		50.00	3.50	53.50
		SUNDRIES					
BA02R	1466	1	250.00		250.00	17.50	267.50
		REMOVE & RENEW REVERSE SENSORS-4 PCS (N)					
BOJSE	1466	1	120.00		120.00	8.40	128.40
		SEALANT FOR REAR END PANEL					
BOJSE	1466	1	120.00		120.00	8.40	128.40
		SEALANT FOR REAR FLOOR PANEL					
BOJSE	1466	1	120.00		120.00	8.40	128.40
		SEALANT FOR TAILGATE					
BML02I	1466	1	250.00		250.00	17.50	267.50
		INSPECT RR LIGHTING MECHANISMS. PERFORM WATER TEST.(N)					



SERVICE PRE-INVOICE

KAH MOTOR CO. SDN. BHD.

(A Member of the Oriental Holdings Berhad)

370 Ubi Road 3 Singapore 408651. Tel: +65 6841 3883 Fax: +65 6741 5022

255 Alexandra Road Singapore 159937. Tel: +65 6471 5458 Fax: +65 6471 5460

GST Reg No.: M200050223
Company Ref. No.: S60FC1380G

Customer: CU0085349 / CHINA TAIPING
Chassis No: JHMRC1890GC202229
License No: SLB2556Y
Mileage: 115553
Engine No: K24W72010905

Document No: SVO22038899
Printed By: SHNG
Order Date: 31. August 2022
Order Time: 5:57:10 PM
Service Advisor: NG SIN HAI

BMI02D	1466 REMOVE & INSTALL SPEAKER BOARD RR SEATS TRUNK LININGS GARNISHES & ETC.(N)	1	650.00	650.00	45.50	695.50
BKTG02R	1466 REMOVE & TRANSFER ITEMS TO NEW TAILGATE. ADJUST & ALIGN TAILGATE.(N)	1	650.00	650.00	45.50	695.50
BG02D	1466 REMOVE & INSTALL RR. WINDSCREEN. (N)	1	650.00	650.00	45.50	695.50
BODAMKIT	1466 WINDSCREEN DAM KIT.	1	120.00	120.00	8.40	128.40
BKRP02M	1466 CUT OFF & RENEW RR PANEL. RR FLOOR PAN & RENEW DAMAGE PARTS.	1	4,368.16	4,368.16	305.77	4,673.93
BP06R	1466 SPRAY PAINTING ON REPAIRED OR REPLACED AREAS. (6P) REAR PORTION	1	3,120.00	3,120.00	218.40	3,338.40
BKBU01R	1466 REMOVE, RE-FIX AND ALIGN REAR VIEW CAMERA	1	580.00	580.00	40.60	620.60
BML01I	1466 INSPECT FR LIGHTING MECHANISMS & FOCUS HEADLIGHTS.(N)	1	250.00	250.00	17.50	267.50
BMC01D	1466 REMOVE & INSTALL RADIATOR WITH FITTINGS. PRESSURE TEST COOLING SYSTEM.(N)	1	480.00	480.00	33.60	513.60
BMA01D	1466 REMOVE & INSTALL A/C CONDENSER WITH FITTINGS. VACUUM & RECHARGE A/C GAS.(N)	1	530.00	530.00	37.10	567.10
BKBH11B	1466 CUT OFF & RENEW BULKHEAD FR L HOUSING COMP. STRAIGHTEN ALIGN FR L FRAME & RENEW DAMAGE PARTS.	1	3,900.00	3,900.00	273.00	4,173.00
BP06R	1466 SPRAY PAINTING ON REPAIRED OR REPLACED AREAS. (6P)	1	3,120.00	3,120.00	218.40	3,338.40
BC012R	1466 RESET VEHICLE SMART ENTRY SYSTEM	1	580.00	580.00	40.60	620.60
BMI00D	1466 REMOVE & INSTALL DASHBOARD INSTRUMENTAL PANEL AUDIO WIRING HARNESS & ETC.(N)	1	1,300.00	1,300.00	91.00	1,391.00
BMS00R	1466 RENEW BOTH DRIVER & PASSENGER AIRBAG ASSY ECU & RESET SRS SYSTEM.(N)	1	650.00	650.00	45.50	695.50
BMS02R	1466 REMOVE & RENEW SEATBELT TENSIONER, ECU & CRASH SEN RESET SYSTEM.	1	650.00	650.00	45.50	695.50



SERVICE PRE-INVOICE

KAH MOTOR CO. SDN. BHD.

(A Member of the Oriental Holdings Berhad)

370 Ubi Road 3 Singapore 408651. Tel: +65 6841 3883 Fax: +65 6741 5022

255 Alexandra Road Singapore 159937. Tel: +65 6471 5458 Fax: +65 6471 5460

GST Reg No.: M200050223

Company Ref. No.: S60FC1380G

Customer: CU0085349 / CHINA TAIPIING
Chassis No: JHMRC1890GC202229
License No: SLB2556Y
Mileage: 115553
Engine No: K24W72010905

Document No: SVO22038899
Printed By: SHNG
Order Date: 31. August 2022
Order Time: 5:57:10 PM
Service Advisor: NG SIN HAI

BO-TOW	1466	1	250.00	250.00	17.50	267.50
	TOWING SERVICES (MBBS)					

SUM LABOUR:	22,758.16	1,593.07	24,351.23
--------------------	------------------	-----------------	------------------

TOTAL SGD	39,000.00	2,730.01	41,730.01
------------------	------------------	-----------------	------------------

Total Payable (SGD)	41,730.01
----------------------------	------------------

GST Amount is calculated from individual line(s)