

National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315





| AUTOMOBILE INSPECTION REPORT | | | | | | |
|--|--|-------------------------------------|--------------|----------------------|------------|--|
| INCOME INSURANCE LTD | | | Ref: | NS/INC22008252/Tvcm4 | | |
| 73 BRAS BASAH ROAD #05-01 NTUC TRADE UNION HOUSESINGAPORE 189556 | | | Date: | 04-10-2022 INC4 | | |
| 1. Policy Particulars :- THIRD PARTY CLAIM | | | | | | |
| | Insured Veh. | SJM 4850A | 1 | nspected | SHA 8158B | |
| | Policy No. | | Cover | age (\$) | 0.00 | |
| | Claim No. | MT/1188539-001 | Exces | s (\$) | 0.00 | |
| | Assign From | | Assign | n Date | 25/08/2022 | |
| 2. Vehicle Particulars & Condition | | | | | | |
| | Make & Model | TOYOTA PRIUS | c.c | | 1798 | |
| | Engine No. | HIDDEN | Year o | f Reg. | 2020 | |
| | Chassis No. | JTDKB3FU103091230 | Colou | r | YELLOW | |
| | Odometer | 263401 | Steerii | ng | IN ORDER | |
| | Brakes | IN ORDER | Modifi | cation | NIL | |
| | General | GOOD | | | | |
| 3. Conditions of Tyres | | | | | | |
| | | Size | Make | | Balance | |
| | R/H Front Tyre | 195/65 R15 | WEST | | 6 mm | |
| | L/H Front Tyre | 195/65 R15 | WEST | LAKE | 6 mm | |
| | R/H Rear Tyre | 195/65 R15 | WEST | LAKE | 6 mm | |
| | L/H Rear Tyre | 195/65 R15 | WEST | LAKE | 6 mm | |
| 4. | Description of Damages | | | | | |
| | THE VEHICLE SUSTAINED DAMAGES AT THE FRONT PORTION. | | | | | |
| | DAMAGES SEE DETAILS. | | | | | |
| 5. | General Information | | | | | |
| | Accident Date | 25/08/2022 | Inspec | tion Date | 25/08/2022 | |
| | Survey held at | COMFORTDELGRO ENGINEER | RING PTE LTD | | | |
| | | 59 LOYANG DRIVE SINGAPORE 508969 | | | | |
| 5a. | | Remarks | | | | |
| | A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS. | | | | | |
| 5b. | Estimate Days of Repair | | | | | |
| | ESTIMATED NORMAL PERIOD FOR REPAIR: 2 Working Days | | | | | |