

COMFORTDELGRO ENGINEERING PTE LTD

REPAIR ESTIMATE

VEHICLE NO SHA8158B

MAKE : TOYOTA

MODEL : PRIUS

DOA 25.08.22

INS. NTUC (SPP)

MVA JUMANI

PARTS DESCRIPTION	QTY	UNIT PRICE	AMOUNT
FRT BUMPER	1		\$ 586.18 <i>de</i>
HEADALMP ASSY LH	1		\$ 2,637.60 <i>run</i>
EMBLEM 'H'	1		\$ 88.00 <i>de</i>
FOG LAMP LH	1		\$ 920.00 <i>run</i>
FRT BUMPER CLIPS	10		\$ 22.00 <i>de</i>
RADIATOR GRILL	1		\$ 438.00 <i>out</i>
FRT BUMPER LOWER GRILLE	1		\$ 301.90 <i>out</i>
FRT BUMPER TOW COVER LH	1		\$ 28.38 <i>mis</i>
FRT BUMPER SPONGE	1		\$ 78.80 <i>one</i>
FRT BUMPER BEAM	1		\$ 812.89 <i>run</i>
FRT NUMBER PLATE GARNISH	1		\$ 99.00 <i>one</i>
		1642.26	
		1231.70	
SUB TOTAL			\$ 6,012.75
LESS 25%			\$ 1,503.00
DISCOUNTED TOTAL			\$ 4,509.00
FRT NUMBER PLAET			\$ <i>mis</i> 50.00
			10% - 45
			\$ 50.00
LABOUR CHARGE			\$ 350 400.00
PANEL BEAT			\$ 250 300.00
SPRAYPAINT			\$ 50 50.00
CHECK WIRING			\$ <i>run</i> 50.00
TUFF KOTE			
TOTAL LABOUR			\$ 800.00
ESTIMATE TOTAL			\$ 5,359.00

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

640

Tanjin 47445944
 WP 25/8/2024
 HS Rummy at Humeron
 Tanjin e Humeron
 2 days

1916.70

1550

2 days