

COMFORTDELGRO ENGINEERING PTE LTD

REPAIR ESTIMATE*

VEHICLE NO SHD4089C

25.08.2022

MAKE REG 30.10.2019

CHIANG/ NUTC

MODEL IONIQ G3

Qty	Parts Description/ Labour	Type	Amount
1	REAR BUMPER		Rp \$459.40
2	REAR BUMPER SIDE BRACKET RH		un X \$55.80
1	REAR BUMPER REINFORCEMENT		un X \$394.80
1	REAR BUMPER CENTRE MOULDING		de \$451.25
2	REAR BUMPER REFLECTOR RH		un X \$41.50
10	REAR BUMPER CLIPS		\$2.20 per \$22.00
	SUB TOTAL	473.25	\$1,424.75
	20.00%	378.60	\$284.95
	DISCOUNTED TOTAL		\$1,139.80
1	REAR REVERES SENSOR		un X \$180.00
1	REAR NUMBER PLATE W/ HOLDER		10% - un \$55.00
1	REAR FENDER ADVERTISEMENT		un \$100.00
1	REAR BUMPER ADVERTISEMENT		un \$50.00
		199.50	\$361.50
	Labour Charge		
	Panel Beating		350 \$550.00
	Spray Painting Charge		250 \$300.00
	Check Lighting and Wiring		un X \$60.00
	Tuff Kote	630	un X \$60.00
	Remove/refix Reverse sensor		30 \$60.00
	TOTAL LABOUR	1208.10	\$1,030.00
		418 \$950	
	ESTIMATE TOTAL	* 2 days	\$2,169.80
This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.			

Tanphi 97495749
 'wp' 25/8/22 @ 4pm
 L/S Resurvey after repair
 tanphi@lkhants.com
 - 2 days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: