



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
BLUWEL AUTOMOTIVE SERVICE PTE LTD			Ref:	CS/TP22008259/Ucy3m4
BLK 1 KAKI BUKIT AVE 6			Date:	12/09/2022
#01-28/53/55/56 (MAIN OFFICE)SINGAPORE				
417883				
ON BEHALF OF ABC CAR LEASING PTE LTD			Code:	TP149
<b>1. Policy Particulars :- THIRD PARTY CLAIM</b>				
Insured Veh.		Veh. Inspected	SNE 9883S	
Policy No.		Coverage (\$)	0.00	
Claim No.		Excess (\$)	0.00	
Assign From		Assign Date	26/08/2022	
<b>2. Vehicle Particulars &amp; Condition</b>				
Make & Model	TOYOTA NOAH HYBRID (A)	c.c	1797	
Engine No.	HIDDEN	Year of Reg.	2022	
Chassis No.	ZWR800505966	Colour	BLACK	
Odometer	31986 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
<b>3. Conditions of Tyres</b>				
	Size	Make	Balance	
R/H Front Tyre	185/65 R15	YOKOHAMA	7 mm	
L/H Front Tyre	185/65 R15	YOKOHAMA	7 mm	
R/H Rear Tyre	185/65 R15	YOKOHAMA	7 mm	
L/H Rear Tyre	185/65 R15	YOKOHAMA	7 mm	
<b>4. Description of Damages</b>				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.				
DAMAGES SEE DETAILS.				
<b>5. General Information</b>				
Accident Date	24/08/2022	Inspection Date	26/08/2022	
Survey held at	BLUWEL AUTOMOTIVE SERVICE PL BLK 1 KAKI BUKIT AVE 6 #01-28/53/55/56 (MAIN OFFICE) SINGAPORE 417883			
<b>5a. Remarks</b>				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
<b>5b. Estimate Days of Repair</b>				
ESTIMATED NORMAL PERIOD FOR REPAIR:			4 Working Days	