

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile					
	LONPAC INSURAN	NCE BHD		Ref:	CS3/LPC22008267/Rvy3
	300 BEACH ROAD #17-04/07 THE CO	NCOURSESINGAPORE 199555		Date:	26/08/2022
				Code:	LPC2
1.	Policy Particulars :- (THIRD PARTY CLAIM)				
	Insured Veh.	XD 5780T	Veh. Inspected		YP 9848G
	Policy No.		Coverage (\$)		0.00
	Claim No.		Excess (\$)		0.00
	Assign From	GERALD POH	Assign Date		26/08/2022
2. Vehicle Particulars & Condition					
	Make & Model		c.c		0
	Engine No.	HIDDEN	Year of Reg.		
	Chassis No.		Colour		
	Odometer	Steering			
	Brakes	Modification			
	General				
3. Conditions of Tyres					
		Size	Make		Balance
	R/H Front Tyre				mm
	L/H Front Tyre				mm
	R/H Rear Tyre				mm
	L/H Rear Tyre				mm
4.	Description of Damages				
5.	General Information				
	Accident Date	25/08/2022	Inspection Dat	е	26/08/2022
	Survey held at	4 Penjuru Close Singapore 6085	74		
	Repairer	AAK LOGISTICS SERVICES PL			
5a.	Remarks				
	A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.				