

HOCK WAH MOTOR WORKSHOP PTE LTD

BLK 3011 BEDOK INDUSTRIAL PARK E
BEDOK NORTH AVE 4,
#01-2008/10/12 SINGAPORE 489977
TEL : 6441 5655 FAX : 6441 5355/6243 8121
R.O.C No : 200104141D GST Reg. No. 20-0104141-D

TO : 53162923J
LIAN GIAP NEWS AGENCY
BLK 217 PASIR RIS STREET 21
10-146
SINGAPORE 510217
TEL : FAX :
PH : 98520258
ATTN :

ESTIMATE BILL

Number : EB00006076
Date : 23/08/2022
Case No : AD00012991
Vehicle No : GBE9178L
Chassis : KDH2010189364
Year of Mfr : 2015
Policy No :
Model : TOYOTA HIACE 3.0
DX DIESEL TURBO

Term:

Sn	DESCRIPTION	QTY	U PRICE	MT 2WD LGV DISC	AMOUNT
1	SLIDING DOOR LH <i>no/ent</i>	1.0	2,030.00	25	1,522.50
2	SLIDING DOOR GLASS LH <i>shotter</i>	1.0	839.00	25	629.25
3	SLIDING DOOR INNER LOCK LH <i>17</i>	1.0	270.10	25	202.58
4	REAR FENDER GLASS LH <i>sketch</i>	1.0	839.00	25	629.25
5	REAR FENDER LH <i>no/cr</i>	1.0	1,640.40	25	1,230.30
List Price - Parts Sub Total					4,213.88
6	WINDSCREEN SEALANT <i>ner</i>	4.0	24.00	0	96.00
7	SLIDING DOOR COMPANY STICKER LH <i>ner</i>	1.0	350.00	0	350.00
Special Nett Price - Parts Sub Total					446.00
Parts Total					4,659.88
8	LABOUR TO REMOVE & REFIT NECESSARY PARTS	1.0	1,500.00	0	1,500.00
9	SPRAY PAINT ON THE AFFECTED AREAS	1.0	1,200.00	0	1,200.00
10	ANTI-RUST COATING	1.0	200.00	0	200.00
11	TO REMOVE & REFIT DOOR/FENDER GLASS	1.0	280.00	0	280.00
Labour 1 Sub Total					3,180.00
SINGAPORE DOLLARS : EIGHT THOUSAND THREE HUNDRED EIGHTY-EIGHT AND CENTS SIXTY-SEVEN ONLY					
Less Excess					0.00
SUBTOTAL					7,839.88
GST 7.00%					548.79
TOTAL					8,388.67

Date of accident : 22/08/2022 01:30 PM. Place : LOADING BAY OF LOGISTICS HUB (COGENT)

E. & O. E.

HOCK WAH MOTOR WORKSHOP PTE LTD

CUSTOMER SIGNATURE

AUTHORISED SIGNATURE