



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Immediate Advice

To : ALLIANZ INSURANCE

Date: 13/09/22

Survey Details:

Date of loss	22-Aug-2022
Date of appointment	24-Aug-2022
Date of survey	5-Sep-2022
Location of survey	HOCK WAH MOTOR WORKSHOP PTE LTD

Vehicle Details:

Claim Type:	THIRD PARTY CLAIM
Vehicle number	GBE9178L
Make and Model	TOYOTA HIACE 3.0 DX DIESE
Date of registration	29-Apr-16
Market Value	\$ 36,000.00
Parf Rebate	\$ 13,690.00
Nett Loss	\$ 22,310.00

Repair details:

Initial Estimate	7,839.88
------------------	----------

Proposed/Revised repair cost:

Parts	\$ 3,800.38
Check items (estimate)	NIL
Labour	\$ 1,680.00
Total	\$ 5,480.38
Lump Sum(if applicable)	\$ 4,300.00

Number of days for repair	4.0
---------------------------	-----



Remarks:

OID reversed and hit TP parked vehicle.

Mandate:

Liability(TP)	100%	
Proposed repair cost (w/GST)	\$ 4,601.00	\$ 4,601.00
Loss of use (6days x \$100.00)	\$ 600.00	NIL
Loss of rental (6days x \$100.00)(w/GST)	NIL	\$ 642.00
Loss of income	NIL	NIL
LTA search fees	\$ 7.45	\$ 7.45
Others	NIL	NIL
Proposed Total	\$ 5,208.45	\$ 5,250.45