

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

DATE: 31.08.2022

DAY : Wednesday

Rasul
Hp 90010068

1 day
29/08/22 @ 0900

Resurvey after repair

SBS Transit

SBS Transit Ltd
Soon Lee Depot
28 Soon Lee Road Singapore 628083

Mainline +65 6284 8866
Facsimile +65 6262 3055

www.sbstransit.com.sg

Company Registration No: 199208653M

Workshop Accident Repair Estimate
****FOR SURVEYOR ONLY****

ACCIDENT DATE	22.08.2022	BUS REGISTRATION NUMBER	SBS7580Y
ACCIDENT TIME	15:15 HRS	BUS TYPE (DD OR SD)	DD
THIRD PARTY CLAIM AGAINST	"UNKNOWN", PRIVATE CAR	DATE of SURVEY	29.08.2022

S/No	SECTION A :	PARTS & MATERIAL COST	
	SBS7580Y, Volvo B9TL Eu5, DD, AC, 3 Axle		
	Part or Item Description	Quantity	Total Cost
1	30750005 = FRONT WINDSCREEN.UPP/S <i>CMA</i>	1 pc	\$ 1,235.00
2	LAST ITEM		\$ -
3			\$ -
4			\$ -
5			\$ -
6			\$ -
7			\$ -
8			\$ -
9			\$ -
10			\$ -
11			\$ -
12			\$ -
13			\$ -
14			\$ -
15			\$ -
TOTAL PARTS & MATERIAL COST			\$ 1,235.00

SECTION B :	ASSESSMENT/REPAIR/SPRAY PAINT (LABOUR COST)	
	FOR WORKSHOP ONLY.....	
Labour		\$ 1,284.40
Spray Painting		\$ -
Vinyl		\$ -
Advertisement		\$ -
		\$ -
TOTAL LABOUR COST		\$ 1,284.40

SECTION C :	SUMMARY	
	TOTAL REPAIR COSTS	\$ 2,519.40
	TOTAL DOWNTIME	1.0 day

NOTE:

- 1) Repair cost is excluding Loss of use.
- 2) Additional parts might be required during the course of repair.