



AUTO UNITED SG PTE LTD

13 Kaki Bukit Rd 4, #03-29,

Bartley Biz Centre, Singapore 417807

Tel: 6844 1184

TP AWA.

Veron.

Page No. 1

Vehicle No. SMA6339A

HONDA FREED

GB71067484

QTY	DESCRIPTION	CONDITION	REPAIRER'S ESTIMATE(S\$)	SURVEYOR ADJUSTMENT
PARTS (LIST ITEMS)				
1	FRONT BUMPER <i>Defound</i>		986.40	✓
2	FRONT BUMPER SIDE HOLDER @38.60 <i>Hit Rnd</i>		77.20	✓ 38.60
3	FRONT BUMPER LOWER GRILLE <i>Renew</i>		165.80	✓
4	FRONT BUMPER REINFORCEMENT <i>Dented</i>		295.80	✓
5	FRONT BUMPER TOW COVER <i>Renew</i>		24.90	✓
6	FRONT GRILLE <i>Crackd</i>		690.40	✓
7	FRONT GRILLE LOGO <i>Renew</i>		78.10	✓
8	FRONT GRILLE OUTER MOULDING <i>Crackd</i>		245.90	✓
9	HEADLAMP @1740.50 <i>Hit Crackd</i>		3481.00	✓ 1740.50
10	HEADLAMP LOWER BRACKET @45.90 <i>Hit Crackd</i>		91.80	✓ 45.90
11	BONNET <i>Distord</i>		820.60	✓
12	BONNET LOCK <i>Distord</i>		103.70	✓
13	BONNET HINGE @57.90 <i>Best.</i>		115.80	✓
14	BONNET WEATHERSTRIPE @44.50 <i>Renew</i>		89.00	✓
15	FRONT SUPPORT PANEL <i>Renew</i>		752.60	✓
16	AIR CON CONDENSER <i>Dented.</i>		987.90	✓
17	RADIATOR <i>Renew</i>		988.70	✓
			9995.60	
		less	20%	20%
			1999.12	
			7996.48	
SPECIAL NETT ITEMS				
1	FRONT NUMBER PLATE <i>3 Renew</i>		30.00	✓
2	FRONT NUMBER PLATE HOLDER		30.00	✓
3	FRONT BUMPER CLIPS <i>3 Renew</i>		30.00	✓
4	FRONT GRILLE CLIPS		20.00	✓
5	BONNET WEATHERSTRIPE CLIPS <i>3 Renew</i>		20.00	✓
6	RADIATOR COOLANT		50.00	✓
Total Parts			180.00	

50.



AUTO UNITED SG PTE LTD

13 Kaki Bukit Rd 4, #03-29,

Bartley Biz Centre, Singapore 417807

Tel: 6844 1184

Page No. 2

Vehicle No. SMA6339A

S/N	DESCRIPTION	REPAIRER'S ESTIMATE (S\$)	OUR ASSESSMENT (S\$)
	LABOUR		
1	PANEL BEATING	1000.00	600
2	SPRAY PAINTING	1000.00	800
3	WIRING	50.00	30
4	TO APPLY TUFF COAT	150.00	40
5	TO REMOVE CONDENSER & TO TOP UP AIR CON GAS	120.00 x	60
6	TO REMOVE RADIATOR & TO TOP UP COOLANT	120.00 x	
	Labour Total :	2440.00	1330
TOTAL (PARTS & LABOUR):		10616.48	

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Total 6483.68

L/S: 5.2K

04 Days

5.2K