



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile CS3/SMO22005032/Kvy3-1				
SOMPO INSURANCE SINGAPORE PL 50 RAFFLES PLACE #03-03 SINGAPORE LAND TOWERSINGAPORE 048623			Ref: CS/SMO22005032/y3 Date: 27/05/2022 26/08/2022 Code: SMO	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SMJ 9008M	Veh. Inspected	SNA 8708T	
Policy No.		Coverage (\$)	0.00	
Claim No.	CMTD2201596/GPL	Excess (\$)	0.00	
Assign From	GRACE TEO GNOH PAU LOONG	Assign Date	27/05/2022 26/08/2022	
2. Vehicle Particulars & Condition				
Make & Model		c.c	0	
Engine No.	HIDDEN	Year of Reg.		
Chassis No.		Colour		
Odometer	-	Steering		
Brakes		Modification		
General				
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre			mm	
L/H Front Tyre			mm	
R/H Rear Tyre			mm	
L/H Rear Tyre			mm	
4. Description of Damages				
5. General Information				
Accident Date	08/05/2022	Inspection Date	30/05/2022	
Survey held at	MING HUA AUTO SERVICES 160 SIN MING DRIVE #02-16 SIN MING AUTO CITY SINGAPORE 575722			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				