



MY CAR CONSULTANT PTE LTD

Reg no.: 201605878Z

Address: 60 JALAN LAM HUAT, CARROS CENTRE #05-68 5737986

HP: 98888885

Estimation

Date: 23/8/2022
 Vehicle: SMX7895H
 Make / Model: TOYOTA PRIUS
 Chassis: ALLIANZ

No.	Description	Unit	Unit Price	Amount
1	BONNET LOCK X NV	1	\$ 312.00	\$ 312.00
2	FRONT BUMPER X Rep	1	\$ 798.00	\$ 798.00
3	FRONT BUMPER LOWER X	1	\$ 651.00	\$ 651.00
4	FRONT BUMPER LOGO X	1	\$ 68.00	\$ 68.00
5	FRONT BUMPER SIDE RETAINER X	2	\$ 58.00	\$ 116.00
6	FRONT BUMPER BRACKET X	2	\$ 52.00	\$ 104.00
7	FRONT BUMPER SPONGE X	1	\$ 215.00	\$ 215.00
8	FRONT BUMPER REINFORCEMENT X	1	\$ 412.00	\$ 412.00
9	FRONT BUMPER FOGLAMP X	2	\$ 312.00	\$ 624.00
10	FRONT BUMPER TOWING COVER X	2	\$ 42.00	\$ 84.00
11	FRONT BUMPER LOWER GRILLE CENTRE X	1	\$ 259.00	\$ 259.00
12	FRONT BUMPER UNDER COVER X	1	\$ 214.00	\$ 214.00
13	FRONT GRILLE X	1	\$ 498.00	\$ 498.00
14	FRONT SUPPORT PANEL X	1	\$ 898.00	\$ 898.00
15	FRONT SUPPORT PANEL TOP GARNISH X	1	\$ 184.00	\$ 184.00
16	HEADLAMP X	2	\$ 2,591.00	\$ 5,182.00
17	HEADLAMP LOWER BRACKET X	2	\$ 42.00	\$ 84.00
20	TAILGATE / Bnc	1	\$ 1,359.00	\$ 1,359.00
21	TAILGATE WEATHERSTRIP / Tui	1	\$ 212.00	\$ 212.00
22	TAILGATE OUTER GARNISH / BT	1	\$ 521.00	\$ 521.00
23	TAILGATE LOGO /	1	\$ 95.50	\$ 95.50
24	TAILGATE EMBLEM PRIUS t /	1	\$ 89.40	\$ 89.40
25	TAILGATE EMBLEM HYBRID /	1	\$ 82.30	\$ 82.30
26	TAILGATE NUMBER PLATE LAMP ?	2	\$ 587.00	\$ 1,174.00
27	TAILGATE DETECTOR ?	1	\$ 321.00	\$ 321.00
28	TAILGATE LOCK / BT	1	\$ 312.00	\$ 312.00
29	TAILGATE WINDSCREEN MOULDING / ncl	1	\$ 198.00	\$ 198.00
30	TAILGATE LOWER GLASS / sm	1	\$ 689.00	\$ 689.00
31	TAILGATE LOWER GLASS MOULDING / ncl	1	\$ 159.00	\$ 159.00
32	TAILGATE LOWER GLASS TRIM / CTA	1	\$ 312.00	\$ 312.00
33	TAILGATE INNER TRIM BOARD / BT	1	\$ 459.00	\$ 459.00
34	TAILGATE INNER HANDLE X NV	1	\$ 38.00	\$ 38.00
35	REAR BUMPER / re	1	\$ 658.00	\$ 658.00
36	REAR BUMPER SIDE RETAINER / CTA	2	\$ 112.00	\$ 224.00
37	REAR BUMPER REINFORCEMENT	1	\$ 350.50	\$ 350.50
38	REAR BUMPER REINFORCEMENT BRACKET / BT	2	\$ 251.00	\$ 502.00
39	REAR BUMPER TOW COVER / M15	1	\$ 52.00	\$ 52.00
40	REAR BUMPER BRACKET ?	2	\$ 114.00	\$ 228.00
41	REAR BUMPER LIP / TN	1	\$ 728.90	\$ 728.90
42	REAR BUMPER LAMP TOP / CTA / CTA / PH X NN	2	\$ 512.00	\$ 1,024.00

43	REAR BUMPER REFLECTOR	2	\$ 68.00	\$ 136.00
44	REAR BUMPER UNDER COVER X	1	\$ 298.00	\$ 298.00
45	REAR FENDER LH X	1	\$ 898.00	\$ 898.00
46	REAR FENDER COWLING	12	\$ 198.20	\$ 396.40
47	REAR FENDER INNER TRIM	2	\$ 612.00	\$ 1,218.00
48	TAILAMP	2	\$ 698.00	\$ 1,396.00
49	TAILAMP LOWER BRACKET X	2	\$ 82.00	\$ 164.00
50	REAR END PANEL	1	\$ 687.00	\$ 687.00
51	REAR END PANEL TOP GARNISH	1	\$ 212.00	\$ 212.00
52	REAR FLOOR PANEL X	1	\$ 1,259.00	\$ 1,259.00
53	REAR FLOOR PANEL TOP BOARD	1	\$ 325.00	\$ 325.00
54	REAR FLOOR PANEL TOP SIDE TRAY	1	\$ 221.00	\$ 221.00
55	REAR FLOOR PANEL TOP SPONGE	1	\$ 411.00	\$ 411.00
56	REAR EXHAUST PIPE X	1	\$ 989.00	\$ 989.00
57	REAR EXHAUST PIPE HEAT SHIELD	1	\$ 312.00	\$ 312.00
				\$ 29,414.00
			Less 20%	\$ 5,882.80
			Total	\$ 23,531.20
	S/Nett items:			
1	FRONT NUMBER PLATE	1	\$ 50.00	\$ 50.00
2	FRONT BUMPER CLIPS SET X	1	\$ 50.00	\$ 50.00
3	FRONT FENDER COWLING CLIP SET X	1	\$ 50.00	\$ 50.00
4	FRONT SUPPORT TOP GARNISH CLIP SET X	1	\$ 30.00	\$ 30.00
5	REAR BUMPER CLIPS	1	\$ 80.00	\$ 80.00
6	REAR TAILGATE INNER TRIM BOARD CLIPS	1	\$ 80.00	\$ 80.00
7	REAR WINDSCREEN SEALANT	1	\$ 80.00	\$ 80.00
8	REAR WINDSCREEN INNER SEAL	1	\$ 80.00	\$ 80.00
9	REAR WINDSCREEN LOWER GLASS SEALANT	1	\$ 80.00	\$ 80.00
10	REAR FENDER INNER TRIM CLIPS SET	1	\$ 50.00	\$ 50.00
11	REAR NUMBER PLATE	1	\$ 50.00	\$ 50.00
12	REAR NUMBER PLATE GARNISH	1	\$ 50.00	\$ 50.00
13	REAR REVERSE SENSOR	1	\$ 250.00	\$ 250.00
14	REAR REVERSE CAMERA X	1	\$ 350.00	\$ 350.00
15	REAR END PANEL TOP GARNISH CLIPS	1	\$ 80.00	\$ 80.00
16	REAR END PANEL SEALANT	1	\$ 60.00	\$ 60.00
				\$ 1,470.00
	Labour to:FRONT AND REAR			
1	TO CHECK REAR ELECTRICAL WIRING	1	\$ 150.00	\$ 150.00
2	REMOVE AND REPAIR A/C AND RADIATOR	1	\$ 150.00	\$ 150.00
3	REALIGN HEADLAMP	1	\$ 50.00	\$ 50.00
4	RESET TROUBLE CODE	1	\$ 300.00	\$ 300.00
5	TO REMOVE AND RENEW REVERSE SENSOR	1	\$ 150.00	\$ 150.00
6	TO REMOVE AND REFIT REAR GLASS	1	\$ 150.00	\$ 150.00
7	TO REMOVE AND REFIT REAR LOWER GLASS	1	\$ 100.00	\$ 100.00
8	REMOVE AND RENEW REAR GARNISH / UPHOLSTERY	1	\$ 200.00	\$ 200.00
9	REMOVE AND RENEW TAILGATE MECHANISM	1	\$ 80.00	\$ 80.00
10	REMOVE AND RENEW REAR EXHAUST SILENCER	1	\$ 150.00	\$ 150.00
11	TO RESPRAY UNDERCOATING	1	\$ 150.00	\$ 150.00
12	APPLY ANTI RUST ON AFFECTED AREAS	1	\$ 200.00	\$ 200.00
13	SPRAY PAINTING ON AFFECTED AREAS	1	\$ 2,000.00	\$ 2,000.00

40

30

30

20

20

30

20

200

20

40

30

X

X

X

40

100

50

60

60

X

60

1400

14	PANEL BEATING ON AFFECTED AREAS	1	\$ 2,000.00	\$ 2,000.00
				\$ 5,830.00
			Parts Replacement Amount	\$ 25,001.20
			Total Amount for Labour	\$ 5,830.00
			Total Amount	\$ 30,831.20

1200

9 Days

4/5

After repair photos

Car A/F

23/8/22

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modifications is allowed
- Supplementary survey is to be resurveyed and is subject to the repairer's insurance company

Acknowledged:
Signature:
Date: