

Plate Number	Case Number	Brand	Model Details	Body Type	Insurance company	Export CSV
SJE7377Y	-	Toyota	Rush	SUV	III	
Technician	SA	Parts Manager				
-	LKK_cs-a	-				

Parts

#	Description	OE Number	Part Type	Unit Price	Cost	Mark up/Disc	Qty	Sum
01	REAR DOOR RH <div>Customized</div>			\$0.00	\$1112.00	-25 %	1	\$834.00
02	REAR BUMPER <div>Customized</div>			\$0.00	\$650.20	-25 %	1	\$487.65
03	REAR BUMPER RETAINER <div>Customized</div>			\$0.00	\$50.00	-25 %	1	\$37.50
								Total :\$1359.15

Materials

#	Description	OE Number	Part Type	Unit Price	Cost	Mark up/Disc	Qty	Sum
01	REAR BUMPER CLIPS <div>Customized</div>			\$0.00	\$20.00	0 %	1.0	\$20.00
02	REAR WHEEL RIM <div>Customized</div>			\$0.00	\$500.00	0 %	1.0	\$500.00
03	BUILD UP SPOILER BODYKIT <div>Customized</div>			\$0.00	\$500.00	0 %	1.0	\$500.00
								Total :\$1020.00

Labors

Replace / RnR

#	Description	Labor Code	Type	Labor Hour	Unit Price	Mark up/Disc	Sum
01	PANEL BEATING REMOVAL AND REPLACING PARTS <div>Customized</div>		RnR	0.00	\$400.00	0 %	\$400.00
02	TO SPRAY PAINT AFFECTED AREA <div>Customized</div>		RnR	0.00	\$600.00	0 %	\$600.00
03	TUFF COAT <div>Customized</div>		RnR	0.00	\$30.00	0 %	\$30.00
04	WIRING CHECK <div>Customized</div>		RnR	0.00	\$30.00	0 %	\$30.00
05	TRANSFER REAR DOOR MECHANISM <div>Customized</div>		RnR	0.00	\$60.00	0 %	\$60.00
06	REMOVE AND REFIX REAR SENSOR SETTING <div>Customized</div>		RnR	0.00	\$50.00	0 %	\$50.00
07	FOUR WHEEL ALIGNMENT <div>Customized</div>		RnR	0.00	\$80.00	0 %	\$80.00
Total :\$1250.00							

Remarks 2 remarks

2023-04-19 11:27 Assessor Supervisor-Insurlogic 5 45248664708  
FINAL REVIEW BASE ON INFORMATION PROVIDED BY LKK:  
CONCLUDED THE COST OF REPAIR AT \$2,900.00 WITH 4 WORKING DAYS

2023-04-19 11:26 Assessor Supervisor-Insurlogic 5 45248664708

FINAL REVIEW BASE ON INFORMATION PROVIDED BY LKK:  
CONCLUDED THE COST OF REPAIR AT \$2,900.00 WITH 1 WORKING DAYS

---