

LEUNG SUM / L.E.H. (P)

India/Chiang

REPAIR DETAILS**Reference****Part Source:** MRM-SG Version: 1.0 (Last Synchronised: 23 Aug 2022)**Parts:** 143 MERCEDES-BENZ E220 BLUETEC 2.1 D (A) (Catalogue:Merimen Singapore 1.0)**Labour:** Repairer's (Price-denominated Standard List)**Print Code:** ComfortDelGro Engineering Pte Ltd/SH6515A/23/08/2022 08:26**Validity:** These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page**Further Info:** Items/values not in reference catalogue are prefixed with an asterisk *.**Estimates on Parts**

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*FRONT BUMPER ASSY	20.00	0.00	Ry *1,890.50 FL
2	1		*FRONT BUMPER BRACKET LH	20.00	0.00	X *95.00 FL
3	1		*FRONT BUMPER GRILLE LH	20.00	0.00	X *240.50 FL
4	1		*FRONT FENDER SPLASHSHIELD LH	20.00	0.00	? *257.00 FL
5	1		*FRONT WHHEL RIM LH	20.00	0.00	out *1,250.00 FL
Sub Total (\$\$)						3,733.00
- List Item Discount on L Items (\$\$)						746.60
Total Parts (\$\$)						2,986.40

F=Franchise part. L=ListItemDisc.

ComfortDelGro Engineering Pte Ltd/SH6515A/23/08/2022 08:26. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

Estimates on Miscellaneous Items

No	Qty	Particulars	Amount
Miscellaneous Items			
1	1	OD/TP Case (Insurer)	11.00
Sub Total (S\$) ✓			11.00

Estimates on Labour

No	Particulars	Lab.Type	Amount
Labour Items			
1	PANEL BEATING	New	400 500.00
2	SPRAY PAINTING	New	250 300.00
3	RESET WHEEL ALIGNMENT	New	80 90.00
Gross Labour Cost (S\$)			890.00

ComfortDelGro Engineering Pte Ltd/SH6515A/23/08/2022 08:26. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

Tan Kah 97495449
 inv 23/8/22 @ 430
 4/5 Runny after repair
 Tan Kah @ Wharfedale
 2 days

Date/Time: 22.08.2022 16:12

Page : 1

am: ARC Repair TP(CLS0)1

JOB CARD Sales Order: 4631063

JC NO: 805527387

STOMER

V/MS COMFORT TRANSPORTATION PTE LTD
STOMER NO. 7010045
DRESS 383 SIN MING DRIVE
Singapore SINGAPORE 575717
65508755 (R) (P) (O)

3COUNT CARD NO.

REGN NO.:

SH 6515A

MILEAGE

MAKE:

MERCEDES BENZ

FUEL

E.....1/2.....F

MODEL

E220CDI (E6)

22.08.2022 13:40

DATE/TIME IN

VR OF MANU.

12.05.2015

TARGET DATE

CHASSIS CODE

WDD2120012B170279

COMPLETION DATE/TIME:

ccident Date: 22.08.2022
ATURE: 3P 22.08.2022

JOB DESCRIPTION


/NO

LABOR CODE

DESCRIPTION

84166

8



ECKED & PASSED OUT BY:

SERVICE ADVISOR

CUSTOMER'S SIGNATURE

nowledgement Slip

Exit Pass

;

;

e No.: SH 6515A

CHIANG

Vehicle No.:

SH 6515A

of Service Advisor

Signature/Date

Name of Service Advisor

Date

returned to Service Reception upon collection

To be kept by Security Guard