

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATE : ACCIDENT REPAIRS
WORKSHOP : UBI ROAD 1
CONTACT NO : 6366 2323
FAX NO : 6841 1183
REFERENCE : PA/OD/0736/2022/EQ
DATE : 25-Aug-22
WIP : 39028

VEHICLE IN WORKSHOP. KINDLY ARRANGE FOR SURVEY ON 26/8/2022.

AIG ASIA PACIFIC INSURANCE PTE LTD

78 SHENTON WAY

#07-16 AIG BUILDING

SINGAPORE 079120

Attn: Motor Claims Dept

Tel: 6880 4602 - Fax: 6880 4838

OWNER'S NAME : PREMIUM AUTOMOBILES PTE LTD
ADDRESS : 55 UBI ROAD 1
SINGAPORE 408699
TELEPHONE : HP +65 66900293
TYPE OF CLAIM : OWN DAMAGE CLAIM
POLICY NO : 0999993555-01/120004546
VEHICLE NO : **SND 490 G**
MODEL CODE : AUDI Q3 1.4 TFSI S-TRONIC
MODEL YEAR : 30/11/2021
ENGINE NO : CZD C47295
CHASSIS NO : WAUZZZF33M1150250
MILEAGE : -
DATE IN : -
ESTIMATED BY : JOHNNY BOO / ALLAN WU
ACCIDENT DATE : 24-Aug-22
PLACE OF ACCIDENT : ENG NEO AVE

PREMIUM AUTOMOBILES



5 UBI ROAD 1, SINGAPORE 408699
TEL : 6366 2323 FAX : 6841 1183
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SND 490 G

S/N	NATURE OF JOBS	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE, CHECK AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR, HEADLIGHT WASHER ASSY AND FRONT PARKING AID.	S/N \$ 480.00 ✓	
2	TO REMOVE AND TRANSFER LHS HEADLIGHT'S CONTROL UNIT AND POWER MODULE.	S/N \$ 400.00 ✓	
3	TO REMOVE AND REINSTALL AIRCON CONDENSER, CHARGE AIR COOLER AND RADIATOR. CHECK ELECTRICAL FANS AND CONTROL UNIT. PRESSURISE COOLING SYSTEM.	S/N \$ 1,600.00 ?	
4	TO CARRY OUT VACUUM AND REGAS FOR R1234.	S/N \$ 1,200.00 ?	
5	TO REMOVE AND TRANSFER LHS FRONT DOOR 'S MULTI-LOCK SYSTEM AND POWER WINDOW DEVICES. INSPECT FOR DAMAGES.	S/N \$ 400.00 ✓	
6	TO REMOVE AND REINSTALL FRONT SEAT ASSY, BACK REST, AB PILLAR TRIMS, SILL TRIMS, CARPETS, ELECTRONIC COMPONENTS AND FUSE TRAYS.	S/N \$ 1,800.00 ✓	
SUB-TOTAL LABOUR CHARGES		: \$ 5,880.00	

PREMIUM AUTOMOBILES



35 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SND 490 G

S/N	NATURE OF JOBS	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
7	TO REMOVE CENTER CONSOLE AND DASHBOARD ASSY FOR A-PILLAR RENEWAL. INSPECT FOR DAMAGES.	S/N \$ 3,200.00	?
8	TO REMOVE AND RENEW LHS FRONT WHEEL SUSPENSION ASSY WITH SUBFRAME.	S/N \$ 2,400.00	?
9	TO CARRY OUT FIRST MEASUREMENT ON CAR-O-LINER.	S/N \$ 800.00	?
10	TO SETUP VEHICLE ON CAR-O-LINER TO FACILITATE THE REPAIR.	S/N \$ 2,400.00	?
11	TO DISMANTLE AND RENEW FRONT BUMPER, LHS FRONT FENDER, LHS FRONT DOOR AND LHS HEADLIGHT. TO REPAIR BONNET AND LHS FRONT FENDER TOP SUPPORT. TO CUT OUT AND WELD LHS A-PILLAR AND LHS SILL PANEL. TO RENEW FRONT LOCK CARRIER AND ALIGN TO POSITION. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.	\$ 9,600.00	3750
12	TO RESPRAY FRONT BUMPER, LHS FRONT FENDER, BONNET, LHS FRONT FENDER TOP SUPPORT, LHS FRONT DOOR, HINGES, LHS WING MIRROR COVER, LHS A-PILLAR, LHS SILL PANEL AND DOOR ENTRANCE.	\$ 7,000.00	3875
SUB-TOTAL LABOUR CHARGES		: \$ 25,400.00	

PREMIUM AUTOMOBILES



,5 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SND 490 G

S/N	NATURE OF JOBS	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
13	TO RENEW LHS FRONT RIM WITH TYRE AND LHS REAR TYRE. TO CARRY OUT PRE/POST WHEEL ALIGNMENT.	S/N \$ 560.00 ✓	
14	TO TOW BACK THE VEHICLE FROM ACCIDENT SCENE.	S/N \$ 280.00 X	
15	TO CARRY OUT PRE/POST DIAGNOSTIC CHECK.	S/N \$ 384.00 ✓	
TOTAL LABOUR CHARGES		: \$ 32,504.00	

PREMIUM AUTOMOBILES



5 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SND 490 G

S/N	PARTS DESCRIPTION	QTY	DAMAGED PARTS & PRICES		REMARKS
			S/NETT		
1	FRONT BUMPER <i>form</i>	1	\$	1,301.00	
2	FRONT BUMPER GRILLE - CENTER <i>?</i>	1	\$	242.00	
3	FRONT BUMPER GRILLE - LH <i>sa</i>	1	\$	124.00	
4	FRONT BUMPER CLOSING ELEMENT <i>?</i>	1	\$	212.00	
5	FRONT BUMPER SPOILER <i>sa</i>	1	\$	426.00	
6	FRONT BUMPER BRACKET <i>cm</i>	1	\$	24.00	
7	RADIATOR AIR GUIDE GRILLE - LH <i>MIS</i>	1	\$	171.00	
8	RADIATOR GRILLE <i>sa</i>	1	\$	1,594.00	
9	RADIATOR GRILLE STRIKER PLATE <i>?</i>	1	\$	271.00	
10	FRONT BUMPER GUIDE SECTION - LH <i>MIS</i>	1	\$	43.00	
11	FRONT BUMPER FOAM FILLER PIECE <i>?</i>	1	\$	114.00	
12	FRONT BUMPER CARRIER <i>?</i>	1	\$	974.00	
13	FRONT BUMPER TOP COVER <i>?</i>	1	\$	137.00	
14	CAUTION SIGN STICKER <i>?</i>	1	\$	16.00	
15	AIR CONDITIONER STICKER <i>?</i>	1	\$	9.00	
16	HORN SIGNAL HIGH TONE - LH <i>X</i>	1	\$	154.00	
17	HORN SIGNAL BRACKET <i>X</i>	1	\$	25.00	
18	FRONT PARKING AID SENSOR <i>?</i>	1 <i>X</i>	\$	531.00	
19	FRONT PARKING AID SEAL RING <i>sa</i>	4	\$	10.00	
20	FRONT BUMPER WIRING SET <i>?</i>	1	\$	750.00	
SUB TOTAL SPARE PARTS		:	\$	7,128.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
SPARE PARTS ARE SPECIAL NETT.

PREMIUM AUTOMOBILES



5 UBI ROAD 1, SINGAPORE 408699

TEL: 6366 2323 FAX: 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SND 490 G

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
21	FRONT FENDER - LH <i>bme</i> ✓	1	\$ 1,445.00	
22	FRONT FENDER ATTACHMENT PARTS <i>nee</i> ✓	1	\$ 66.00	
23	FRONT FENDER BRACE - LH <i>bt</i> ✓	1	\$ 98.00	
24	FRONT FENDER BRACKET - LH <i>bt</i> ✓	1	\$ 39.00	
25	FRONT FENDER CLOSING ELEMENT - LH <i>ca</i> ✓	1	\$ 37.00	
26	FRONT FENDER SEAL - LH <i>ne</i> ✓	1	\$ 40.00	
27	FRONT WHEEL HOUSING LINER - LH <i>Torn</i> ✓	1	\$ 260.00	
28	FRONT WHEEL HOUSING LINER ATTACHMENT PARTS <i>ne</i> ✓	1	\$ 105.00	
29	FRONT FENDER COVER - LH <i>X</i>	1	\$ 18.00	
30	HEADLIGHT MOUNTING - LH <i>ca</i> ✓	1	\$ 132.00	
31	HEADLIGHT - LH <i>bo</i> ✓	1	\$ 5,952.00	
32	HEADLIGHT POWER MODULE <i>ca</i> ✓	1	\$ 850.00	
33	HEADLIGHT HEAT SINK <i>?</i>	1	\$ 870.00	
34	HEADLIGHT HOSE - LH <i>?</i>	1	\$ 28.00	
35	HEADLIGHT COMPENSATING PIECE <i>ne</i> ✓	1	\$ 45.00	
36	LIFT CYLINDER - LH <i>ca</i> ✓	1	\$ 231.00	
37	LIFT CYLINDER HOSE <i>?</i>	1	\$ 92.00	
38	HEADLIGHT WASHER PUMP <i>but X</i>	1	\$ 172.00	
39	LIFT CYLINDER WASH WATER RESERVOIR <i>de</i> ✓	1	\$ 240.00	
40	WINDSCREEN WASHER PUMP <i>X</i>	1	\$ 138.00	
SUB TOTAL SPARE PARTS		:	\$ 10,858.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
SPARE PARTS ARE SPECIAL NETT.

PREMIUM AUTOMOBILES



55 UBI ROAD 1, SINGAPORE 408699
TEL: 6366 2323 FAX: 6841 1183
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SND 490 G

S/N	PARTS DESCRIPTION	QTY	DAMAGED PARTS & PRICES		REMARKS
			S/NETT		
41	FRONT FENDER FLEDGE COVER - LH ?	1	\$	46.00	
42	LOCK CARRIER ?	1	\$	1,412.00	
43	READY-MIX COOLANT ?	6	\$	297.00	
44	RADIATOR AIR GUIDE - LH ?	1	\$	43.00	
45	RADIATOR AIR GUIDE - UPPER / LOWER ?	2	\$	96.00	
46	OUTSIDE TEMPERATURE SENSOR BRACKET ?	1	\$	9.00	
47	A/B PILLAR FRAME - LH <i>bt</i>	1	\$	3,629.00	
48	FRONT BODY SIDE SILL TRIM STRIP - LH <i>rec</i>	1	\$	99.00	
49	FRONT SIDE MEMBER TRIM - LH <i>de</i>	1	\$	189.00	
50	FRONT DOOR - LH <i>bt</i>	1	\$	3,017.00	
51	FRONT OUTER DOOR SEAL - LH <i>re</i>	1	\$	185.00	
52	FRONT DOOR CATCH - LH ?	1	\$	134.00	
53	FRONT DOOR COVER - LH <i>re</i>	1	\$	283.00	
54	FRONT WING MIRROR MOUNTING - LH <i>scr</i>	1	\$	2,278.00	
55	FRONT WING MIRROR CAP - LH <i>requir</i>	1	\$	203.00	
56	FRONT WING MIRROR GLASS - LH X	1	\$	940.00	
57	FRONT DOOR CORNER TRIM - LH X	1	\$	51.00	
58	FRONT WINDOW GUIDE TRIM STRIP - LH X	1	\$	287.00	
59	FRONT WINDOW OUTER SLOT SEAL TRIM STRIP - LH <i>scr</i>	1	\$	251.00	
60	FRONT WINDOW PILLAR B TRIM - LH X	1	\$	131.00	
SUB TOTAL SPARE PARTS			:	\$ 13,580.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST
LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
SPARE PARTS ARE SPECIAL NETT.

PREMIUM AUTOMOBILES



55 UBI ROAD 1, SINGAPORE 408699

TEL: 6366 2323 FAX: 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SND 490 G

S/N	PARTS DESCRIPTION	QTY	DAMAGED PARTS & PRICES	
			S/NETT	REMARKS
61	FRONT WINDOW GUIDE - LH <i>X</i>	1	\$ 481.00	
62	FRONT DOOR WINDOW - LH <i>X</i>	1	\$ 269.00	
63	FRONT UPPER HINGE HALVES - LH <i>?</i>	2	\$ 106.00	
64	FRONT LOWER HINGE HALVES - LH <i>?</i>	2	\$ 106.00	
65	FRONT WATER DEFLECTOR STRIP - LH <i>at-</i>	1	\$ 52.00	
66	FRONT UNDERBODY TRIM - LH <i>cm-</i>	1	\$ 216.00	
67	FRONT WHEEL ARCH COVER - LH / RH <i>ne-</i>	2	\$ 566.00	
68	FRONT ALUMINIUM RIM - LH <i>at-</i>	1	\$ 1,414.00	
69	RUBBER VALVE <i>ne-</i>	4	\$ 15.00	
70	FRONT ASSEMBLY CARRIER <i>?</i>	1	\$ 753.00	
71	FRONT BONDED RUBBER BUSHES - UPPER / LOWER <i>?</i>	1	\$ 179.00	
72	FRONT OUTER SUPPORT BRACKET - LH <i>?</i>	1	\$ 25.00	
73	FRONT TRACK CONTROL ARM - LH <i>?</i>	1	\$ 512.00	
74	FRONT WHEEL BEARING HOUSING - LH <i>?</i>	1	\$ 753.00	
75	FRONT BEARING WHEELHUB - LH <i>?</i>	1	\$ 550.00	
76	FRONT SUSPENSION BALL JOINT - LH <i>?</i>	1	\$ 145.00	
77	FRONT POLES LEVEL SENSOR - LH <i>?</i>	1	\$ 652.00	
78	FRONT COUPLING ROD <i>?</i>	1	\$ 105.00	
79	FRONT COUPLING ROD STABILIZER <i>?</i>	1	\$ 457.00	
80	FRONT GAS SHOCK ABSORBER - LH <i>?</i>	1	\$ 338.00	
SUB TOTAL SPARE PARTS		:	\$ 7,694.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
SPARE PARTS ARE SPECIAL NETT.

PREMIUM AUTOMOBILES



55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SND 490 G

S/N	PARTS DESCRIPTION	DAMAGED PARTS & PRICES		
		QTY	S/NETT	REMARKS
81	FRONT DRIVE SHAFT - LH ?	1	\$ 1,521.00	
82	FRONT STEERING GEAR ?	1	\$ 5,990.00	
83	FRONT TRACK ROD - LH ?	1	\$ 99.00	
84	FRONT TIE ROD END - LH ?	1	\$ 126.00	
85	FRONT NOISE INSULATION ?	1	\$ 516.00	
86	FRONT NO PLATE ne/	S/N	\$ 60.00	
87	SUNDRIES ?		\$ 1,000.00	
88	LHS Front tyre - punctured ✓			
TOTAL SPARE PARTS		:	\$ 48,572.00	
TOTAL LABOUR CHARGES		:	\$ 32,504.00	
GRAND TOTAL		:	\$ 81,076.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
SPARE PARTS ARE SPECIAL NETT.

PREMIUM AUTOMOBILES



55 UBI ROAD 1, SINGAPORE 408699

TEL: 6366 2323 FAX: 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

NAME

SURVEYED DATE

AUTHORISED DATE

EXCESS COST

LIABILITY

REMARKS

: Rasul - Hy 90010068
: 26/08/22 @ 1630
: 10 days
: EXCESS: TBA
: REPAIR
: Resy before paint

PLEASE NOTE

: THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF THE
AFFECTED VEHICLE. SHOULD WE REQUIRE FURTHER
LABOUR CHARGES AND SPARE PARTS IN THE PROGRESS OF
REPAIR, WE SHALL INFORM YOU ACCORDINGLY.
FOR INSPECTION OF VEHICLE, PLEASE REFER TO
MS. NORAH KHAI AT TEL: 6768 9828 / 6768 9911 FOR
APPOINTMENT.

YOURS FAITHFULLY,
PREMIUM AUTOMOBILES PTE LTD

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

JOHNNY BOO
BODY REPAIR MANAGER

ALLAN WU
CLAIMS CONSULTANT