

Workshop Accident Repair Estimate
FOR WORKSHOP ONLY

ACCIDENT DATE 23.08.2022 BUS REGISTRATION NUMBER SBS5023C
ACCIDENT TIME 11:15AM BUS TYPE (DD OR SD) SD
THIRD PARTY CLAIM AGAINST Accident Reference & Bus No AR-2022-2004

S/No	SECTION A :	PARTS & MATERIAL COST	
	Part or Item Description	Quantity	Total Cost
1	BUMPER REAR F/G C&D SERIES <i>cm</i>	1	\$ 248.00
2	LED TAIL/STOP LAMP <i>cm</i>	1	\$ 95.00
3	LED INDICATOR LAMP <i>cm</i>	1	\$ 100.00
4	LED REVERSE LAMP <i>cm</i>	1	\$ 103.00
5			
6			
7			
8			
9			
10			
11			
12			
13			
14			
15			
		TOTAL PARTS & MATERIAL COST	\$ 546.00

S/No	SECTION B:		ASSESSMENT/REPAIR/SPRAY PAINT (LABOUR COST)	
1	contractor's repair charges -Soon Bee		Quotation	\$480
2	Workshop Labour			\$188.00
3	Spray Painting & Sikaflex x 255			\$40
4	Vinyl		NA	
5	Touch up sticker		Sticker & AVD	
6	Towing		CRS Towing	
			TOTAL LABOUR COST	\$708

SECTION C :	SUMMARY
	TOTAL DOWNTIME-1 dar
	TOTAL REPAIR COSTS \$1,254

Name of Surveyor: Rasul - Hp 90010068

Company Name: LKK

DATE Surveyor : 29/08/22 @ 1045

Resurvey after repair
1 day
email: rasul@lkkauto.com

- LKK Auto Consultants hence notify the Repairer of the following:
- To resurvey before/after spray painting
 - To display damaged part(s) during resurvey
 - Parts prices are subject to confirmation
 - Third party survey is on a "Without Prejudice" basis
 - No illegal modification(s) is allowed
 - Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: