



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

DAMAGE ASSESSMENT REPORT

INCOME INSURANCE LTD

Ref: CS/INC22008328/Uvy3m4

73 BRAS BASAH ROAD
#05-01 NTUC TRADE UNION HOUSESINGAPORE
189556

Date: 14/09/2022

ATTN: FIONA SHEN

Code: INC

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SMT 9469M	Veh. Inspected	SMA 8650L
Policy No.		Coverage (\$)	0.00
Claim No.	MT/1183496-002	Excess (\$)	0.00
Assign From	ANNIE KOH	Assign Date	29/08/2022

2. Vehicle Particulars & Condition

Make & Model	HONDA FREED HYBRID (A)	c.c	1496
Engine No.	HIDDEN	Year of Reg.	2018
Chassis No.	GB71065234	Colour	WHITE
Odometer	122313 KM	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	185/65 R15	TOYO	6 mm
L/H Front Tyre	185/65 R15	TOYO	6 mm
R/H Rear Tyre	185/65 R15	TOYO	6 mm
L/H Rear Tyre	185/65 R15	TOYO	6 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.

DAMAGES SEE DETAILS.

5. General Information

Accident Date	07/08/2022	Inspect Date / Time	29/08/2022 (10:37 AM)
Survey held at	PROGRESSIVE CAR CARE PTE LTD BLK 3022A UBI ROAD 1 #01-45/46, SINGAPORE 048716		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.
B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	7 Working Days
-------------------------------------	----------------