



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
NGS MOTORSPORT PTE LTD BLK 10 ANG MO KIO INDUSTRIAL PARK 2A #02-01 AMK AUTOPOINT SINGAPORE 568047 ON BEHALF OF ONG AUTOMOTIVE			Ref: CS/TP22008329/Knce2 Date: 01/09/2022 Code: TP549	
<b>1. Policy Particulars :- THIRD PARTY CLAIM</b>				
	Insured Veh.	Veh. Inspected	SLA 8607A	
	Policy No.	Coverage (\$)	0.00	
	Claim No.	Excess (\$)	0.00	
	Assign From	Assign Date	03/08/2022	
<b>2. Vehicle Particulars &amp; Condition</b>				
	Make & Model	HYUNDAI ELANTRA (A)	c.c	1591
	Engine No.	HIDDEN	Year of Reg.	2016
	Chassis No.	KMHD841CMHU099778	Colour	METALLIC GREY
	Odometer	264937 KM	Steering	IN ORDER
	Brakes	IN ORDER	Modification	STANDARD ALLOY RIM
	General	GOOD		
<b>3. Conditions of Tyres</b>				
		Size	Make	Balance
	R/H Front Tyre	205/55 R16	ARIVO	8 mm
	L/H Front Tyre	205/55 R16	ARIVO	8 mm
	R/H Rear Tyre	205/55 R16	WEST LAKE	7 mm
	L/H Rear Tyre	205/55 R16	WEST LAKE	7 mm
<b>4. Description of Damages</b>				
	THE VEHICLE SUSTAINED DAMAGES AT THE REAR AND FRONT PORTION. DAMAGES SEE DETAILS.			
<b>5. General Information</b>				
	Accident Date	03/07/2022	Inspection Date	03/08/2022
	Survey held at	NGS AUTOMOTIVE 10 ANG MO KIO INDUSTRIAL PARK 2A #02-01 AMK AUTOPOINT SINGAPORE 568047		
<b>5a. Remarks</b>				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
<b>5b. Estimate Days of Repair</b>				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		21 Working Days	