



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
AXA INSURANCE PTE LTD 8 SHENTON WAY #24-01 AXA TOWERS SINGAPORE 068811			Ref: CS3/ASM22006296/Envy3 Date: 01/07/2022 29/08/2022 Code: ASM	CS3/ASM22006296/Envy3-1
1. Policy Particulars :- (THIRD PARTY CLAIM)				
Insured Veh.	XD 9087K	Veh. Inspected	GBE 5150S	
Policy No.		Coverage (\$)	0.00	
Claim No.	S2M045OI	Excess (\$)	0.00	
Assign From	HO WINNIE	Assign Date	01/07/2022 29/08/2022	
2. Vehicle Particulars & Condition				
Make & Model		c.c	0	
Engine No.	HIDDEN	Year of Reg.		
Chassis No.		Colour		
Odometer	-	Steering		
Brakes		Modification		
General				
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre			mm	
L/H Front Tyre			mm	
R/H Rear Tyre			mm	
L/H Rear Tyre			mm	
4. Description of Damages				
5. General Information				
Accident Date	29/06/2022	Inspection Date	01/07/2022	
Survey held at	7 SOON LEE STREET #01-39 ISPACE SINGAPORE 627608			
Repairer	LYS ENGINEERING			
5a. Remarks				
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.				