

ASS. FEO. BY:

REP:

CS/GA122008365/Acy3.

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured _____

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 12 days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: _____ Person Contacted: _____

Veh No: JSN7513 Yr Regn: 2018, Jan.

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Proton Exora c.c. 1561

Colour: Red. A/C: Insured / Std / NI / NA

Sp. Reading: 154853 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: PL1FZ6YDRJF168791

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 205/55R16

R: 205/55R16

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or Falken

Front _____ Rear _____

R/Bal. 06 mm R/Bal. 06 mm

L/Bal. 06 mm L/Bal. 06 mm

D.O.A. _____ D.O.I. 30/08/22

Survey held at HD Perfect

Des. of Damages: Front / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	TP Great American.
10/11	Adrian finalised LS \$11,500; 12 days with Repairer. (Red. 20,021.48, 63%)
	MV: 42K (RM).
	PV: 3K (RM)
	Nett: 39K (RM) $\approx$ 13K.

Date/Time, File Pass to?

☐

: Preli. Report

1)

☒

: Final Report

Date/Time, File Return to?

2)

Days Of Repair: 12

Resurvey No. of Trip: _____

Survey Fee:

Transportation

3 + RS SI

Photos

Others

Add Fee: ☐ : Site Insp (\$

☐ : Interview (\$

☐ : Tech. Insp (\$

Report Format: _____



SIJIL PEMILIKAN KENDERAAN

JABATAN PENGANGKUTAN JALAN

KRSWCALE

No Pendaftaran : JSN7513
No ID : 790624085671
Nama Pemunya Berdaftar : TANG KONG WENG
Alamat : #07-14, JALAN PERSIARAN BAYU PUSAT 2, TAMAN BAYU
PUTERI,
80150 JOHOR BAHRU JOHOR
No. Chasis/Enjin : PL1FZ6YDRJF168791 / S4PHVL8878
Buatan>Nama Model : PROTON / EXORA FL 1.6L CVT
Keupayaan Enjin : 1561
Bahan Bakar : PETROL
Status Asal : PEMASANGAN TEMPATAN
Kejas Kegunaan : PERSENDIRIAN-MOTOKAR INDIVIDU
Jenis Badan/Tahun Dibuat : MOTOKAR PELBAGAI UTILITI / 2018
Tarikh Pendaftaran : 18/01/2018
B. D. M/B. G. K/BTM : -
Syarat Pendaftaran 1 : -
Syarat Pendaftaran 2 : -
Syarat Pendaftaran 3 : -



LESEN KENDERAAN MOTOR

AKTA PENGANGKUTAN JALAN 1987 (KEDAH KENDERAAN MOTOR (PENDAFTARAN DAN PELESEKAN) 1988)



LESEN KENDERAAN MOTOR
AKTA PENGANGKUTAN JALAN 1987 (KEDAH KENDERAAN MOTOR (PENDAFTARAN DAN PELESEKAN) 1988)

Sila baca maklumat di muka sebelah sebelum
melekatkan LKKA ini di cermin kenderaan anda.

2019
17 JAN
JSN7513
0101011 / JmsrJcE 18012018
16012018 17012019
1561SP AB RM99.00
PERSENDIRIAN
53285958

53285958



Zurich General Insurance Malaysia Berhad

Registration No. 201701035345 (1249516-V)
 Level 23A, Mercu 3, No. 3, Jalan Bangsar, KL Eco City, 59200 Kuala Lumpur, Malaysia
 Tel: 03-2109 6000 Fax: 03-2109 6888 Call Center: 1-300-888-622

CONFIRMATION OF PURCHASE OF INSURANCE

E-C/Note No : D17140-22000005
 Issue Date & Time : 10 JAN 2022 08:35:14am
 Period of Cover : From 18 JAN 2022 To 17 JAN 2023
 Vehicle Registration No. : JSN7513
 Make of Vehicle : PROTON EXORA EXECUTIVE FACELIFT CONTINUOUS VARIABLE
 Engine No. : S4PHVL8878 Chassis No. : PL1FZ6YDRJF168791
 Capacity : 1561 CC Year of Make : 2018
 Insured Name : TANG KONG WENG
 Address : A-5-7 PERSIARAN LAGUN SUNWAY, PANGSAPURI DESA ALPINE BANDAR
 SUNWAY, 31150, ULU KINTA, PERAK DARUL RIDZUAN
 790624-08-5671

NRIC/Business Reg No. :
 Type of Cover : V-CO MOTOR COMPREHENSIVE
 Product : PRIVATE CAR - Z-DRIVER
 HP Owner : MALAYAN BANKING BERHAD
 Sum Insured (RM) : 41,000 Endt No : 87 (Agreed Value)
 Transaction Type : Renewal
 Claims Excess : RM 0.00
 Voluntary Excess : RM 0.00

Sum Insured	(RM)	41,000	Premium	(RM)	1,210.95
NCD %		45.00 %	NCD Amt	(RM)	544.93
			Voluntary Excess	(RM)	(0.00)
			Basic Net	(RM)	666.02
			Extra Coverage	(RM)	201.25
SST		6.00 %	SST	(RM)	52.04
			Stamp Duty	(RM)	10.00
Act Premium	(RM)	261.06	Payable Premium	(RM)	929.31

Extra Benefits	Extra Sum Ins (RM)	Extra Premium (RM)
LEGAL LIABILITY TO PASSENGERS	0	53.75
LEGAL LIABILITY OF PASSENGERS FOR NEGLIGENT ACTS	0	7.50
BREAKAGE OF GLASS IN WINDSCREEN, WINDOW OR SUNROOF -	800	120.00
ZDRIVER	0	20.00
AUTHORISED DRIVER		

Named Drivers
 ALL DRIVERS

Agent : D17140-000 SHEENA CHEN POH CHEAN
 Tel No : 017-7939903

THIS IS A COMPUTER GENERATED FORM. SIGNATURE IS NOT REQUIRED

CERTIFICATE OF INSURANCE

ROAD TRANSPORT ACT, 1987 (MALAYSIA)
THE MOTOR VEHICLES (THIRD PARTY RISKS, RULES 1959 (MALAYSIA)
THE MOTOR VEHICLES (THIRD PARTY RISKS AND COMPENSATION) ACT
(CAP 189) (REPUBLIC OF SINGAPORE)
THE MOTOR VEHICLES (THIRD PARTY RISKS AND COMPENSATION) RULES 1959 (REPUBLIC OF
SINGAPORE)
THE MOTOR VEHICLES INSURANCE (THIRD PARTY RISKS) ACT (CAP 90) NEGARA BRUNEI DARUSSALAM

SIJIL INSURANS

AKTA PENGANGKUTAN JALAN RAYA, 1987 (MALAYSIA)
PERATURAN KENDERAAN MOTOR (RISIKO PIHAK KETIGA) 1959 (MALAYSIA)
AKTA KENDERAAN MOTOR (RISIKO DAN PAMPASAN PIHAK KETIGA) (CAP 189) (REPUBLIC SINGAPURA)
PERATURAN KENDERAAN MOTOR (RISIKO DAN PAMPASAN PIHAK KETIGA) 1959 (REPUBLIC
SINGAPURA)
AKTA INSURANS KENDERAAN MOTOR (RISIKO PIHAK KETIGA) (CAP 90) NEGARA BRUNEI
DARUSSALAM

D17140-000

Certificate No. (No. Sijil) : 501900005167-02

1. Index Mark and Registration Number of Vehicle : **JSN7513** NCD : 45.00 %
(Tanda Indeks dan Nombor Pendaftaran Kenderaan) : **PROTON EXORA EXECUTIVE FACELIFT CONTINUOUS VARIABLE**
2. Name of Policyholder (Nama Pemegang Polisi) : **TANG KONG WENG**
3. Effective date of the Commencement of Insurance for the purposes of the Regulations, Ordinance of
Enactment : **18 JAN 2022**
4. Date of Expiry of the Insurance (Tarikh Insurans Tamat) : **17 JAN 2023**
5. Persons or Classes of Persons entitled to drive* (Orang atau Kelas Orang yang berhak memandu*) :

a) Policyholder b) Any other person who is driving on the Policyholder's order or with his permission.
Provided that the person driving is permitted in accordance with the licensing or other laws or regulations to
drive the Motor Vehicle or has been so permitted and is not disqualified by order of a Court of Law or by
reason of any enactment or regulation in that behalf from driving the Motor Vehicle.

Limitation on Usage

Use only for social, domestic and pleasure purposes and for the policyholder's business or profession. The
policy does not cover :- Use for hire or reward, racing, pace-making, reliability trial, speed- testing, or
the carriage of goods (other than samples) in connection with any trade or business or use for any purpose in
connection with Motor Trade.

* Limitations rendered inoperative by Section 95 of the Road Transport Act 1987 (Malaysia) or Section 8 of the Motor Vehicles (Third Party Risks and Compensation) Act (Cap 189) Republic of Singapore or Section 7
of the Motor Vehicles Insurance (Third Party Risks) Act (Cap 90) Negara Brunei Darussalam are not to be included under these heading.

* Had - had yang tidak lagi berkuatkuasa kerana Seksyen 95 Akta Pengangkutan Jalan Raya, 1987 (Malaysia) atau Seksyen 8 Akta Kenderaan Motor (Risiko Dan Pampasan Pihak Ketiga) (Cap 189)
Republik Singapura atau Seksyen 7 Akta Insurans Kenderaan Motor (Risiko Pihak Ketiga) (Cap 90) Negara Brunei Darussalam tidak boleh dimasukkan di bawah tajuk ini.


Insured in pursuance to cover Note No : D17140-22000005

Dikeluarkan mengikut Nota Lindungan No :

I / We hereby certify that the Policy to which the Certificate is issued in accordance
with the provisions of Part IV of the Road Transport Act, 1987 (Malaysia), Motor
Vehicles (Third Party Risks & Compensation) Act (Cap 189) Republic of Singapore
and the Motor Vehicles Insurance (Third Party Risks) Act (Cap 90) Negara Brunei
Darussalam.

Saya / Kami dengan ini mengesahkan bahawa Polisi yang berkaitan dengan Sijil
ini dikeluarkan selaras dengan peruntukan - peruntukan Bahagian IV Akta
Pengangkutan Jalan Raya, 1987 (Malaysia), Akta Kenderaan Motor (Risiko Dan
Pampasan Pihak Ketiga) (Cap 189) Republik Singapura dan Akta Insurans
Kenderaan Motor (Risiko Pihak Ketiga) (Cap 90) Negara Brunei Darussalam

For and on behalf of / Untuk dan bagi pihak
ZURICH GENERAL INSURANCE MALAYSIA BERHAD



Junior Cho
Chief Executive Officer

Search for cars by Brand, Model, or Keywords

Brand & Model Body Type Budget Year Transmission Mileage Color CARSOME Certified Store

Reset

DEALS

Proton & EXORA X

2021 Proton EXORA PREMIUM 1.6

5,149 km | Automatic | Kuala Lumpur

Reverse Came... Leather Se... ABS I

RM **59,900** RM 656/mo ⓘ

2015 Proton EXORA 1.6

85,813 km | Automatic | Melaka

Reverse Camera ABS Brake SRS Ai

RM **37,400** RM 410/mo ⓘ

2013 Proton EXORA BOLD CFE PREMIU...

161,500 km | Automatic | Kuala Lumpur

View 360 Reverse Camera Leather

RM **33,400** RM 366/mo ⓘ

RM 60

2013 Proton EXORA FL CVT 1.6

129,666 km | Automatic | Pulau Pinang

SRS Airbag ABS Brake Reverse Car

RM **32,300** RM 354/mo ⓘ

2013 Proton EXORA FL CVT 1.6

83,062 km | Automatic | Perak

Reverse Cam... Leather Se... SRS A

RM **33,900** RM 371/mo ⓘ

2013 Proton EXORA FL CVT 1.6

131,250 km | Automatic | Melaka

NEW ARRIVAL ABS Brake SRS Airb

RM **33,400** RM 366/mo ⓘ

Search for cars by Brand, Model, or Keywords

Brand & Model

Body Type

Budget

Year

Transmission

Mileage

Color

CARSOME Certified

Store

Reset

DEALS

Proton & EXORA X

2013 Proton
EXORA BOLD 1.6

147,104 km | Automatic | Johor

Leathe...

Touchscreen Au...

Revers

RM **32,400** RM 355/mo ⓘ2014 Proton
EXORA FL CVT 1.6

104,750 km | Automatic | Kuala Lumpur

SRS Airbag

ABS Brake

View 360

RM **30,900** RM 339/mo ⓘ2016 Proton
EXORA FL CVT 1.6

78,856 km | Automatic | Kuala Lumpur

View ...

Auto Cruise Co...

Reverse I

RM **41,400** RM 454/mo ⓘ2014 Proton
EXORA FL CVT 1.6

130,651 km | Automatic | Selangor

View 3...

Auto Cruise Con...

Leathe

RM **33,400** RM 366/mo ⓘ2019 Proton
EXORA EXECUTIVE 1.6

46,447 km | Automatic | Melaka

ABS Brake

SRS Airbag

Alarm Syste

RM **49,900** RM 547/mo ⓘ2015 Proton
EXORA FL CVT 1.6

33,934 km | Automatic | Johor

View 360

SRS Airbag

ABS Brake

RM **39,400** RM 432/mo ⓘ



SINGAPORE POLICE FORCE



F/20220827/7016

1 of 2

Report No. F/20220827/7016

POLICE REPORT (NP299)

Police Station Of Origin
Ang Mo Kio Division HQ
51 Ang Mo Kio Avenue 9 SINGAPORE
569784
Tel No:1800-2180000

Date/Time Report Made 27/08/2022 10:09	Vide Report No.	Station Diary No.
Name Of Informant TANG KONG WENG	Address 49 TEBAN GARDENS ROAD #01-584 SINGAPORE 600049	
ID Type / ID No. FIN NO / G7043813K	Contact No. Home/Office: Mobile: 94513353	
Nationality MALAYSIAN	Email Address tk.weng@hotmail.com	
Occupation CONSTRUCTION WORKER-CUM DRIVER	Sex Male	Age 43
Institution/School Name	Date of Birth 24/06/1979	Race Chinese
Date/Time Of Incident 26/08/2022 10:35	Language English	
	Location Of Incident HOUGANG AVENUE 3	

Brief details.

On 26.08.2022 at about 10:35 hours along Hougang Avenue 3 towards Tampines Road, I was travelling straight on lane 2 at the above mentioned location and when the front vehicle (C) slowed down and stopped, hence I also followed suit.

Suddenly, I heard a loud bang from behind and the great impact forced my vehicle (A) to move forward and collided onto the rear portion of vehicle (C). When I alighted, I realised it was vehicle (B) that collided onto the rear portion of my vehicle (A), thus causing damages onto the front and rear portion of my vehicle (A).

Signature Of Officer Recording The Report: Not applicable	Signature Of Informant: The identity of the person making this report has been authenticated by Singpass. No signature is required.
Signature Of Interpreter: Not applicable	Date/Time: 27/08/2022 10:09
Officer In-Charge Of Case:	Classification Of Case:



**SINGAPORE
POLICE FORCE**



F/20220827/7016

2 of 2

POLICE REPORT (NP299)

CONTINUATION OF REPORT

Report No. F/20220827/7016

I wish to state that it was a chain collision of total of 3 vehicles involved.
After the accident, I felt pain and I went to seek for doctor and was given 3days mc

Clinic : UNIHEALTH 24-HR CLINIC (TOA PAYOH)

Vehicle (A): JSN 7513

Vehicle (B): GBH 9561Y

Vehicle (C): SLN 5045Y

Signature Of Officer Recording The Report:
Not applicable

Signature Of Interpreter:
Not applicable

Officer In-Charge Of Case:

Signature Of Informant:

The identity of the person making this
report has been authenticated by Singpass.
No signature is required.

Date/Time:
27/08/2022 10:09

Classification Of Case:


HD Perfect Autowork Pte Ltd

Company Reg No: 202136904Z

8 Kaki Bukit Ave 4, #08-09 Premier@Kaki Bukit
Singapore 415875

Tel : 6341 6789 Fax: 6341 6778

E-mail: hdperfectautowork@gmail.com



HD PERFECT
AUTOWORK PTE LTD

DATE : 29.08.2022

TO : **GREAT AMERICAN** MOTOR CLAIMS DEPTS
VEHICLE NO : **JSN7513**
MODEL : **PROTON EXORA**
DATE OF ACCIDENT : 26.08.2022
TIME OF ACCIDENT : 10:35HRS

Celine

WE APPEND HEREUNDER THE ESTIMATED COST OF REPAIRS TO BE CARRIED OUT TO THE ABOVE VEHICLE.

CLAIM DETAIL : PARTS

S/N	DESCRIPTION	QTY	UNIT LIST PRICE	TOTAL LIST PRICE
1	FRONT BUMPER <i>Delcd</i>	1	\$ 495.00	\$ 495.00
2	FRONT BUMPER LOWER GRILLE <i>new</i>	1	\$ 130.00	\$ 130.00
3	FRONT BUMPER FOGLAMP RING <i>new</i>	2	\$ 70.00	\$ 140.00
4	FRONT BUMPER REINFORCEMENT <i>Delcd</i>	1	\$ 263.30	\$ 263.30
5	FRONT BUMPER SPONGE <i>Delcd</i>	1	\$ 138.20	\$ 138.20
6	FRONT BUMPER SIDE RETAINER <i>new</i>	2	\$ 18.40	\$ 36.80
7	FRONT BUMPER NUMBER PLATE HOLDER <i>Delcd</i>	1	\$ 86.40	\$ 86.40
8	HEADLAMP <i>Crashed</i>	2	\$ 650.00	\$ 1,300.00
9	HEADLAMP LOWER BRACKET <i>Crashed</i>	2	\$ 38.20	\$ 76.40
10	CENTER GRILLE <i>Crashed</i>	1	\$ 352.20	\$ 352.20
11	CENTER GRILLE LOGO <i>new</i>	1	\$ 45.00	\$ 45.00
12	FRONT FENDER COWLING <i>new</i>	2	\$ 125.30	\$ 250.60
13	BONNET <i>Delcd</i>	1	\$ 550.20	\$ 550.20
14	BONNET LOCK <i>new</i>	1	\$ 97.70	\$ 97.70
15	BONNET STOPPER <i>new</i>	2	\$ 17.20	\$ 34.40
16	BONNET HINGE <i>new</i>	2	\$ 39.40	\$ 78.80
17	BONNET INSULATOR <i>new</i>	1	\$ 198.70	\$ 198.70
18	BONNET INNER RUBBER	2	\$ 59.20	\$ 118.40
19	FRONT SUPPORT PANEL <i>Crashed</i>	1	\$ 455.20	\$ 455.20
20	AIR CON CONDENSER <i>new</i>	1	\$ 704.20	\$ 704.20
21	AIR CON CONDENSER MOUNTING RUBBER <i>new</i>	4	\$ 29.40	\$ 117.60
22	AIR CON CONDENSER BRACKET <i>new</i>	2	\$ 29.40	\$ 58.80
23	AIR CON CONDENSER SIDE GARNISH <i>new</i>	1	\$ 27.40	\$ 27.40
24	RADIATOR <i>new</i>	1	\$ 1,540.80	\$ 1,540.80

TO : GREAT AMERICAN MOTOR CLAIMS DEPTS
 VEHICLE NO : JSN7513
 MODEL : PROTON EXORA
 DATE OF ACCIDENT : 26.08.2022
 TIME OF ACCIDENT : 10:35HRS

25	TAIL LAMP	Lit cruld, Distorted	2	\$ 369.00	\$ 738.00
26	TAILGATE	Distorted	1	\$ 1,280.00	\$ 1,280.00
27	TAILGATE LOGO	2	1	\$ 65.00	\$ 65.00
28	TAILGATE EMBLEM 'EXORA'	1	1	\$ 75.00	\$ 75.00
29	TAILGATE EMBLEM 'TURBO'	1	1	\$ 55.00	\$ 55.00
30	TAILGATE OUTER MOULDING	cruld	1	\$ 240.00	\$ 240.00
31	TAILGATE THIRD BRAKE LAMP	new	1	\$ 1,477.00	\$ 1,477.00
32	TAILGATE INNER LOCK	Repl	1	\$ 365.00	\$ 365.00
33	TAILGATE LOWER LOCK	new	1	\$ 25.00	\$ 25.00
34	TAILGATE INNER HOLDER	new	1	\$ 28.00	\$ 28.00
35	TAILGATE DAMPER	2 new	2	\$ 130.00	\$ 260.00
36	TAILGATE STOPPER	1 new	2	\$ 15.00	\$ 30.00
37	TAILGATE WEATHER STRIP	lit	1	\$ 195.00	\$ 195.00
38	TAILGATE INNER TRIM (LOWER)	new	1	\$ 285.00	\$ 285.00
39	TAILGATE WINDSCREEN MOULDING	new	1	\$ 170.00	\$ 170.00
40	TAIL GATE WINDSCREEN GLASS	shattered	1	\$ 953.20	\$ 953.20
41	TAILGATE WIPER ARM	2 new	1	\$ 114.30	\$ 114.30
42	TAILGATE WIPER MOTOR	Repl	1	\$ 382.40	\$ 382.40
43	TAILGATE WIPER BOLT COVER	2 new	1	\$ 26.00	\$ 26.00
44	REAR BUMPER	Distorted	1	\$ 590.00	\$ 590.00
45	REAR BUMPER REFLECTOR	new	2	\$ 65.00	\$ 130.00
46	REAR BUMPER BRACKET	new	4	\$ 25.00	\$ 100.00
47	REAR BUMPER SIDE RETAINER	new	2	\$ 85.00	\$ 170.00
48	REAR BUMPER CENTER LAMP	new	1	\$ 165.00	\$ 165.00
49	REAR BUMPER REINFORCEMENT	Distorted	1	\$ 395.00	\$ 395.00
50	REAR BUMPER REVERSE SENSOR (SET)	Repl	1	\$ 500.00	\$ 500.00
51	REAR FENDER INNER TRIM	cruld	2	\$ 420.00	\$ 840.00
52	REAR FENDER INNER COWLING	new	2	\$ 155.00	\$ 310.00
53	REAR END PANEL	Distorted	1	\$ 480.00	\$ 480.00
54	REAR END PANEL TOP GARNISH	Del	1	\$ 135.00	\$ 135.00
55	REAR END PANEL (EXTEND)	Repl	2	\$ 195.00	\$ 390.00
56	REAR END PANEL BOTTOM (CENTRE)	Repl	1	\$ 210.00	\$ 210.00
57	REAR TOOLS TRAY	new	1	\$ 201.80	\$ 201.80
58	REAR FLOOR PANEL	Repl	1	\$ 970.00	\$ 970.00
59	REAR FLOOR PANEL TOP BOARD	Del	1	\$ 364.10	\$ 364.10
60	SPARE TYRE BRACKET (HOLDER)	3 new	1	\$ 370.00	\$ 370.00
61	REAR SPARE TYRE BOLT HOLDER	new	1	\$ 95.00	\$ 95.00

369.

215.

70

20/50

660

TO : GREAT AMERICAN MOTOR CLAIMS DEPTS
 VEHICLE NO : JSN7513
 MODEL : PROTON EXORA
 DATE OF ACCIDENT : 26.08.2022
 TIME OF ACCIDENT : 10:35HRS

62	REAR FLOOR TOP BOARD INNER SUPPORT	1	\$ 281.30	\$ 281.30
----	------------------------------------	---	-----------	-----------

1100270 SN:20
 990243

TOTAL PRICE \$ 20,757.20
 LESS 10% \$ 2,075.72
 SUB TOTAL PRICE \$ 18,681.48

S/N	DESCRIPTION	QTY	UNIT S/NETT	TOTAL S/NETT
1	FRONT NUMBER PLATE <i>culd</i>	1	\$ 50.00	\$ 50.00
2	FRONT BUMPER LOWER LID (SPECIAL TYPE) <i>per</i>	1	\$ 800.00	\$ 800.00
3	FRONT BUMPER CLIP (SET) <i>per</i>	1	\$ 50.00	\$ 50.00
4	FRONT BUMPER FOGLAMP COVER GRANISH CLIP (SET) <i>per</i>	1	\$ 30.00	\$ 30.00
5	FRONT BUMPER LOWER GRILLE SIDE GARNISH CLIP (SET) <i>per</i>	1	\$ 30.00	\$ 30.00
6	BONNET SEALANT <i>per</i>	1	\$ 150.00	\$ 150.00
7	BONNET AIR GUARD GARNISH CLIP (SET) <i>per</i>	1	\$ 30.00	\$ 30.00
8	CENTER GRILLE CLIP (SET) <i>per</i>	1	\$ 30.00	\$ 30.00
9	COOLANT <i>per</i>	1	\$ 80.00	\$ 80.00
10	REAR NUMBER PLATE <i>culd</i>	1	\$ 50.00	\$ 50.00
11	REAR BUMPER CLIPS (SET) <i>per</i>	1	\$ 80.00	\$ 80.00
12	TAILLAMP CLIP (SET) <i>per</i>	1	\$ 50.00	\$ 50.00
13	TAILGATE OUTER MOULDING CLIP (SET) <i>per</i>	1	\$ 50.00	\$ 50.00
14	TAILGATE INNER TRIM (LOWER) CLIP (SET) <i>per</i>	1	\$ 80.00	\$ 80.00
15	TAILGATE WINDSCREEN SEALANT <i>per</i>	1	\$ 80.00	\$ 80.00
16	TAILGATE WINDSCREEN INNER SHIELD <i>per</i>	1	\$ 60.00	\$ 60.00
17	TAILGATE WINDSCREEN SOLAR FILM <i>per</i>	1	\$ 550.00	\$ 550.00
18	REAR FENDER INNER TRIM CLIP (SET) <i>per</i>	1	\$ 80.00	\$ 80.00
19	REAR FENDER INNER COWLING CLIP (SET) <i>per</i>	1	\$ 60.00	\$ 60.00
20	REAR END PANEL INSULATION SEAL <i>per</i>	1	\$ 150.00	\$ 150.00
21	REAR END PANEL TOP GARNISH CLIP (SET) <i>per</i>	1	\$ 50.00	\$ 50.00
22	REAR END PANEL (EXTEND) SEALANT <i>per</i>	2	\$ 60.00	\$ 120.00
23	REAR FLOOR PANEL SEALANT <i>per</i>	1	\$ 350.00	\$ 350.00
24	REAR SPARE TYRE <i>per</i>	1	\$ 380.00	\$ 380.00
25	REVERSE CAMERA <i>per</i>	1	\$ 480.00	\$ 480.00
26	REVERSE SENSOR <i>per</i>	1	\$ 220.00	\$ 220.00

850 TOTAL \$4,140.00

CLAIM DETAILS: LABOUR AND SPRAY PAINTING (FRONT)

S/N	JOB DESCRIPTION	PRICE	ADJUSTED COST
1	PANEL BEATING, REMOVING AND REPLACING PARTS	\$ 1,400.00	800

TO : GREAT AMERICAN MOTOR CLAIMS DEPTS
 VEHICLE NO : JSN7513
 MODEL : PROTON EXORA
 DATE OF ACCIDENT : 26.08.2022
 TIME OF ACCIDENT : 10:35HRS

2	SPRAY PAINTING TO AFFECTED AREA	\$ 1,400.00	500
3	WIRING CHECK	\$ 180.00	30
4	REMOVE AND REFIX AIRCON CONDENSOR AND REFILL AIRCON GAS	\$ 120.00	60
5	REMOVE AND REFIX RADIATOR AND CONDUCT PRESSURE TEST	\$ 80.00	60
6	REFOCUS HEADLAMP BEAM	\$ 60.00	x

1450

CLAIM DETAILS: LABOUR AND SPRAY PAINTING (REAR)

S/N	JOB DESCRIPTION	PRICE	ADJUSTED COST
1	TO PANEL BEAT, REMOVE AND REPLACE PARTS	\$ 1,800.00	800
2	TO SPRAY PAINT AFFECTED AREA	\$ 1,600.00	800
3	TUFF COAT	\$ 250.00	60
4	WIRING AND BULB CHECK	\$ 180.00	30
5	REMOVE AND REFIX CUSHION SEAT/UPHOLSTRY & ROOF LINING TO FACILITATE REPAIR	\$ 350.00	60
6	REMOVE AND REFIX REVERSE SENSOR AND DISTANCE SETTING	\$ 80.00	50
7	REMOVE AND REFIX REVERSE CAMERA AND DISTANCE SETTING	\$ 80.00	50
8	REAR CHASSIS ALIGNMENT	\$ 250.00	x
9	TRANSFER TAILGATE MECHANISM	\$ 80.00	✓
10	CONDUCT WATER LEAKAGE TEST	\$ 120.00	x
11	REMOVE AND REFIX REAR EXHAUST PIPE	\$ 180.00	x
12	REMOVE AND REFIX TAILGATE WINDSCREEN	\$ 120.00	✓
13	REMOVE AND REFIX FUEL TANK TO FACILITATE FLOOR PANEL REPLACEMENT	\$ 120.00	x

TO : GREAT AMERICAN MOTOR CLAIMS DEPTS
VEHICLE NO : JSN7513
MODEL : PROTON EXORA
DATE OF ACCIDENT : 26.08.2022
TIME OF ACCIDENT : 10:35HRS

14	TO CHECK DIAGNOSTICS OF VEHICLE MANAGEMENT/CONTROL UNITS, RESET MEMORIES TO SPECIFICATION ETC.	\$ 250.00	X
----	--	-----------	---

2050

TOTAL \$ 8,700.00

ESTIMATE REPORT

TOTAL PARTS COST : \$22,821.48
TOTAL LABOUR COST : \$8,700.00
TOTAL REPAIR COST : \$31,521.48

Adrian G
1/2 30/08/22
12 Days

NB: THIS IS ONLY AN ESTIMATE AND SHOULD ADDITIONAL WORK BE FOUND NECESSARY TO BE CARRIED OUT IN THE COURSE OF REPAIRS, EXTRA MATERIALS AND LABOUR COST WILL BE CHARGED ACCORDINGLY WHICH HOWEVER YOU WILL BE INFORMED PRIOR TO ACTION TAKEN.
PARTS PRICES ARE SUBJECT TO CHANGES.

YOURS FAITHFULLY,

IRENE

SERVICE ADVISOR
IRENE
HP : 8297 9787

total: 14452.43
1/2 11.5K

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date: