

MS Car Auto Pte Ltd

8 Kaki Bukit Ave 4 #01-07 Premier @ Kaki Bukit Singapore 415875

Tel : 6385-1838 / 9725 4442 Fax : 6386-1838 Email: motorstopoffice@gmail.com / motorstopservices@gmail.com

SJE : _____

Vehicle Nos : JTE 4504

Date of Survey : _____

Model : Yamaha Legenda

Contacts : _____

Year : _____

**** AGREED COR and Days with SJE ****

Amount : _____

Repair Days Agreed : _____

Nos.	Description	QTY	UNIT \$	Total \$	REMARKS IF ANY
1	Front Handle Bar <i>bt</i>	1	\$ 175.00	\$ 175.00	<i>bt</i>
2	Front Handle Grip	1	\$ 105.00	\$ 105.00	<i>out</i>
3	Front Brake Lever	1	\$ 75.00	\$ 75.00	<i>out</i>
4	Front Clutch Lever	1	\$ 75.00	\$ 75.00	<i>x nn</i>
5	Front Mirror Assy	1	\$ 95.00	\$ 95.00	<i>out</i>
6	Front Cowling	1	\$ 355.00	\$ 355.00	<i>cut</i>
7	Front Left Side Cowling	1	\$ 195.00	\$ 195.00	<i>dis</i>
8	Front Right Side Cowling	1	\$ 195.00	\$ 195.00	<i>dis</i>
9	Rear Right Pillion Foot Rest	1	\$ 65.00	\$ 65.00	<i>x nn</i>
10	Balancer	1	\$ 65.00	\$ 65.00	<i>out</i>
11	Front SideLamp (Set)	1	\$ 295.00	\$ 295.00	<i>cut</i>
12	Front HeadLamp	1	\$ 385.30	\$ 385.30	<i>cut</i>
13	Front HeadLamp Stay	1	\$ 136.50	\$ 136.50	<i>x nn</i>
14	Front HeadLamp Top Cowling	1	\$ 155.30	\$ 155.30	<i>cut</i>
15	Fork Stem	2	\$ 122.50	\$ 245.00	<i>bt</i>
16	Fork Assy	1	\$ 635.00	\$ 635.00	<i>bt</i>
17	Front HeadLamp Lower Cowling	1	\$ 355.00	\$ 355.00	<i>de</i>
18	Front Side Lower Fairing (Set)	1	\$ 395.00	\$ 395.00	<i>de</i>
19	Front Foot Rest L+R	2	\$ 65.00	\$ 130.00	<i>Right LH x nn 65</i>
20	Front Left Gear Selector	1	\$ 65.00	\$ 65.00	<i>x nn</i>
21	Front Right Foot Brake	1	\$ 65.00	\$ 65.00	<i>x nn</i>
22	Front Right Kick Start Pedal	1	\$ 75.00	\$ 75.00	<i>x nn</i>
23	Front Center Cowling	1	\$ 105.00	\$ 105.00	<i>mis</i>
24	Rear End Fender	1	\$ 105.00	\$ 105.00	<i>x nn</i>
25	Rear Cowling L + R	2	\$ 195.00	\$ 390.00	<i>LH x nn Right - 195</i>
26	Rear Tail Lamp	1	\$ 135.00	\$ 135.00	<i>x nn</i>
27	Rear Tail End Garnish	1	\$ 75.00	\$ 75.00	<i>de</i>
28	Rear signal RL	2	\$ 126.70	\$ 253.40	<i>x nn</i>
29	Front signal RL	2	\$ 122.40	\$ 244.80	<i>x nn</i>
30	Rear Exhaust Pipe	1	\$ 575.80	\$ 575.80	<i>x nn</i>
31	Rear Exhaust Pipe Protector	1	\$ 95.00	\$ 95.00	<i>xxx mis</i>
Total Price				\$ 6,316.10	4260.60
Discount 10%				\$ 631.61	3834.54
Parts Total				\$ 5,684.49	

Nos.	Special Nett Items	QTY	UNIT \$	Total \$	REMARKS IF ANY
1	Front Number Plate	1	\$ 10.00	\$ 10.00	<i>ne</i>
2	Front Fork Oil	1	\$ 30.00	\$ 30.00	<i>ne</i>
3	Rear End Tail Box Assy	1	\$ 150.00	\$ 150.00	<i>x nn</i>
4	Rear Number Plate	1	\$ 12.00	\$ 12.00	<i>x nn</i>
Total				\$ 202.00	40

MS Car Auto Pte Ltd

8 Kaki Bukit Ave 4 #01-07 Premier @ Kaki Bukit Singapore 415875

Tel: 6385-1838 / 9725 4442 Fax: 6386-1838 Email: motorstopoffice@gmail.com / motorstopservices@gmail.com / msgroupoffice@gmail.com

SJE :

Vehicle Nos : JTE 4504

Date of Survey :

Model : Yamaha Legenda

Contacts :

Year :

**** AGREED COR and Days with SJE ****

Amount :

Nos	Claims Details : Labour and Spray Painting	Total S\$	REMARKS IF ANY
1	To Replace Accident Affected Areas	\$ 500.00	250
2	To Putty and Spray Paint to Affected Areas	\$ 400.00	200
3	To Check Wheel Alignment Fork assy	\$ 300.00	120
4	To Focus Front Lighting Wiring	\$ 40.00	30
Total		\$ 1,240.00	600

0.5 days

4474.54
Special Nett \$ 202.00 l/s\$3550
LABOUR TOTAL \$ 1,240.00 5 days #
OVERALL TOTAL \$ 1,442.00

PARTS TOTAL \$ 5,684.49
Special Net \$ 202.00
LABOUR TOTAL \$ 1,240.00
OVERALL TOTAL \$ 7,126.49

NAME OF SURVEYOR :

REMARKS :

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: