

Car-in

29/9/22

wp= 38715

PREMIUM AUTOMOBILES

Bendi.



55 UBI ROAD 1, SINGAPORE 408699

TEL: 6366 2323 FAX: 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

Veron.

ALG - Adrian.

- 5 days.

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SMP 5338 E

DAMAGED PARTS & PRICES

S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
1	REAR BUMPER <i>Deh d</i>	1 S	3,188.00 ✓	
2	REAR BUMPER FIXING PARTS <i>neu</i>	1 S	487.00 +	
3	REAR BUMPER SECURING STRIPS <i>Neu</i>	1 S	249.00 ✓ <i>fl.s.</i>	
4	REAR BUMPER SPOILER <i>lit</i>	1 S	276.00 ✓	
5	REAR BUMPER BLACK TRIM <i>guled</i>	1 S	326.00 ✓	
6	REAR BUMPER BRACKET LH / RH ?	2 S	260.00 ?	
7	REAR BUMPER LIGHT REFLECTOR REAR LH / RH <i>neu</i>	2 S	92.00 +	
8	REAR BUMPER REINFORCEMENT BEAM <i>Dented</i>	1 S	1,131.00 ✓	
9	REAR BUMPER SEAL <i>Neu</i>	1 S	32.00 ✓	
10	REAR BUMPER GUIDE SECTION LH / RH <i>neu</i>	2 S	52.00 +	
11	REAR BUMPER HOLDING STRIPS LH / RH <i>neu</i>	2 S	188.00 +	
12	REAR PARKING AID SENSORS INNER / OUTER <i>Inner Misco</i>	2 S	531.00 ✓	
13	REAR PARKING AID SENSORS SEAL RINGS <i>Neu</i>	4 S	10.00 ✓	
14	EXHAUST TAIL TRIM PIPE LH / RH <i>neu</i>	2 S	766.00 +	
15	REAR LID <i>Dented</i>	1 S	3,497.00 ✓	
16	REAR LID LOCK	1 S	218.00 +	
17	REAR LID LOCK COVER CAP <i>neu</i>	1 S	8.00 +	
18	REAR LID LOCK STRIKER	1 S	37.00 +	
19	PARKING ADHESIVE <i>neu</i>	1 S	21.00 ✓	
20	REAR LID WEATHERSTRIP <i>neu</i>	1 S	229.00 +	
SUB TOTAL SPARE PARTS			\$ 11,598.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
SPARE PARTS ARE SPECIAL NETT.

Adrian L
fl.s. Resurveyed.