



55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

**ESTIMATE** : ACCIDENT REPAIRS  
**WORKSHOP** : UBI ROAD 1  
**CONTACT NO** : 6366 2323  
**FAX NO** : 6841 1183  
**REFERENCE** : PA/OD/0675/2022/EQ  
**DATE** : 11-Aug-22  
**WIP** : 36496

**VEHICLE NOT IN WORKSHOP. KINDLY ARRANGE FOR SURVEY ON 12/08/2022**

**AIG ASIA PACIFIC INSURANCE PTE LTD**

78 SHENTON WAY

#07-16 AIG BUILDING

SINGAPORE 079120

Attn: Motor Claims Dept

**Tel: 6880 4602 - Fax: 6880 4838**

**OWNER'S NAME** : MS SOPHIA EVANGELINE GOH YI QING  
**ADDRESS** : 53 CHEMPAKA AVENUE

SINGAPORE 349667  
**TELEPHONE** : HP +65 97878747  
**TYPE OF CLAIM** : OWN DAMAGE CLAIM  
**POLICY NO** : 7220036108  
**VEHICLE NO** : **SNE 7738 S**  
**MODEL CODE** : A3 SEDN 1.5 TFSI  
**MODEL YEAR** : 8/4/2022  
**ENGINE NO** : DFY 309676  
**CHASSIS NO** : WAUZZZGY2NA026112  
**MILEAGE** : -  
**DATE IN** : -  
**ESTIMATED BY** : JOHNNY BOO / ALLAN WU  
**ACCIDENT DATE** : 6-Aug-22  
**PLACE OF ACCIDENT** : ALONG ORCHARD ROAD OUTSIDE TAKASHIMAYA



55 UBI ROAD 1, SINGAPORE 408699  
 TEL : 6366 2323 FAX : 6841 1183  
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

**ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SNE 7738 S**

S/N	NATURE OF JOBS		ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE, CHECK AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR, HEADLIGHT WASHER ASSY ANF FRONT PARKING AID.	S/N \$	480.00	✓ ✓
2	TO RMEOVE AND TRANSFER BOTH HEADLIGHT'S CONTROL UNIT AND POWER MODULE.	S/N \$	700.00	X
3	TO DISMANTLE AND RENEW FRONT BUMPER AND BOTH HEADLIGHT. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.	\$	1,050.00	500 ✓
4	TO RESPRAY FRONT BUMPER	\$	1,200.00	550 ✓
5	TO CARRY OUT DIAGNOSTIC CHECK	S/N \$	192.00	✓ ✓
<b>TOTAL LABOUR CHARGES</b>		<b>:</b>	<b>\$ 3,622.00</b>	



55 UBI ROAD 1, SINGAPORE 408699  
 TEL : 6366 2323 FAX : 6841 1183  
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

**MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SNE 7738 S**

					DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT		REMARKS	
1	FRONT BUMPER <i>chd</i>	1	\$	1,677.00	✓	1341.60
2	FRONT BUMPER FIXING PARTS <i>new</i>	1	\$	290.00	X	
3	FRONT BUMPER CLOSING ELEMENT - LH / RH <i>new</i>	2	\$	260.00	f	
4	FRONT BUMPER GRILLE - LOWER CENTRE <i>chd</i>	1	\$	433.00	✓	346
5	FRONT BUMPER CLOSING ELEMENT - LOWER CENTRE <i>new</i>	1	\$	265.00	f	
6	FRONT BUMPER AIR GUIDE - LH / RH <i>new</i>	2	\$	134.00	f	
7	FRONT BUMPER SPOILER <i>new</i>	1	\$	326.00	f	
8	FRONT BUMPER SPOILER TRIM - LH / RH	2	\$	208.00	f	
9	FRONT BUMPER AIR GUIDE GRILLE - LH / RH <i>new</i>	2	\$	342.00	f	
10	FRONT PARKING AID SENSOR BRACKET - LH / RH	2	\$	86.00	f	
11	RADIATOR GRILLE <i>chd</i>	1	\$	932.00	✓	745.60
12	RADIATOR GRILLE CLOSING ELEMENT - CENTER <i>cracked</i>	1	\$	210.00	>	168
13	FRONT BUMPER FOAM FILLER PIECE <i>x nn</i>	1	\$	120.00	?	
14	FRONT BUMPER CARRIER <i>new</i>	1	\$	748.00	f	
15	FRONT BUMPER COVER - INNER <i>x nn</i>	1	\$	93.00	?	
16	FRONT BUMPER GUIDE SECTION - LH / RH <i>new</i>	2	\$	108.00	f	
17	FRONT BUMPER SUPPORT - LH / RH <i>new</i>	2	\$	20.00	f	
18	CAUTION SIGN STICKER <i>new</i>	1	\$	16.00	✓	12.40
19	AIR CONDITIONER STICKER <i>new</i>	1	\$	9.00	✓	6.64
20	FRONT PARKING AID SENSOR - INNER <i>new</i>	2	\$	558.00	f	
<b>SUB TOTAL SPARE PARTS</b>			:	<b>\$ 6,835.00</b>		

ALL CHARGES ARE NOT INCLUSIVE OF GST  
 LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED  
 SPARE PARTS ARE SPECIAL NETT.



55 UBI ROAD 1, SINGAPORE 408699  
 TEL : 6366 2323 FAX : 6841 1183  
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

**MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SNE 7738 S**

S/N	PARTS DESCRIPTION	QTY	DAMAGED PARTS & PRICES	
			S/NETT	REMARKS
21	FRONT PARKING AID SEAL RING	4	\$	52.00 X
22	HEADLIGHT - LH / RH	2	\$	8,168.00 X
23	LIFT CYLINDER - LH / RH	2	\$	422.00 X
24	LIFT CYLINDER HOSE	1	\$	108.00 X
25	TEMPERATURE SENSOR HOLDER	1	\$	6.00 X
26	RADIATOR AIR GUIDE	2	\$	84.00 X
27	FRONT NO PLATE <i>Derbed</i>	S/N	\$	60.00 ✓ 60
28	SUNDRIES <i>? x nn</i>		\$	400.00 ?
<b>TOTAL SPARE PARTS</b>		:	\$	<b>16,135.00</b>
<b>TOTAL LABOUR CHARGES</b>		:	\$	<b>3,622.00</b>
<b>GRAND TOTAL</b>		:	\$	<b>19,757.00</b>

ALL CHARGES ARE NOT INCLUSIVE OF GST  
 LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED  
 SPARE PARTS ARE SPECIAL NETT.



55 UBI ROAD 1, SINGAPORE 408699  
TEL : 6366 2323 FAX : 6841 1183  
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

**NAME** : *Adrian L*  
**SURVEYED DATE** : *29/08/22*  
**AUTHORISED DATE** :  
**EXCESS COST** :  
**LIABILITY** :  
**REMARKS** : *Not Authorised, 03 Days.*

**PLEASE NOTE** : THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF THE AFFECTED VEHICLE. SHOULD WE REQUIRE FURTHER LABOUR CHARGES AND SPARE PARTS IN THE PROGRESS OF REPAIR, WE SHALL INFORM YOU ACCORDINGLY. FOR INSPECTION OF VEHICLE, PLEASE REFER TO MS. NORAH KHAI AT TEL: 6768 9828 / 6768 9911 FOR APPOINTMENT.

YOURS FAITHFULLY,  
PREMIUM AUTOMOBILES PTE LTD

- LKK Auto Consultants hence notify the Repairer of the following:
- To resurvey before/after spray painting
  - To display damaged part(s) during resurvey
  - Parts prices are subject to confirmation
  - Third party survey is on a "Without Prejudice" basis
  - No illegal modification(s) is allowed
  - Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

JOHNNY BOO  
BODY REPAIR MANAGER

ALLAN WU  
CLAIMS CONSULTANT