

Hsiao Tong (LKKAUTO)

From: Hsiao Tong (LKKAUTO)
Sent: Wednesday, 1 February 2023 8:54 AM
To: Adeline Chng
Cc: Admin A; claimsdept@sg.cntaiping.com
Subject: [SEEK MANDATE] - SNM22D205941/C02/SMD2094R/CHNGPW / RE: Direct Settlement - Accident Involving SMD2094R (OI : CTI - TBA) AND SJU9085S (TP : LKK REF - CC6/CTI22008439/Apa3) on 20/08/2022
Attachments: LKK SURVEY REPORT & PHOTOS.pdf; LOD_SJU9085S.pdf; Letter to OI_SMD2094R_.pdf

Your ref: **SNM22D205941/C02/SMD2094R/CHNGPW**
LKK ref : CC6/CTI22008439/Apa3q2

Dear Sirs/Mdm,

ACCIDENT INVOLVING SMD2094R(CHINA TAIPING) AND SJU9085S (TP) ON 20/08/2022

We refer to the above matter.

It is a head-to-rear collision. We are of the view that liability is not in our driver's favour.

We seek your approval to offer repairer **"MG SOLUTION PTE LTD"** at **\$7,243.45(all-in)**.

The summary is as follows: -

	Amount Claimed	Amount Revised
1. Cost of Repair (with 8% GST)	\$ 16,397.90	\$ 6,696.00 (\$6,200.00 + 8%GST)
2. Loss of Use (9days x \$200.00)	\$ 1,800.00	\$ 540.00 (9DAYS X \$60.00)
3. LTA/ GIA SEARCH FEE	\$ 7.45	\$ 7.45
Total	\$ 18,205.35	<u>\$ 7,243.45</u>

Surveyor recommended 7days for repair +1PRS + 1SUNDAY = 9DAYS.

Enclosed here with all the relevant documents for your perusal.

Kindly note that this inspection report dated 06/01/2023 is only for mandate purpose.

Kindly let us have your approval / instruction.

Best Regards,
Hsiao Tong, Chew (Ms) | Case Handler
LKK Auto Consultants Pte Ltd
Phone: 6742-3197 | Email: chewht@lkkauto.com |
HQ : Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

-----Original Message-----

From: Hsiao Tong (LKKAUTO)
Sent: Tuesday, 27 December 2022 5:35 PM
To: Adeline Chng <adeline.chng@sg.cntaiping.com>

Cc: Admin A <admin-a@lkkauto.com>; claimsdept@sg.cntaiping.com
Subject: RE: SNM22D205941/C02/SMD2094R/CHNGPW / RE: Direct Settlement - Accident Involving SMD2094R (OI : CTI - TBA) AND SJU9085S (TP : LKK REF - CC6/CTI22008439/Apa3) on 20/08/2022

Dear Sirs/ Mdm,

Enclosed for your perusal is: -

- Estimated cost of repair.
- Preliminary advice.
- Photographs of TP vehicle in its damaged condition

Thank you.

Best Regards,
Hsiao Tong, Chew (Ms) | Case Handler
LKK Auto Consultants Pte Ltd
Phone: 6742-3197 | Email: chewht@lkkauto.com | HQ : Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

-----Original Message-----

From: Adeline Chng <adeline.chng@sg.cntaiping.com>
Sent: Monday, 5 September 2022 10:16 AM
To: Mei Kwan (LKKAuto) <Meikwan@lkkauto.com>
Cc: Hsiao Tong (LKKAuto) <chewht@lkkauto.com>; Admin A <admin-a@lkkauto.com>
Subject: RE: SNM22D205941/C02/SMD2094R/CHNGPW / RE: Direct Settlement - Accident Involving SMD2094R (OI : CTI - TBA) AND SJU9085S (TP : LKK REF - CC6/CTI22008439/Apa3) on 20/08/2022

[Strictly Confidential]

This is a Secure PDF message. This email has been protected as an encrypted PDF document.

Please retrieve the PDF password from <https://se-password.secureage.com/#/?id=395ae616-f757-4073-aac8-abbb28ffaa0b> and open the encrypted PDF attachment to view your secure message. If you have problem accessing the encrypted message, please contact the sender of the message.