

PANG SCOOTER SERVICE
Blk 1006 Bukit Merah Lane 2 #01-06 Singapore 159762
Tel : 6271 4618 Fax : 6273 2632
Business Regn. No. 10115500W

INVOICE NO. 0016/2022

BIKE NO: FZ9325X

Messer

RIDUAN BIN DALI

Date 16/09/2022

BLK 630 WOODLANDS RING ROAD #07-226

D.O.A. 22/10/2021

SINGAPORE 730630

MAKE/MODEL : T135

S/No	DESCRIPTION	AMOUNT
1	HANDLER BAR	\$85.00
2	HANDLER BRACKET	\$45.00
3	HANDLER END	\$35.00
4	COWLING STAY	\$48.00
5	UNDER BRACKET	\$185.00
6	STEERING CON	\$98.00
7	FORK ASST	\$450.00
8	F WHEEL RIM	\$350.00
9	F BRAKE DISC	\$150.00
10	F FENDER	\$80.00
11	F WHEEL SHAFT	\$45.00
12	2X SIGNAL LIGHT	\$98.00
13	CLUTCH LEVER	\$25.00
14	HEAD LIGHT ASST	\$135.00
15	RADIATOR ASST	\$280.00
16	HEAD LIGHT COVER	\$85.00
17	F COWLING	\$165.00
18	L/H LEG SHIELD	\$85.00
19	R/H LEG SHIELD	\$85.00
20	L/H GUIDE AIR	\$45.00
21	R/H GUIDE AIR	\$45.00
22	CENTER PANEL	\$120.00
23	F FOOT REST BAR	\$85.00
24	F FOOT REST RUBBER	\$25.00
25	BRAKE PEDAL	\$68.00
26	TOWING	\$100.00
27	COOLANT	\$20.00
28	REAR BOX	\$385.00
29	BOX BRACKET	\$185.00
30	IU UNIT	\$165.00
31	IU BRACKET	\$35.00
32	MIRROR	\$45.00
33	LABOUR	\$500.00
	LUMP SUM REPAIR \$2950/-	