



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

NTUC INCOME INSURANCE CO-OPERATIVE LTD
73 BRAS BASAH ROAD
#05-01 NTUC TRADE UNION HOUSESINGAPORE
189556

Ref: CS/INC22008467/Dqy3

Date: 31/08/2022

Code: INC

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	GBL 9776Z	Veh. Inspected	SHA 5585X
Policy No.		Coverage (\$)	0.00
Claim No.	MT/1186607-002	Excess (\$)	0.00
Assign From	ANNIE KOH	Assign Date	31/08/2022

2. Vehicle Particulars & Condition

Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

4. Description of Damages

--

5. General Information

Accident Date	29/08/2022	Inspection Date	31/08/2022
Survey held at	Blk 9 Sector C #01-42, Sin Ming Industrial Estate		
Repairer	BIFROST AUTO PTE LTD		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.
B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.