

## **LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

Affiliated to rederation internationale des Experts En Automobile						
	NTUC INCOME IN:	SURANCE CO-OPERATIVE LTD		Ref:	CS/INC22008468/Dvy3	
	73 BRAS BASAH F #05-01 NTUC TRA 189556	ROAD DE UNION HOUSESINGAPORE		Date:	31/08/2022	
				Code:	INC	
1.	1. Policy Particulars :- THIRD PARTY CLAIM					
	Insured Veh.	SNC 7017A	Veh. Inspected	l	SHD 4558R	
	Policy No.		Coverage (\$)		0.00	
	Claim No.	MT/1186312-002	Excess (\$)		0.00	
	Assign From	ANNIE KOH	Assign Date		31/08/2022	
2.	2. Vehicle Particulars & Condition					
	Make & Model		c.c		0	
	Engine No.	HIDDEN	Year of Reg.			
	Chassis No.		Colour			
	Odometer	-	Steering			
	Brakes		Modification			
	General					
3. Conditions of Tyres						
		Size	Make		Balance	
	R/H Front Tyre				mm	
	L/H Front Tyre				mm	
	R/H Rear Tyre				mm	
	L/H Rear Tyre				mm	
4.	Description of Damages					
5. General Information						
	Accident Date	26/08/2022	Inspection Dat	е	31/08/2022	
	Survey held at	Blk 9 Sector C #01-42, Sin Ming	Industrial Estate			
	Repairer	BIFROST AUTO PTE LTD				
5a. Remarks						
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.					