

EROFIA MOTOR TRADING PTE LTD (201202259N)

No 1 Kaki Bukit Avenue 6 #02-62 AutoBay @ Kaki Bukit Singapore 417883

Tel : 67527740 Fax : 67528669

E-mail: erofia@singnet.com.sg

Name : Heng Han Bin, Bill

Accident Date : 24-Aug-22

Vehicle No : FBN2015Y (COE310728)

Vehicle Model : Honda CBF 190WH

Estimated Repair Costs

Qty	Description List Items	Amount S(\$)
1	Front fender <i>one</i>	128 \$ 155.00 ✓
1	Front fork <i>assy surf/tan</i>	750 \$ 1,100.00 ✓
1	Fork underbracket <i>surf</i>	225 \$ 385.00 ✓
1	Front rim <i>1</i>	\$ 380.00 X
1	Front rim shaft <i>11</i>	\$ 98.00 q
1	Front rim bearing <i>11</i>	\$ 78.00 q
1	Front brake disc <i>11</i>	\$ 220.00 x
1	Handle bar - L/R/H <i>surf</i>	180 \$ 360.00 ✓
1	Handle bar end (1 set) <i>cut</i>	40 \$ 150.00 —
1	Hand grip (1 set) <i>11</i>	\$ 88.00 X
1	Brake lever (1 set) <i>cut</i>	115 \$ 168.00 —
1	Mirror (1 set) <i>320</i>	86 \$ 178.00 —
1	Front signal - L/R/H <i>cut</i>	80 \$ 280.00 —
1	Windshield <i>one</i>	150 \$ 280.00 —
1	Headlamp (LED) <i>320</i>	650 \$ 780.00 —
1	Headlamp cover <i>mis</i>	112 \$ 240.00 —
1	Headlamp side cover - L/R/H <i>cut</i>	160 \$ 310.00 —
2	Upper centre cover - L/R/H <i>o/s one</i>	160 \$ 360.00 <i>1 pc</i>
2	Lower centre cover (glossy black) - L/R/H <i>o/s one</i>	100 \$ 300.00 <i>1 pc</i>
1	Fuel tank side cover - L/R/H <i>one</i>	290 \$ 520.00 ✓
1	Clutch outer cover <i>cut</i>	480 \$ 650.00 —
1	Front footrest (1 set) <i>320</i>	60 \$ 166.00 —
1	Front footrest bracket (1 set) <i>one</i>	250 \$ 580.00 —
1	Rear footrest (1 set) <i>cut</i>	60 \$ 145.00 —
1	Rear footrest bracket (1 set) <i>11</i>	\$ 480.00 X
1	Brake pedal <i>surf</i>	115 \$ 178.00 —
1	Exhaust assy <i>100</i>	800 \$ 950.00 —
1	Exhaust protector <i>mis</i>	60 \$ 185.00 —
1	Swing arm <i>surf/tan</i>	\$ 680.00 ✓
1	Chain cover <i>cut</i>	102 \$ 188.00 —
1	Rear cover - L/R/H <i>cut</i>	180 \$ 315.00 —
		\$ 10,947.00
	Less 10%	\$ 1,094.70
		\$ 9,852.30

EROFIA MOTOR TRADING PTE LTD (201202259N)

No 1 Kaki Bukit Avenue 6 #02-62 AutoBay @ Kaki Bukit Singapore 417883

Tel : 67527740 Fax : 67528669

E-mail: erofia@singnet.com.sg

Name : Heng Han Bin, Bill

Accident Date : 24-Aug-22

Vehicle No : FBN2015Y (COE310728)

Vehicle Model : Honda CBF
190WH

Estimated Repair Costs

Special Net Items

1	Number plate (1 set)	new for	\$	38.00	10
1	Fork oil	17	\$	40.00	X
2	Fork oil seal	17	\$	78.00	X
1	Steering cone	new	\$	138.00	80
1	Clutch cover gasket	new	\$	105.00	60
1	Engine oil	new	\$	50.00	50.25
1	Rear box	cut	\$	480.00	400
1	Rear box bracket	new	\$	180.00	
			\$	1,109.00	

S/No. Labour

1	To provide towing service (LOD) \$70.00	\$	-
2	To check wiring and reset headlamp focusing	\$	17 80.00 X
4	To provide spray paint	\$	680.00 400
5	To provide labour	\$	480.00 380
			\$ 1,720.00

Grand Total

\$

Singapore Dollars: Twelve Thousand Six Hundred Eighty-One and Cents: Thirty only

EROFIA MOTOR TRADING PTE LTD

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: