

Thiam Heng Huat Pte Ltd

176 Sin Ming Drive #05-14 Sin Ming Autocare Singapore 575721

Mobile: 82636295 Email: thiamhenghuat@gmail.com

Not Authorized
Resurvey B4 painting
2 days

Make/Model: AUDI A5

Engine/Chassis No.: WAUZZZF54LA018257

Date of accident:


Damaged area: Rear

Date: 31/08/2022

Claim Type: TP

VRN: SJT966P

84077.94



List items				
S/N	Parts description	QTY	UNIT PRICE	AMOUNT
1	Rear bumper <i>2087-20 Bumper</i>	1	\$ 2,174.30	\$ 2,174.30
2	Rear bumper reinforcement <i>R</i>	1	\$ 870.00	\$ 870.00
3	Rear bumper side retainer upper <i>Sm</i>	2	\$ 56.20	\$ 112.40
4	Rear bumper side reflector <i>082 d/s cm</i>	2	\$ 231.95	\$ 463.90
5	Rear exhaust chrome garnish inner bracket o/s <i>cm</i>	1	\$ 191.25	\$ 191.25
6	Rear bumper lower <i>rd/br</i>	1	\$ 669.70	\$ 669.70
7	Rear exhaust chrome garnish o/s <i>409 rd</i>	1	\$ 450.00	\$ 450.00
8	Rear bumper center bracket <i>Sm</i>	1	\$ 90.00	\$ 90.00
9	Rear bumper side retainer lower <i>Sm</i>	2	\$ 56.20	\$ 112.40
Subtotal			\$	5,133.95
List discount				5.00%
Total			\$	4,877.25

Special nett items				
No.	Parts description	QTY	UNIT PRICE	AMOUNT
1	Rear bumper reverse sensor <i>sm</i>	1	\$ 294.75	\$ 294.75
2	Rear bumper sensor holder <i>nn</i>	1	\$ 26.00	\$ 26.00
3	Rear bumper clips <i>NN</i>	12	\$ 5.50	\$ 66.00
4	Sundries <i>nn</i>	1	\$ 50.00	\$ 50.00
Total			\$	436.75

Labour			
No.	Description	Work unit	Amount
1	To dismantle / renew the accident damaged portion. To panel beat, reshape, straighten, orientate and align repair / replacement parts.	6	\$ 1,200.00
2	To disconnect rear wire harness of electrical components to facilitate repairs, reconnect and check functions including taillamp lightings.	0.25	\$ 50.00
3	To rust proof all affected portions after repair.	0.5	\$ 100.00
4	Supply spray paint material and necessary items to respray affected area / panel.	5	\$ 1,000.00
Total labour			\$ 2,350.00
Estimate Grand Total			\$ 7,664.00

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: