

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

DAMAGE ASSESSMENT REPORT						
	INCOME INSURAN	ICE LTD	Re	ef:	CS/INC22008477/Kqy3m4	
	75 BRAS BASAH FINCOME CENTRE	Da	ate:	05/01/2023		
	ATTN: AZHARI AF	IDI	Co	ode:	INC	
1.	Policy Particulars :- THIRD PARTY CLAIM					
	Insured Veh.	SLE 9006G	Veh. Inspected		SJT 966P	
	Policy No.		Coverage (\$)		0.00	
	Claim No.	MT/1186481-002	Excess (\$)		0.00	
	Assign From	ANNIE KOH	Assign Date		31/08/2022	
2. Vehicle Particulars & Condition						
	Make & Model	AUDI A5 (A)	c.c		1984	
	Engine No.	HIDDEN	Year of Reg.		2020	
	Chassis No.	WAUZZZF54LA018257	Colour		METALLIC BLACK	
	Odometer	39867 KM	Steering		IN ORDER	
	Brakes	IN ORDER	Modification		STANDARD ALLOY RIM	
	General	GOOD				
3. Conditions of Tyres						
		Size	Make		Balance	
	R/H Front Tyre	245/40ZR18	CONTINENTAL		6 mm	
	L/H Front Tyre	245/40ZR18	CONTINENTAL		6 mm	
	R/H Rear Tyre	245/40ZR18	CONTINENTAL		8 mm	
	L/H Rear Tyre	245/40ZR18	CONTINENTAL		8 mm	
4. Description of Damages						
	THE VEHICLE SUSTAINED DAMAGES AT THE REAR O/S PORTION.					
	DAMAGES SEE DETAILS.					
5.	General Information					
	Accident Date	26/08/2022	Inspect Date / Tim	ne	31/08/2022 (10:21 AM)	
	Survey held at	THIAM HENG HUAT PTE LTD				
		176 SIN MING DRIVE #05-14 SINGAPORE 575721				
5a.	5a. Remarks					
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.					
5b.	Estimate Days of Repair					
	ESTIMATED NORMAL PERIOD FOR REPAIR: 2 Working Days					