

Cheng Auto Bodyworks (Co Reg No 53315238X)

5 Soon Lee Street #01-62 Pioneer Point

Singapore 627607

Tel: 6631 0707 Fax: 6316 2431 Email: cab@chengauto.com

INSURER: **Allianz Insurance Singapore Pte. Ltd. (HQ)****PARTICULARS OF CLAIM**

Claim Type:	OD (Own Damage)	Ref. No:	
Policy No:	SP200743851-01	Date of Loss:	16/08/2022
Vehicle Reg. No.:	SGR52Y	Driveable?	
Driver Age/Info:		Party At Fault:	UNKNOWN
TP Injury Involved?	NO	Third Party Involved?	YES
Insured/Claimant:	CHING AH CHOON		
Make/Model:	TOYOTA VELLFIRE, 2.5 Z G-EDITION CVT (A)	Vehicle Reg. Date:	14/11/2016
Vehicle Colour:	Black		
Engine No:	2ARH695016	Chassis No:	AGH300055941
Odometer:	0 KM		
Paint Type:			
Total Loss?	NO		
Est. Duration of Repair (day)	8		
Present Location:	CHENG AUTO BODYWORKS (HQ)		

COST OF CLAIMS

	Amount
Parts	9,592.00
Miscellaneous Items	160.00
Labour	1,700.00
Paintwork Labour	0.00
Towing	0.00
Gross Total (S\$)	11,452.00
+ GST 7.00% (S\$)	801.64
Nett Amount (S\$)	12,253.64

This claim is handled by: **MURUGESAN S/O REGUNATHAN**

Generated using Merimen e-Claims Internet Estimation & Adjusting System

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 30 Aug 2022)

Parts: M1-MPV TOYOTA VELLFIRE 2.5 Z G EDITION CVT (A) (Catalogue: Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: Cheng Auto Bodyworks/SGR52Y/30/08/2022 12:22

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1	NA	*BONNET X R	0.00	0.00	*550.00 F
2	1	NA	*BONNET HINGE RH X BT	0.00	0.00	*45.00 F ✓
3	1	NA	*BONNET HINGE LH X BT	0.00	0.00	*45.00 F ✓
4	1	NA	*BONNET ISOLATOR X NN	0.00	0.00	*140.00 F
5	1	NA	*BONNET LOCK ASSY X NN	0.00	0.00	*90.00 F
6	1	NA	*BONNET RUBBER X NN	0.00	0.00	*30.00 F
7	1	NA	*BONNET CHROME X CRA	0.00	0.00	*250.00 F ✓
8	1	NA	*GRILLE ASSY X BR	0.00	0.00	*700.00 F ✓
9	1	NA	*GRILLE LOGO X NEC	0.00	0.00	*90.00 F ✓
10	1	NA	*HEADLAMP RH X BR	0.00	0.00	*1,850.00 F ✓
11	1	NA	*HEADLAMP LH X BR	0.00	0.00	*1,850.00 F ✓
12	1	NA	*FOGLAMP GRILLE RH WITH CHROME X NN	0.00	0.00	*180.00 F ✓
13	1	NA	*FOGLAMP GRILLE LH WITH CHROME X BR	0.00	0.00	*200.00 F ✓
14	1	NA	*REINFORCEMENT X BT	0.00	0.00	*70.00 F ✓
15	1	NA	*SPONGE X BR	0.00	0.00	*150.00 F
16	1	NA	*NO PLATE GARNISH COVER X NN	0.00	0.00	*600.00 F ✓
17	1	NA	*FRT BUMPER X BR	0.00	0.00	*70.00 F
18	1	NA	*FRT BUMPER BRACKET RH X NN	0.00	0.00	*70.00 F ✓
19	1	NA	*FRT BUMPER BRACKET LH X BR	0.00	0.00	*70.00 F
20	1	NA	*HEADLAMP BRACKET RH X NN	0.00	0.00	*70.00 F
21	1	NA	*HEADLAMP BRACKET LH X NN	0.00	0.00	*70.00 F
22	1	NA	*BUMPER LOWER LIPS X NN	0.00	0.00	*200.00 F
23	1	NA	*FOGLAMP RH X NN	0.00	0.00	*160.00 F
24	1	NA	*FOGLAMP LH X BR	0.00	0.00	*160.00 F ✓
25	1	NA	*FRT SUPPORT ASSY X Repair	0.00	0.00	*900.00 F

F=Franchise part.

Sub Total (\$\$)

8,720.00

+ Margin on L,N Items 10.00% (\$\$)

872.00

Total Parts (\$\$)

9,592.00

Cheng Auto Bodyworks/SGR52Y/30/08/2022 12:22. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

6110
+10%
6721

Estimates on Miscellaneous Items

No	Qty	Particulars	Amount
<u>Miscellaneous Items</u>			
1	1	BUMPER CLIPS <i>MR</i>	30 ✓ 80.00
2	1	GRILLE CLIPS <i>NEC</i>	20 ✓ 80.00
3	1	No plate w/case. 40 ✓ <i>MR</i>	
Sub Total (\$)			160.00

90

Estimates on Labour

No	Particulars	Lab.Type	Amount
<u>Labour Items</u>			
1	LABOUR	450 New <i>250</i>	800.00
2	SPRAYPAINTING	800 New <i>600</i>	800.00
3	DISCONNECT & CHECK ELECTRICAL WIRING, HARNESS, WIRE SOCKETS, ETC., REMOVE & REINSTALL DAMAGED PARTS, TEST & RECTIFY FOR PROPER FUNCTIONING	New <i>50</i>	100.00
1300			
Gross Labour Cost (\$)			1,700.00

Cheng Auto Bodyworks/SGR52Y/30/08/2022 12:22. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

main - 8111

supp - 121

8232

Steve (LKK)

12/9/22, 12:00p

OD-M AL

EXPRS-7

P/P

by BL y

4 dy 5

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: